Submit 3 Copies To Appropriate District State of New Mexico	
Office State of Itew Wextee	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	May 27, 2004
District II OIL CONSERVATION DIVISION	30-025-27811
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	LG-814
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Woodpecker SY State
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 2
2. Name of Operator	9. OGRID Number
Yates Petroleum Corporation	025575
3. Address of Operator 105 S. 4 th Street, Artesia, NM 88210	10. Pool name or Wildcat Saunders Permo Upper Penn
4. Well Location	Saunders Fernio Opper Ferni
4. Well Location Unit Letter H : 1980 feet from the North line and	660 feet from the East line
Section 21 Township 14S Range 33E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
4212.5' GR	
Pit or Below-grade Tank Application or Closure	
Pit type <u>Steel</u> Depth to Groundwater <u>N/A</u> Distance from nearest fresh water well, <u>N/A</u> Distance from nearest surface water <u>N/A</u> Pit Liner Thickness; <u>N/A</u> Distance from nearest fresh water well, <u>N/A</u> bils; Construction Material <u>N/A</u>	
DE NOTICIED 22 AOURS PHILIPAL O HIE ate Nature of Notice, Report of Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
Yates Petroleum Corporation proposes to Plug and Abandon well as follows:	
 Set 5-1/2" CIBP @ 9742' and dump 35' cement on plug. RIH w/tubing, circulate plugging mud and spot 100' plug (25 sx) in casing 7774-7674'. 	
3) RIH w/wireline and shoot squeeze holes @ 5630'.	
4) RIH w/tubing and packer and spot 100' plug (30 sx) in and out of casing 5630-5530' TAG	
5) RIH w/wireline and shoot squeeze holes @ 4250'.	
6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T	ag plug.
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T. 7) RIH w/wireline and shoot squeeze holes @ 3479'. 	
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 	(AG)
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 	(AG)
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 	-TAG
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 	-TAG
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Tag 13) RIH w/wireline and shoot squeeze holes @ 60'. 14) Circulate 15 sx cement in and out of casing from surface to 60'. 	-TAG g plug.
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Tag 13) RIH w/wireline and shoot squeeze holes @ 60'. 	-TAG
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400' 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Tag 13) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Tag 14) Circulate 15 sx cement in and out of casing from surface to 60'. 15) Cut off wellhead. Install marker. Clean location. 	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below-
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Tag 13) RIH w/wireline and shoot squeeze holes @ 60'. 14) Circulate 15 sx cement in and out of casing from surface to 60'. 15) Cut off wellhead. Install marker. Clean location. 	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below-
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Ta 13) RIH w/wireline and shoot squeeze holes @ 60'. 14) Circulate 15 sx cement in and out of casing from surface to 60'. 15) Cut off wellhead. Install marker. Clean location. 17) Hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] 	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan [].
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Ta 13) RIH w/wireline and shoot squeeze holes @ 60'. 14) Circulate 15 sx cement in and out of casing from surface to 60'. 15) Cut off wellhead. Install marker. Clean location. 17) Hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] 	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan [].
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Ta 13) RIH w/wireline and shoot squeeze holes @ 60'. 14) Circulate 15 sx cement in and out of casing from surface to 60'. 15) Cut off wellhead. Install marker. Clean location. 17) Hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] 	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan [].
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 500-400'. Tage (30 sx) in and out of casing 5	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below- l or an (attached) alternative OCD-approved plan []. ance Technician DATE <u>2-13-06</u> n.com Telephone New 505-748-1471 TIVE II/STAFF MAN
 6) RIH w/tubing and packer and set 164' plug (50 sx) in and out of casing 4250-4086'. T 7) RIH w/wireline and shoot squeeze holes @ 3479'. 8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 3479-3379' 9) RIH w/wireline and shoot squeeze holes @ 2710'. 10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2710-2610' 11) RIH w/wireline and shoot squeeze holes @ 500'. 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 500-400'. Ta 13) RIH w/wireline and shoot squeeze holes @ 60'. 14) Circulate 15 sx cement in and out of casing from surface to 60'. 15) Cut off wellhead. Install marker. Clean location. 17) Hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] 	-TAG g plug. (Proposed Schematic Attached) ge and belief. I further certify that any pit or below- l or an (attached) alternative OCD-approved plan []. ance Technician DATE <u>2-13-06</u>

