

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection <input checked="" type="checkbox"/> <b>HOBBS OCD</b>		WELL API NO. 30-025-26860 ✓
2. Name of Operator ConocoPhillips Company ✓		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P. O. Box 51810 Midland, TX 79710		6. State Oil & Gas Lease No. B-2284-2
4. Well Location Unit Letter <u>L</u> : <u>2540</u> feet from the <u>South</u> line and <u>40</u> feet from the <u>West</u> line Section <u>29</u> Township <u>17S</u> Range <u>35E</u> NMPM County <u>Lea</u> ✓		7. Lease Name or Unit Agreement Name East Vacuum GB-SA Unit Tract 2957 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3971' GR		8. Well Number 002 ✓
9. OGRID Number 217817		10. Pool name or Wildcat Vacuum; GB-SA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: Isolate & repair <input checked="" type="checkbox"/>		<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>	
--	--	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

ConocoPhillips Company would like to isolate problem in well and fix per attached procedure.

**Condition of Approval: notify  
 OCD Hobbs office 24 hours  
 prior of running MIT Test & Chart**

Spud Date:  Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rhonda Rogers TITLE Staff Regulatory Tech DATE 09/24/2015  
 Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: 432-688-9174  
**For State Use Only**  
 APPROVED BY: Makay Brown TITLE Dist. Supervisor DATE 9/29/2015  
 Conditions of Approval (if any) OCT 07 2015

**EVGSAU 2957-002W**  
**MIT Remediation**  
**API #30-025-26860**

**Project Scope**  
**Justification and Background** The well a water disposal has currently failed its MIT test. Well is a support well. While pressuring up on the casing, water, immediately started flowing from the surface valve. Current pressures are 1200 psi on tubing, 0 on casing. Both the surface and production had returns during cementing. Well was last well serviced on 6/09/2000.

<b>Perforations</b>			
Type	Formation	Top	Bottom
Perforations	San Andres	4459	4600
Openhole			
PBD		4713	
TD		4800	

**Well Service Procedure:**

- Verify anchors have been tested prior to RU.**  
**Review JSA prior to RU on well.**
1. MI, RU WSU. NDWH, NUBOP.
  2. TOOH with injection tubing and packer. LD tubing and PKR.
  3. MI workstring and tally. MI reverse unit.
  4. TIH with 3 7/8 bit, collars and tubing and clean out to 4700'.
  5. COOH with tubing, collars and bit.
  6. TIH with RBP, packer and tubing. Set RBP @ +/- 4000', pull up 1 stand and set packer.
  7. Pressure test packer/RBP to 500 psi.
  8. If packer/RBP test passes, COOH change out packer to a tension packer, RBI and set packer 100' from surface. RU pump truck to tubing and pressure test packer/RBP to 400 psi. If test passes, CUH and isolate leak.
  9. Test result and finding for possible job scope change.
  10. After repairs have been made. And casing has been tested.
  11. TIH with retrieving head and tubing and COOH with RBP and tubing, lay all down.
  12. MO workstring. MI injection tubing and tally. (Tubing to come from CTB yard).
  13. **Setting the Injection Packer**

**NOTE: Ensure injection PKR has been shop tested to 3000 psi or 1000 psi above MASP.**

A. Well has remained killed during well service	B. Well has been flowing / is hard to keep killed
↓↓	↓↓
1. TIH w/ a. 4.5"x2.375" 14# NP Baker Hughes 10K Hornet PKR w/ CO <sub>2</sub> elements b. On-off tool w/ 1.875" XN profile c. 2.375" 4.7# IPC tubing. Set PKR @ 4386'.	1. MIRU wireline services a. Pressure test lubricator to 3000 psi or 1000 psi above MASP.
2. Get off on-off tool & circulate PKR fluid to surface (4386' x .0114 = 50 bbls).	2. PU & RIH w/ the following in order from bottom to top. a. 2.375" wireline re-entry guide b. 4.5"x2.375" 14# NP Baker Hughes 10K Hornet PKR w/ CO <sub>2</sub> elements c. 2.375" on-off tool w/ 1.875" XN profile

**EVGSAU 2957-002W  
MIT Remediation  
API #30-025-26860**

3. Get back on on-off tool.	3. Use CCL to correlate proposed PKR setting depth & set PKR @ 4386'.
4. NDBOP. NUWH.	4. POOH w/ wireline & bleed off any casing pressure for 20 min to verify isolation. RD wireline
5. RU pump truck and 1000 psi chart recorder. Test casing / PKR to 450 psi for 20 min. a. Notify NMOCD of impending test. b. Give chart to PE Tech to be put into Wellview.	5. TIH w/ top section of on-off tool & new 2.375" 4.7# IPC injection tubing. a. Pressure test tubing GIH b. Circulate PKR fluid to surface. (4386' x .0114 = 50 bbls). c. Engage on-off tool d. Pressure test on-off tool to 2000 psi
6. RDMO WSU. Clean up location.	6. RU wireline. a. Retrieve profile plug in XN nipple b. RDMO wireline
7. Acidize according to schedule	8. NDBOP. NUWH.
	9. RU pump truck to casing & test PKR/casing to 450 psi for 30 min. a. Notify NMOCD of impending test b. Chart pressure test
	10. RDMO WSU. Clean up location.
	11. Acidize according to schedule

**Rig-less Acidizing**

14. MIRU Acid pump trucks

- a. Pressure test lines to 3000 psi or 1000 psi over the highest observed well pressure.
- b. Verify shower trailer will operate properly.
- c. Pump 10 bbls 15% HCL acid at a rate of 1 to 2 bbls per min.
  - i. NOTE: Maximum pumping pressure 2000 psi.
- d. Flush with 22bbls brine water.
- e. Record rates and pressure during acid job and 15 mins, 10 mins & 5 min.
- f. RD acid pump truck and MO.
- g. Put back on injection.

**EVGSAU 2957-002W**  
**MIT Remediation**  
**API #30-025-26860**

**Project Scope**  
**Justification and Background** The well a water disposal has currently failed its MIT test. Well is a support well. While pressuring up on the casing, water, immediately started flowing from the surface valve. Current pressures are 1200 psi on tubing, 0 on casing. Both the surface and production had returns during cementing. Well was last well serviced on 6/09/2000.

<b>Perforations</b>			
Type	Formation	Top	Bottom
Perforations	San Andres	4459	4600
Openhole			
PBD		4713	
TD		4800	

**Well Service Procedure:**

Verify anchors have been tested prior to RU.

Review JSA prior to RU on well.

1. MI, RU WSU. NDWH, NUBOP.
2. TOOH with injection tubing and packer. LD tubing and PKR.
3. MI workstring and tally. MI reverse unit.
4. TIH with 3 7/8 bit, collars and tubing and clean out to 4700'.
5. COOH with tubing, collars and bit.
6. TIH with RBP, packer and tubing. Set RBP @ +/- 4000', pull up 1 stand and set packer.
7. Pressure test packer/RBP to 500 psi.
8. If packer/RBP test passes, COOH change out packer to a tension packer, RBI and set packer 100' from surface. RU pump truck to tubing and pressure test packer/RBP to 400 psi. If test passes, CUH and isolate leak.
9. Test result and finding for possible job scope change.
10. After repairs have been made. And casing has been tested.
11. TIH with retrieving head and tubing and COOH with RBP and tubing, lay all down.
12. MO workstring. MI injection tubing and tally. (Tubing to come from CTB yard).
13. **Setting the Injection Packer**

**NOTE: Ensure injection PKR has been shop tested to 3000 psi or 1000 psi above MASP.**

A. Well has remained killed during well service	B. Well has been flowing / is hard to keep killed
↓↓	↓↓
1. TIH w/ <ol style="list-style-type: none"> <li>a. 4.5"x2.375" 14# NP Baker Hughes 10K Hornet PKR w/ CO<sub>2</sub> elements</li> <li>b. On-off tool w/ 1.875" XN profile</li> <li>c. 2.375" 4.7# IPC tubing. Set PKR @ 4386'.</li> </ol>	1. MIRU wireline services <ol style="list-style-type: none"> <li>a. Pressure test lubricator to 3000 psi or 1000 psi above MASP.</li> </ol>
2. Get off on-off tool & circulate PKR fluid to surface (4386' x .0114 = 50 bbls).	2. PU & RIH w/ the following in order from bottom to top. <ol style="list-style-type: none"> <li>a. 2.375" wireline re-entry guide</li> <li>b. 4.5"x2.375" 14# NP Baker Hughes 10K Hornet PKR w/ CO<sub>2</sub> elements</li> <li>c. 2.375" on-off tool w/ 1.875" XN profile</li> </ol>

**EVGSAU 2957-002W  
MIT Remediation  
API #30-025-26860**

3. Get back on on-off tool.	3. Use CCL to correlate proposed PKR setting depth & set PKR @ 4386'.
4. NDBOP. NUWH.	4. POOH w/ wireline & bleed off any casing pressure for 20 min to verify isolation. RD wireline
5. RU pump truck and 1000 psi chart recorder. Test casing / PKR to 450 psi for 20 min. a. Notify NMOCD of impending test. b. Give chart to PE Tech to be put into Wellview.	5. TIH w/ top section of on-off tool & new 2.375" 4.7# IPC injection tubing. a. Pressure test tubing GIH b. Circulate PKR fluid to surface. (4386' x .0114 = 50 bbls). c. Engage on-off tool d. Pressure test on-off tool to 2000 psi
6. RDMO WSU. Clean up location.	6. RU wireline. a. Retrieve profile plug in XN nipple b. RDMO wireline
7. Acidize according to schedule	8. NDBOP. NUWH.
	9. RU pump truck to casing & test PKR/casing to 450 psi for 30 min. a. Notify NMOCD of impending test b. Chart pressure test
	10. RDMO WSU. Clean up location.
	11. Acidize according to schedule

**Rig-less Acidizing**

14. MIRU Acid pump trucks

- a. Pressure test lines to 3000 psi or 1000 psi over the highest observed well pressure.
- b. Verify shower trailer will operate properly.
- c. Pump 10 bbls 15% HCL acid at a rate of 1 to 2 bbls per min.
  - i. NOTE: Maximum pumping pressure 2000 psi.
- d. Flush with 22bbls brine water.
- e. Record rates and pressure during acid job and 15 mins, 10 mins & 5 min.
- f. RD acid pump truck and MO.
- g. Put back on injection.