			ARS OCD				
Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE INT	TERIOR	FI	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010			
SUN	BUREAU OF LAND MANAGE		5. Lease Serial I NMNM251				
	use this form for proposals to dr ed well. Use form 3160-3 (APD)			6. If Indian, Allottee or Tribe Name			
SUBMIT	IN TRIPLICATE - Other instruction	ons on reverse side.	7. If Unit or CA	/Agreement, Name and/or No.			
1. Type of Well Oil Well Gas Well			8. Well Name an NORTHEAS	nd No. ST DRINKARD UNIT (NEDU) 242			
2. Name of Operator APACHE CORPORATI	ON E-Mail: Reesa.Fisher	EESA FISHER @apachecorp.com	9. API Well No. 30-025-378	375			
3a. Address 303 VETERANS AIRPA MIDLAND, TX 79705		bb. Phone No. (include area code Ph: 432-818-1062	10. Field and Po EUNICE; E	ool, or Exploratory 3-T-D, NORTH			
4. Location of Well (Footage	, Sec., T., R., M., or Survey Description)		11. County or P	arish, and State			
Sec 3 T21S R37E SWM	NE 3050FSL 2595FEL		LEA COUNTY COUNTY, NM				
12. CHECK	APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR O	THER DATA			
TYPE OF SUBMISSION	N	ТҮРЕ С	F ACTION	V			
Notice of Intent	□ Acidize	Deepen	Production (Start/Resum	ne) 🔲 Water Shut-Off			
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	U Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	□ Other			
Final Abandonment No	otice Change Plans	Plug and Abandon	Temporarily Abandon				
	Convert to Injection	Plug Back	□ Water Disposal				
If the proposal is to deepen d Attach the Bond under which	eted Operation (clearly state all pertinent d irectionally or recomplete horizontally, giv the work will be performed or provide the involved operations. If the operation result Final Abandonment Notices shall be filed o dy for final inspection.)	e subsurface locations and meas Bond No. on file with BLM/BI	ured and true vertical depths of all A. Required subsequent reports sh	pertinent markers and zones. all be filed within 30 days			
Apache would like to co proposed WBD's are al	onvert this well to injection, per the so included.	attached procedure. Curr	ent and				
		MILLET AL	N MIT PRICE NTECTION	OR TO			
		Mart Pou	N THE THE				
	BE	EGINING	NTECTION	- 11-2			
			01	KE			
14. I hereby certify that the fore	Electronic Submission #326	6388 verified by the BLM We CORPORATION, sent to th	ell Information System e Hobbs				
Name (Printed/Typed) REESA FISHER		Title SR ST	Title SR STAFF REGULATORY ANALYST				
Signature (Ele	ctronic Submission)	Date 12/15/2	2015				
4	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE				
Approved By		Title	Accepted for Rec				
Conditions of approval, if any, are	attached. Approval of this notice does not al or equitable title to those rights in the su to conduct operations thereon.	t warrant or					
	Title 43 U.S.C. Section 1212, make it a crinudulent statements or representations as to			ent or agency of the United			
** OP	ERATOR-SUBMITTED ** OPE	ERATOR-SUBMITTED	** OPERATOR-SUBMIT	TED **			

cy

DEC 3 1 2015' 114/10

NEDU 242 Proposed Workover Procedure API: 30-025-37875 Summary: Reactivate Well, Run Liner, Add pay to Drinkard, Acid Stimulate, Install Injection Equipment

Note: Prior to starting workover, ensure casing has been pressure tested to 500 psig to ensure well will pass MIT

- Day 1/2/3: MIRU. ND WH. NU BOP. PU 2-7/8" work string and RIH w/work string and 4-3/4" bit. MIRU N2 / Reverse Unit as required. Drill out plugs suspending the Blinebry, Tubb, and Drinkard. Circulate clean to PBTD depth of +/- 6,873'. POOH w/tubing and bit.
- Day 4: RU casing crew and equipment and RIH with 4" 9.5 lb/ft, J-55 flush joint casing with float collar and float shoe to +/- 6,873'.

RU cement crew. Perform single stage cement job to surface consisting of 20 bbl fresh water flush, 40 bbl seal bond LCM spacer, and 384 sacks of Class C cement + additives (weight 13.2 ppg, yield 1.60 cf/sack, volume 113.5 bbls, 100% excess slurry). Displace with 83.6 bbl fresh water (confirm all volumes).

- Day 5: Wait on Cement
- Day 6: PU and RIH w/ 3-3/4" bit on 2-3/8" work string. Drill out float collar and cement to +/- 6,858'. Circulate clean. POOH w/ bit and work string.
- Day 7: MIRU WL and RIH w/ GR/CBL/CCL. Log well from TD to surface. POOH.

PU and RIH w/3-3/8" slick guns with SDP charges (or similar). Perforate the Drinkard @ 4 SPF, 90 deg phasing as per the attached sheet (total 52 ft, 208 shots). POOH & RD WL.

RIH w/ 4-1/2" treating packer on 2-3/8" work string. Set packer @ +/-6,550'.

Day 8: Acidize the Drinkard w/10,000 gals 15% HCl-NE-FE-BXDX acid w/scale inhibitor and rock salt @ +/- 10 BPM (Max pressure 4,500 psia). Release packer. Wash out salt. POOH

PU and RIH w/ 4-1/2" injection packer, on-off tool and 2-3/8" work string.

Set packer @ +/- 6,550'. Release on/off tool and POOH. LD 2-3/8" work string.

Day 9: Test in hole w/2-3/8" IPC injection tubing. Circulate packer fluid and pressure test backside to 500 psi. Latch on to packer @ +/- 6,550'.

Run MIT for NMOCD. Run pressure profile and temperature survey.

Place well on injection. Send first flow form to Reesa Fisher.

	Guns: 3-	3/8" slick	guns w/ Stand	dard Charge	S	
Stage	Zone	Тор	Bottom	Length	SPF	Shots
1	Drinkard	6622	6623	2	4	8
1	Drinkard	6625	6626	2	4	8
1	Drinkard	6629	6630	2	4	8
1	Drinkard	6633	6634	2	4	8
1	Drinkard	6636	6637	2	4	8
1	Drinkard	6640	6641	2	4	8
1	Drinkard	6644	6645	2	4	8
1	Drinkard	6648	6649	2	4	8
1	Drinkard	6652	6653	2	4	8
1	Drinkard	6660	6661	2	4	8
1	Drinkard	6664	6665	2	4	8
1	Drinkard	6678	6679	2	4	8
1	Drinkard	6682	6683	2	4	8
1	Drinkard	6686	6687	2	4	8
1	Drinkard	6690	6691	2	4	8
1	Drinkard	6694	6695	2	4	8
1	Drinkard	6698	6699	2	4	8
1	Drinkard	6702	6703	2	4	8
1	Drinkard	6706	6707	2	4	8
1	Drinkard	6710	6711	2	4	8
1	Drinkard	6714	6715	2	4	8
1	Drinkard	6718	6719	2	4	8
1	Drinkard	6722	6723	2	4	8
1	Drinkard	6726	6727	2	4	8
1	Drinkard	6730	6731	2	4	8
1	Drinkard	6734	6735	2	4	8
	Tot	-al		52		208



