Submit 3 Copies To Appropriate District	State of New Mexico Energy, Minerals and Natural Resources		Form C-103			
District I 1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	June 19, 2008		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATIO	OBVISION	<u>30-025-0</u>			
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 00000 01. 110		5. Indicate Type of STATE			
District IV	Santa Fe, INM 8	7502B 0 9 2017	6. State Oil & Gas			
1220 S. St. Francis Dr., Santa Fe, NM 87505		DECEIVED	027815	2 cuse 110.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or U State "J"	Jnit Agreement Name:		
1. Type of Well: Oil Well X Gas Well	. Type of Well:					
2. Name of Operator			9. OGRID Number			
Energen Resources Corporation			1629			
3. Address of Operator 3510 N. "A" St., Bldgs A & B Midland, TX 79705			10. Pool name or Wildcat Saunders, Permo Penn			
4. Well Location						
Unit Letter E	1980 feet from the Nor	th line and	feet from	n the West line		
Section 23	Township 14-S	Range 33-E	NMPM	County Lea		
Sector and sectors	11. Elevation (Show whether	DR, RKB, RT, GR, etc 95' GL	c.)			
12. Check Ap	propriate Box to Indicate	Nature of Notice, F	Report, or Other D	Data		
NOTICE OF INTE	SEQUENT REP	ORT OF:				
	PLUG AND ABANDON X	REMEDIAL WORK				
	CHANGE PLANS	COMMENCE DRILLI				
PULL OR ALTER CASING		CASING/CEMENT JO		INT TO PA		
				P&A R		
OTHER:		OTHER:				
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 						
See Attached PROPOSED Plug	and Abandon Procedure.		- 210	RTONS		
			HOURS PRIC	RATIONS		
TIEY OCD 24 TIGGING OT						
See Attached PROPOSED Plug and Abandon Procedure. NOTIFY OCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS						
		BEO				
				7		
Spud Date:	Rig Relea	ase Date:				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Brenda Ha	this AN	- Degulator	Analyst .	02/06/2017		
SIGNATURE / Mula Mathyn TITLE Regulatory Analyst DATE 02/06/2017 brenda.rathjen@energen.com						
Type or print name Brenda F Rathjen E-mail address: PHONE 432-688-3323						
APPROVED BY Manh With TITLE Petroleum Engr. Specialistate 02/09/2017						
APPROVED BY Conditions of Approval (if any):			J. J. D.	AIE		

ENERGEN STATE -J- 4, API # 30-025-01147 AFE # PB17500073, \$75,000 1980' FNL & 660' FWL Sec. 23, T-14-S, R-33-E Lea County, NM

The State -J- 4 was spud 08/17/58, and was completed 09/24/28 as a Permo-Penn producer, with additional Permo-Penn perfs added in 1961. It has been shut-in since August, 2016 after a downhole failure. The well was making less than 1 BOPD at the time. This was the last active well on the lease. It is not economical to repair and needs to be plugged and abandoned. This lease, NM002214-00R, will expire, and all surface facilities will need to be remediated.

For scope changes during work, stop and discuss with engineering before proceeding

API:	30-025-01147	KB:	4205'	PBTD: 9942'
Spud Date:	8/17/1958	GLE:	4195'	TD: 9950'

Proposed Plug and Abandon Procedure

SAFETY CONSIDERATIONS

Observe all Energen Guidelines for PPE and H2S Safety Observe perforation and contractor safety guidelines Wireline and explosives on location while perforating Workstring should be in good condition and tested to 5000 psi. BOP should be in good working condition and tested Rig anchors will need to be tested prior to MIRU Keep a TIW valve open and on the rig floor at all times Notify the NM OCD 24 hours prior to starting P&A operations Meet with engineer, superintendents, and consultant prior to beginning the job, to assure that everyone is agreement with the procedure.

- 1 MIRU Well Service Unit.
- 2 Bleed well down.
- 3 NDWH
- 4 Unset pump. POOH w/ rods and pump.
- 5 NU adapter flange and BOP for 8-5/8" csg and 2-3/8" tubing. Test to 500 psi above working pressure.
- 6 Unset TAC. POOH w/ tbg.
- 7 Unload and rack 10,000' 2-7/8" workstring. Maintain kill truck w/10 ppg brine on location.
- 8 Change BOP rams to 2-7/8" tbg
- 9 RIH, set CIBP @9700'. Dump bail 5 sx Class 'H' cmt (or 25 sx through tubing) on top CIBP.
- 10 RIH with workstring. Circulate hole to 10 ppg mud.
- 11 Pressure test csg.
- 12 Perforate and squeeze at 7400' w/ 30 sx cement plug and displace to 7300'. (Tubb)
- 13 WOC and tag.
- 14 Perforate and squeeze at 4219' w/ 40 sx cement plug and displace to 4119'. (shoe)
- 15 Perforate and squeeze at 4096' w/ 40 sx cement plug and displace to 3996'. (liner top)-

16 Spot 25 sx Class "C" cmt @ 3000', base of salt sections


17 Spot 25 sx Class "C" cmt @ 2000' top of salt sections / 1700


>18 Spot Class "C" cmt from 350' to surface (shoe). Circ to surface

- 19 ND BOP. Top off well with cement. RD and clean location.
- 20 Verify cmt to surface all strings.
- 21 Cut off all casing strings at base of cellar or 3' below restored ground level.
- 22 Cover wellbore with metal plate welded in place or with cement cap.
- 23 Erect capped abandonment marker inscribed with well information.
- 24 Cut off dead man anchors and fill in cellar. RDMO.
- 25 Clean and restore location and facilities to natural condition and fulfill any and all regulatory requirements.

SPOT 50 SX CMT @ 4300' WOC \$TAG

at 3990 or better





2/2/2017 State J-4 P&A pkg.xlsx