

Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	- OBBS O	30-025-30969
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5 Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. 3 2017 Santa Fe, NM 87505	STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	ECEIVED	
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH	VACUUM GLORIETA WEST UNIT
PROPOSALS.)		8. Well Number: 75
1. Type of Well: Oil Well	Gas Well Other	/
2. Name of Operator Chevron U.S.A. INC.	/	9. OGRID Number 4323
3. Address of Operator		10. Pool name or Wildcat
	MIDLAND, TX 79706 RM.N3002	VACUUM GLORIETA
4. Well Location		
Unit Letter <u>H</u> :	2310' feet from the <u>NORTH</u> line and	990 feet from the EAST line
Section 36	Township 17S Range 34E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	.)
	3995' GL	
12. Charle Assessments Day to Indiants Nature of Nation Depart on Other Date		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF I	NTENTION TO: SUE	SEQUENT STRAFT OF
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DF	ILLING OPNS.[INT TO PA PM X
PULL OR ALTER CASING		IT JOB L P&A NR
DOWNHOLE COMMINGLE	J	P&A R
OTHER:	OTHER:	
13. Describe proposed or con	npleted operations. (Clearly state all pertinent details, and	
13. Describe proposed or con of starting any proposed or	npleted operations. (Clearly state all pertinent details, an work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
13. Describe proposed or con	npleted operations. (Clearly state all pertinent details, an work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or con of starting any proposed or proposed completion or re 	npleted operations. (Clearly state all pertinent details, an work). SEE RULE 19.15.7.14 NMAC. For Multiple Coecompletion.	
 13. Describe proposed or con of starting any proposed or proposed completion or re 1. Call and notify NM 	npleted operations. (Clearly state all pertinent details, an work). SEE RULE 19.15.7.14 NMAC. For Multiple Coecompletion.	
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. N 	npleted operations. (Clearly state all pertinent details, an work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. 5087'	ompletions: Attach wellbore diagram of
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. N Tag CIBP@5,850', 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. spot 25sx of cmt. on top. Circulate well w/	9.5 ppg mud. Pressure test casing.
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. N Tag CIBP@5,850', Spot 25sx of Class 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent states all pe	9.5 ppg mud. Pressure test casing. g. (DV Tool)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. N Tag CIBP@5,850', Spot 25sx of Class 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. spot 25sx of cmt. on top. Circulate well w/	9.5 ppg mud. Pressure test casing. g. (DV Tool)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. N Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state all pertinent states all pe	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt)
 Describe proposed or con of starting any proposed or proposed completion or re Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class 	npleted operations. (Clearly state all pertinent details, an work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050° -4,850°, WOC&Ta "C" cement from 3,050° -2,500°, WOC&Ta "C" cement from 1,700° -1,400°, WOC&Ta	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050° -4,850°, WOC&Ta "C" cement from 3,050° -2,500°, WOC&Ta "C" cement from 1,700° -1,400°, WOC&Ta "C" cement from 350° to surface. (Shoe/FV	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state of the sec	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. 5037' spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050'-4,850', WOC&Ta "C" cement from 3,050'-2,500', WOC&Ta "C" cement from 1,700'-1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FV urface on all casings. Cut off wellhead and a clean location.	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the second state of the sec	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface)
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. 5037' spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050'-4,850', WOC&Ta "C" cement from 3,050'-2,500', WOC&Ta "C" cement from 1,700'-1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FV urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids.	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the ecompletion. OCD 24 hrs. before operations begin. U BOPE. Spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FW) urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. NOTIFY OC	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the ecompletion. OCD 24 hrs. before operations begin. U BOPE. Spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FW) urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. NOTIFY OC	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on
 Describe proposed or con of starting any proposed or proposed completion or re Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above for 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. (OCD 24 hrs. before operations begin. U BOPE. 5037 spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FW urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. NOTIFY OC BEGINNING	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on
 Describe proposed or con of starting any proposed or proposed completion or r Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concerning the ecompletion. OCD 24 hrs. before operations begin. U BOPE. Spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FW) urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. NOTIFY OC	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on
 Describe proposed or con of starting any proposed or proposed completion or re Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above for 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. 5087 spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FV urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. mabove is true and complete to the be NOTIFY OC BEGINNING TITLE Project Manager	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on CD 24 HOURS PRIOR TO S PLUGGING OPERATIONS
 Describe proposed or con of starting any proposed or proposed completion or re Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above for 	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050° -4,850°, WOC&Ta "C" cement from 3,050° -2,500°, WOC&Ta "C" cement from 1,700° -1,400°, WOC&Ta "C" cement from 350° to surface. (Shoe/FV urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. MOTIFY OC BEGINNING MARCE STREE Project Manager	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on CD 24 HOURS PRIOR TO S PLUGGING OPERATIONS
 Describe proposed or con of starting any proposed or proposed completion or re Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above I hereby certify that the information SIGNATURE	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. 5037 spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FW urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. NOTIFY OC BEGINNING Mark	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) unchors 3' below grade. Weld on CD 24 HOURS PRIOR TO DATE 03/08/17
 Describe proposed or con of starting any proposed or proposed completion or re Call and notify NM MIRU. NDWH. NI Tag CIBP@5,850', Spot 25sx of Class Spot 60sx of Class Spot 35sx of Class Spot 40sx of Class Verify cement to su dryhole marker and Closed loop above I hereby certify that the information SIGNATURE	npleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion. OCD 24 hrs. before operations begin. U BOPE. 5087 spot 25sx of cmt. on top. Circulate well w/ "C" cement from 5,050 -4,850', WOC&Ta "C" cement from 3,050' -2,500', WOC&Ta "C" cement from 1,700' -1,400', WOC&Ta "C" cement from 350' to surface. (Shoe/FV urface on all casings. Cut off wellhead and a clean location. ground tank system will be used for fluids. mabove is true and complete to the be NOTIFY OC BEGINNING TITLE Project Manager	9.5 ppg mud. Pressure test casing. g. (DV Tool) g. (Shoe/B.Salt) g. (T.Salt/Shoe) V/surface) anchors 3' below grade. Weld on CD 24 HOURS PRIOR TO S PLUGGING OPERATIONS

PROPOSED P&A WBD

VACUUM GLORIETA WEST UNIT #49



CURRENT WELLBORE DIAGRAM



TD: 6300'