

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-41530
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Encoree M State
8. Well Number 12
9. OGRID Number 370080
10. Pool name or Wildcat WC-025 G-02 S223729G; Glorieta

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Breitbart Operating LP

3. Address of Operator
1111 Bagby Street, Suite 1600 Houston, Texas 77002

4. Well Location
 Unit Letter: **K** **2264** feet from the **South** line and **1702** feet from the **West** line
 Section **20** Township **22 S** Range **37 E** NMPM **Lea County**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3384' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE
 CLOSED-LOOP SYSTEM
 OTHER:

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER: Plug Back Wantz;Abo, Drinkard, Tubb and Blinebry.
 Perforate and acidize WC Glorieta.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/28-3/29/2017: MIRUPU. Cannot unseat pump, back off rods, POOH and LD rods. Close well in and SION.
3/29-3/30/2017: Kill csg. NDWH, unset TAC, NU BOP, start out with tbg. POOH. Shut down due to wind. Close well and SION.
3/30-3/1/2017: Finish POOH w/tbg, TAC. RIH w/4 5/8" bit and scraper to 5658'. MIRU WL, RIH w/gauge rig and junk basket to 5600', **RIH w/5.5-20# CIBP set @ 5575'**. RIH and dump 10' cement on top of CIBP (**new PBDT 5565'**). SION
3/31-4/01/2017: RIH w/ pkr and 2 7/8" tubing. Set pkr @ 5438'. Test CIBP to 5000#. Good test, test casing to 5000#, good test. Spot 150 gal. acid across perfs, POOH w/tbg and pkr. RIH and perforate Stage 1 Glorieta @ 3 spf, 5414'-5418', 5420'-5422', 5426'-5430', 5432'-5434', 48 holes. RIH w/ pkr and tbg, set pkr @ 5298'. Acidize zone w/2000 gal 15% NEFE acid and ball sealers. RU swab. SION. **4/01-4/02/2017:** swabbing. **4/03-4/04/2017:** Release packer, POOH w/tbg and packer. Close well in and SION. **4/04-4/05/2017:** RIH and set **CBP @ 5405'**. POOH. RIH w/ perf guns and perforate Stage 2 Glorieta @ 3 spf, 5350'-5352', 5355'-5358', 5361'-5363', 5365'-5367', 5371'-5374', 5377'-5380', 5382'-5386', 5389'-5391', 21 net feet, 87 holes. RIH w/packer to 5397', set pkr. Test CBP to 5000#, pull pkr to 5391'. Spot 150 gal. 15% NEFE acid across perfs, pull up to 5201', set pkr and treat Stage 2 w/ 2250 gals 15% NEFE acid and ball sealers. RU swab. Close well in and SION. **4/05-4/07/2017:** Swabbing. **4/07-4/08/2017:** RIH and set **CBP @ 5344'**, Perforate Stage 3Glorieta with 3 spf @ 5278'-5280', 5282'-5284', 5294'-5298, 5301'-5303', 5308'-5314', 5323'-5324', 5326'-5331', 87 holes. RIH w/ packer and tubing. Close well in and SION. **4/10-4/11/2017:** RIH w/ gauge ring and junk basket, tag CBP @ 5384. **RIH w/ CBP and set @ 5340'**. RIH w/packer and test CBP to 5000#, pull up to 5331', and spot 150 gal acid across perfs. Pull up and set packer @ 5136', acidize Stage 3 with 1400 gal 15% HCL NEFE acid and ball sealers. Close well in and SION. **4/11-4/12/2017:** Swabbing. **4/12-4/13/2017:** Unset packer and POOH and LD packer, RIH w/2 7/8" tubing, TAC, EOT @ 5337'. Close well in and SION. **4/13-4/14/2017:** RIH w/ 2.5-2.0-24' RHB (HVR) BDV pump, load and test tbg. and pump action to 500#, Good test. RDPU and MO. **4/19-4/20/2017:** MIRUPU. POOH and LD rods and pump. Unset TAC, POOH w/tubing. RIH w/gauge ring and junk basket. **RIH w/ CBP and set @ 5240'**. Perforate Glorieta stage 4w/ 3spf @ 5129-5142', 5154-5164, 5195-5206', 111 holes.
4/20-4/21/2017: RIH w/ packer and 2 7/8" tubing, tag CBP @ 5240', set packer @ 5238' and test CBP and casing to 5000#, unset packer, spot 1.5 bbls acid across perfs, set packer @ 5014', test casing to 550#, acidize well w/3500 gal 15% NEFE HCL, ball sealers. Begin swabbing. **4/21-4/22/2017:** Unset packer, POOH and LD packer, RIH w/ 2 7/8" tubing, TAC, RIH w/ 2.5-2.0-24' RHBC pump. Begin pumping to test tanks. SD for night. **4/22-4/25/2017:** Testing, RDPU and MO.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shelly Doescher

TITLE: **Agent** DATE: **05/01/2017**

Type or print name: **Shelly Doescher** E-mail address: **shelly_doescher@yahoo.com** PHONE: **505-320-5682**
For State Use Only

Petroleum Engineer

APPROVED BY: [Signature]
Conditions of Approval (if any):

TITLE _____

DATE 05/11/17