Submit I Copy To Appropriate District	State of Ne	ew Mexico		Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240	1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		WELL API NO.	
811 S. First St., Ártesia, NM 88210			30-025-3129 5. Indicate 7	Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE 🗌 FEE 🛛	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, 1	NM 8/303	6. State Oil	& Gas Lease No.
87505	LCES AND DEPORTS ON U		7. 1	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Lovington Paddock Unit	
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other Injection CRS OCD			8. Well Number: 120	
2. Name of Operator Chevron Midcontinent LP		9. OGRID Number		
3. Address of Operator MAY 2.92020			4323 10. Pool name or Wildcat	
6301 DEAUVILLE BLVD., MIDLAND, TX 79706			Lovington P	
4. Well Location RECEIVED				
Unit Letter <u>D</u> :				from theWestline
Section 6	Township 17S	Range 37E her DR, RKB, RT, GR, etc.,	NMPM	County Lea
	3,813' GL, 3,829' KB	<i>Ter DR</i> , <i>RRD</i> , <i>R</i> 1, <i>GR</i> , <i>etc.</i> ,	,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB I				
PULL OR ALTER CASING			I JOB	
				_
OTHER: <u>TEMPORARILY ABANDON</u> 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion. 8-5/8" @ 1,887' TOC Surface, 5-1/2" @ 6,450' TOC Surface. Perforations: 6,032'-				
6,324'. Chauran USA DIC regreatfully requests to abandon this well as follows:				
Chevron USA INC respectfully requests to abandon this well as follows: All Cement sack volumes are calculated using 1.32 yield for Class C and 1.18 yield for Class H. Adjust volumes to				
match footage as necessary based on the yield used at the time of execution.				
1. Call and notify NMOCD 24 hrs before operations begin.				
2. MIRU pulling unit.				
3. Check well pressures, kill well as necessary, perform bubble test on surface casing annuli, if bubble test fails				
Chevron intends to Zonite, cut and pull casing, or eliminate SCP with another means after the well is plugged to a				
certain point agreed upon by the NMOCD and Chevron. a. Bubble test should be at least 30 minutes and follow the bubble test SOP.				
b. Bubble tests should occur each morning, critical times are prior to pumping upper hydrocarbon plug or				
numping cement to surface				
c. Perform final b	ubble test after cement has	hardened.		Attacheu roval
4. Pressure test tubing to 5	00 psi for 15 minutes (or h	ighest anticipated pressu	ire of the job	See number of Approver
5. N/U and function test ro		•••	See Attached ditions of Approval	
6. Laydown rod string and			Con	
7. N/U BOP and pressure test as per SOP.				
a. 250 psi low, MASP or 500 psi, or highest expected pressure (whichever is greater) for the job for 5 minutes each.				
8. Stand back tubing.				
a. If tubing failed a pressure test, test tubing back in the well after setting CIBP.				
9. R/U wireline unit, pressure test lubricator t/ 500 psi for 10 minutes.				
10. M/U and set CIBP at 5,950'.				
a. Do not run a gauge ring if TAC pulled smoothly out of the well.				

11. TIH with open ended tubing.

a. Fill well with freshwater while tripping.

12. Tag CIBP and pressure test casing to 500 psi for 15 minutes.

a. If casing pressure test fails, contact the engineer to add cement or pump Jet-Seal depending on LC severity.

13.Spot MLF, subtracting cement volumes. Do not place MLF until casing pressure tests.

14.Spot 25 sx CL "C" cement f/ 5,950' t/ 5,704' (Perfs).

a. TOC must be at 5,850' or shallower.

b. Discuss with NMOCD on waiving WOC and tag if casing passed a pressure test.

15.Spot 40 sx CL "C" cement f/ 4.587' t/ 4,192' (San Andres, Grayburg).

a. TOC must be at 4,223' or shallower.

16.Spot 25 sx CL "C" cement f/ 2,998' t/ 2,752' (Yates).

a. TOC must be at 2,898' or shallower.

17.Spot 200 sx CL "C" cement f/ 1,887' t/ Surface (Shoe, FW).

a. Deepest freshwater zone in the area is \sim 75'.

18. Cut all casings & anchors & remove 3' below grade. Verify cement to surface & weld on dry hole marker (4" diameter, 4' tall). Clean location.

Note: All cement plugs class "C" (<7,500') or "H" (>7,500') with closed loop system used, and MLF spotted between plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. 42 TITLE P&A Engineer, Attorney in fact DATE 05/27/2020 SIGNATURE

E-mail address: howie.lucas@chevron.com PHONE: (832)-588-4044 Type or print name Howie Lucas For State Use Only DATE 5-29-26 - 6

TITLE (

APPROVED BY: Conditions of Approval (if any)

Wellbore Diagram



Wellbore Diagram

