State of New Mexico Office	Form C-103			
District I Energy, Minerals and Natural Resources	May 27, 2004			
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.			
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-005-20004			
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 Santa E. NIM 87505	STATE FEE S			
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.			
87505				
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	CATO SAN ANDRES UNIT			
1. Type of Well: Oil Well Gas Well Other	8. Well Number 44			
2 Name of Operator	9. OGRID Number 183718			
LOTHIAN OIL INC. UHC NEW Mexico Corp	3. OGIGD Number 103710			
3. Address of Operator	10. Pool name or Wildcat			
405 N. MARIENFELD, MIDLAND, TX 79701	CATO SAN ANDRES - 10540			
4. Well Location				
	0 1 70 000 11			
Unit Letter I :1,980'_feet from theSOUTH line and660'_feet				
Section 9 Township 18-S Range 30-E NMPM				
11. Elevation (Show whether DR, RKB, RT, GR, etc.				
4,056' – GL, 4,068' – DF				
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	stance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; C	onstruction Material			
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data			
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:			
-				
	RILLING OPNS. P AND A			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB			
	IT JOB			
OTHER: OTHER:				
OTHER: OTHER: OTHER: OTHER:	nd give pertinent dates, including estimated date			
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OF starting any proposed work). SEE RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: OTHER: OTHER: OTHER:	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OF starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' - 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors.	and give pertinent dates, including estimated date trach wellbore diagram of proposed completion C & Tag Received Hobbs OCD OCD Received			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' - 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors.	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion C & Tag Received Hobbs OCD Received			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors.	and give pertinent dates, including estimated date trach wellbore diagram of proposed completion 8 Tag Received Hobbs OCD ROTTON DIVISION MUST HOURS PRIOR TO THE			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors.	and give pertinent dates, including estimated date trach wellbore diagram of proposed completion 8 Tag Received Hobbs OCD ROTTON DIVISION MUST HOURS PRIOR TO THE			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Stub (50' Below & Above Stub). WOC Stub (50' Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' – 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors. THE OIL CONSEPBERONING OF Plus of the best of my knowled.	ad give pertinent dates, including estimated date trach wellbore diagram of proposed completion 8 Tag Received HAY 2000 Received Hobbs OCD ROTTO THE LUGGING OPERATION Sty pit or below-			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' - 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors.	ad give pertinent dates, including estimated date trach wellbore diagram of proposed completion 8 Tag Received HAY 2005 Received Hobbs OCD ROTTO THE LUGGING OPERATION Sty pit or below-			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Spot a 100' Plug f/ 1,065' − 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors. THE OIL CONSEF BE NOTIFIED 24 BEGINNING OF PLANTING OF PLA	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2. & Tag Received Hobbs OCD REVATION DIVISION MUST HOURS PRIOR TO THE LUGGING OPERATIONS by pit or below- or an (attached) alternative OCD-approved plan			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC 5) Pmp 9.5 - 10 ppg Mud between Plugs. 6) Spot a 100' Plug f/ 1,065' − 1,165'. 7) Pmp 9.5 - 10 ppg Mud between Plugs. 8) Spot a 100' Plug f/ 454' - 554'. (Surf. Csg Shoe Plug). WOC & Tag. 9) Spot Cmt f/ 30' to Surf. 10) Cut Off Well Head & Cap below 3' & Install a Dry Hole Marker. 11) Remove all Rig Anchors. THE OIL CONSEPBER BE NOTIFIED 24 BEGINNING OF PI I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □	ad give pertinent dates, including estimated date trach wellbore diagram of proposed completion 8 Tag Received HAY 2000 Received Hobbs OCD ROTTO THE LUGGING OPERATION Sty pit or below-			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Stub (50' Below (50' Be	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2 & Tag Received Hobbs OCD REVATION DIVISION MUST HOURS PRIOR TO THE LUGGING OPERATIONS: y pit or below- or an (attached) alternative OCD-approved plan DATE: May 18, 2006			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC St	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2 & Tag Received Hobbs OCD REVATION DIVISION MUST HOURS PRIOR TO THE LUGGING OPERATIONS: y pit or below- or an (attached) alternative OCD-approved plan DATE: May 18, 2006			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC St	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2 & Tag Received Hobbs OCD REVATION DIVISION MUST HOURS PRIOR TO THE LUGGING OPERATIONS: y pit or below- or an (attached) alternative OCD-approved plan DATE: May 18, 2006			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC St	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2 & Tag Received Hobbs OCD PEZL RECEIVED RECEIVED			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC St	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2 & Tag Received Hobbs OCD REVATION DIVISION MUST HOURS PRIOR TO THE LUGGING OPERATIONS: y pit or below- or an (attached) alternative OCD-approved plan DATE: May 18, 2006			
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) RIH to 3,200' & Set a CIBP. Spot a 35' Cmt Plug. WOC & Tag. 2) Free Point 4-1/2" Csg. 3) Chemical Cut 4-1/2" Csg & POOH & Salvage 4-1/2" Prod. Csg. 4) Spot a 100' Plug across 4-1/2" Csg Stub (50' Below & Above Stub). WOC Stub (50' Below (50' Be	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 2 & Tag Received Hobbs OCD PEZL RECEIVED RECEIVED			

LOTHIAN OIL, INC.

CONDITION OF HOLE

INJECTION WELL

								3/15/06	
FIELD:	Cato San Andres	LE	EASE:	Cato San	Andres Unit	_ WEL	L NO:	44	-
LEGAL:	1980' FSL & 660'	FEL, Unit I, Sec. 9, T-8-S, R-30-E, NMPM, Chaves County, NM							
API No.:		30-005-20004 SPUD DATE:				02/04/67			
STATE LE	EASE No.:				COMPLET	ION DA	TE:	02/22/67	
REASON	FOR WORK:	To increase wa	ter injecti	on.					
CONDITIO	ON OF HOLE:								
	TOTAL DEPTH:	3,500'	PBTD):3,390'	KB DATUN	vi:	12'	Above:	4,056'-GL, 4,068'-DI
С	ASING RECORD:	12 jts (491') of 107 jts (3,490') Replaced Top 5	of 4-1/2",	9.5#, J-55,					
	PERFORATIONS:	3,256-87' w/ 1-	JSPF. A	Total of 31' I	Net Perfs & 31	1 Holes.			P-1
		3,320-56' w/ 1-JSPF. A Total of 36' Net Perfs & 36 Holes.						P-2	
		3,406'-18' w/ 1-JSPF. A total of 12' Net Perfs & 12 Holes.					P-3		
	TUBING DETAIL:								
W	ellhead Model, Ty	pe & Rating:							
	Po	umping Unit:							
ROD 8	& PUMP DETAIL: Rod Pump: Polish Rod:				Pol Rod Li	iner:			
REGULA	TORY REQUIREM	ENTS:							
		V	VELL H	ISTORY:					
2/4/67	Spud Well for Un Orignal Well Na Ran 12 jts (491') Cmt'd w/ 300 sxs	me: Crosby # 5 of 8-5/8", 20#, J	5 I-55, 8V, S	ST&C Surf C	sg. Set Csg		515'.		
2/15/67	Drilled 7-7/8" Hol Ran 107 jts (3,49	-		Brd, ST&C P	rod Csg. Set 0	Csg @ 3	3,500'.		

Cmt'd w/ 150 sxs of Cl "C" Incor +12% Gel + 1/4#/sx Flocele + 5#/sx Gilsonite &

Tailed w/ 150 sxs of 50-50 Incor Pozmix + 2% Gel + 10#/sx Salt. TOC @ 2,300' by T.S.

2/17/67 Perf'd the P-3 f/ 3,406'-18' w/ 1-JSPF. A total of 12' Net Perfs & 12 Holes.

Acidized the P-3 f/ 3,406-18' w/ 1,500 gals of 15% DS-50 Acid. Drp'd 9 BS f/ divert.

Pmax: 3300#, Pavg: 3200#, ISIP: 2800#, AIR: 2.5 BPM.

2/18/67 Acidized the P-3 f/ 3,406-18' w/ 3,000 gals of 28% DS-50 Acid. Drp'd 9 BS f/ divert. Pmax: 3100#, Pavg: 2600#, ISIP: 2400#, AIR: 3.6 BPM.

2/20/67 Set Baker CIBP @ 3,390'

Perf'd the P-2 f/ 3,320-56' w/ 1-JSPF. A Total of 36' Net Perfs & 36 Holes. Perf'd the P-1 f/ 3,256-87' w/ 1-JSPF. A Total of 31' Net Perfs & 31 Holes.

2/21/67 Acidized the P-2 f/ 3,320-56' w/ 3,500 gals of 15% DS-50 Acid. Drp'd 30 BS f/ Divert.

Pmax: 2100#, Pavg: 1700#, ISIP: 1800#, AIR: 2.5 BPM

Acidized the P-1 f/ 3,256-87' w/ 3,000 gals of 15% DS-50 Acid. Drp'd 25 BS f/ Divert.

Pmax: 2500#, Pavg: 2000#, ISIP: 1750#, AIR: 3.5 BPM

2/22/67 I P 'd: 91 BOPD, 71 BWPD, 0 MCFPD

5/30/75 Frac'd the P-2 Perfs f/ 3,320'-56' Dwn Tbg w/ 30,000 gals of Gel BW + 36,000# 20-40 Sd in 5 Stgs. Sd Concen: 1/2 - 2 ppg. Csg on Vac when Pmp'ing Sd. FRMBRKDWN: 4,000# - 3,800# Pmax: 4000#, Pavg: 3,950# ISIP: 2200#, AIR: 10.5 BPM

5/31/75 Frac'd the P-1 Perfs f/ 3,256'-87' w/ 30,000 gals of Gel BW + 36,000# 20-40 Sd in 5 Stgs. Sd Concen: 1/2 - 2 ppg. Csg on Vac when Pmp'ing Sd. FRMBRKDWN: 4,000# - 3,800# Pmax: 4000#, Pavg: 3,850# ISIP: 2000#, AIR: 11.5 BPM

5/1/86 Change of Ownership: Apollo Energy of Hobbs, NM bought the well.
Well Name has changed to UT Crosby "1" # 5

2/2/88 Change of Ownership: Kelt Oil & Gas of Roswell, NM bought the well.

02/12/90 Well Name has changed to CATO San Andres Unit # 44

04/01/91 Well was Converted f/ Production to Water Injection. POOH w/ Rod Pump, Rods & Tbg.

Cut 4-1/2" Csg @ 650'. POOH & LD Top 5 Jts of 4-1/2" Csg.Washed Dwn Lead Csg Patch &

Tied String Back Together @ 650' w/ 5 jts of 4-1/2". TST'd Csg to 300# -OK. CO Fill & Pushed CIBP Dwn to 3,390'

Ran 2-3/8" PCID Tbg w/ Baker Mod. AD-1 Pkr. SPA 3,192'. Load Annulus w/ 58 bbls of Pkr Fluid.

Start Wtr Inj on 9/28/90 in accordance with Division Order # 9029, Dated: 10/30/89.

04/03/95 POOH & LD Inj. Pkr & PCID Tbg. T & A'd Well.

11/01/95 Change of Ownership: Secondary Oil Corp. of Marble Falls, TX bought the well.

12/01/97 Change of Ownership: Seirra Blanca Operating Co. of Cleburne, TX bought the well.

06/01/99 Change of Ownership: UHC New Mexico Corp. of Cleburne, TX bought the well.

12/27/05 Lothian Oil Bought the Well.