

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-025-09301 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name: STATE A A/C 3 |
| 8. Well Number 3 |
| 9. OGRID Number 194849 |
| 10. Pool name or Wildcat LANGLIE MATTIX 7 RVRS QUEEN, GB |

Pit or Below-grade Tank Application ☐ or Closure ☐
Pit type N/A Depth to Groundwater 149' Distance from nearest fresh water well 1000+ Distance from nearest surface water 1000+
Pit Liner Thickness: N/A mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other _____

2. Name of Operator
PETROHAWK OPERATING COMPANY

3. Address of Operator
1100 LOUISIANA, STE. 4400 HOUSTON TX 77002

4. Well Location
Unit Letter I : 1980 feet from the SOUTH line and 660 feet from the EAST line
Section 10 Township 23S Range 36E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3460' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| PLUG AND ABANDON <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| MULTIPLE COMPLETION <input type="checkbox"/> | OTHER: <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | |

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.**

See attached for Procedure and Wellbore Schematic to Plug and Abandon Well

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE [Signature] TITLE Regulatory Analyst DATE 05/16/06
E-mail address: _____ Telephone No. 832-204-2760

Type or print name Anna Tarpey

For State Use Only

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY [Signature] TITLE _____ DATE MAY 19 2006
Conditions of Approval, if any: _____



State A A/C-3 #3
Jalmat Field
Lea County, NM

May 15, 2006

Plug and Abandonment Procedure

1. MIRU plugging rig. Dump 35' cement on top of CIBP at 3603'.
2. TIH with open ended workstring to PBTD and load hole with 10 ppg gelled brine.
3. Mix and spot 200' bottom of salt plug from 2850' to 2650' (58 sx class A).
- * 4. Perforate 5-1/2" casing at 1410'. Mix 200' top of salt cement plug (100 sx class A). Pump through perfs at 1410' leaving top of cement inside casing at 1210'.
5. Perforate 5-1/2" casing @ 385'. Mix surface plug (260 sx class A). Squeeze through perfs at 385', attempting to circulate cement to surface. Leave top of cement inside casing at surface.
6. Cut off wellhead, cap well and install P&A marker.
7. Clean location for OCD inspection.

→ WOC + TAG



