	of New Mexico		m C-103
Office Energy, Minera	als and Natural Resources	WELL API NO.	y 27, 2004
1625 N. French Dr., Hobbs, NM 87240 District II	2122232	30 · 025 · 09358	-
1301 W. Grand Ave., Artesia, NM 88210	ERVATION DIVISION STORES	5. Indicate Type of Lease	
District III 1220 SG 1000 Rio Brazos Rd., Aztec, NM 87410 Sant	ta Fe, NM 87505	STATE 🗓 FEE 🗆	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	5	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPOR	TS ON WELLS	7. Lease Name or Unit Agreement	Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR	TO DEEPEN OR PLUG BACK TO A	STATE A A/C 1	Traine.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT PROPOSALS.)	" (FORM C-101) FOR SUCH		
1. Type of Well:	10 10 10 10 10 10 10 10 10 10 10 10 10 1	8. Well Number	_
Oil Well X Gas Well Other		39	
2. Name of Operator		9. OGRID Number	_
PETROHAWK OPERATING COMPANY  3. Address of Operator		194849 10. Pool name or Wildcat	
1100 LOUISIANA, STE. 4400 HOUSTON TX 770	02	JALMAT TANSILL YATES 7 RVRS	QUEEN
4. Well Location			
Unit Letter J : 1980 feet from	the SOUTH line and	1980 feet from the EAST	line
Section 17 Townshi	<u> </u>	NMPM County	LEA
11. Elevation (5)	how whether DR, RKB, RT, GR, et 3461'KB	(c.)	
Pit or Below-grade Tank Application or Closure		Dougle department of the C.S. and Dougle of the Control of the Annual Control of the Annual Control of the Control of the Annual Control of the Control of t	
Pit type N/A Depth to Groundwater 149' Distance from	om nearest fresh water well <u>1000+</u> Di	stance from nearest surface water 1000+	_
Pit Liner Thickness: N/A mil Below-Grade	Fank: Volumebbls; Constructi	on Material	
12 Check Appropriate Roy	to Indicate <sub>I</sub> Nature of Notice,	Penart or Other Data	
NOTICE OF INTENTION TO:	· · · · · · · · · · · · · · · · · · ·	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABAI		ALTERING O	ASING [
	_	<del></del>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
TEMPORARILY ABANDON	COMMENCE DRILL	ING OPNS. PLUG AND ABANDONM	IFNT L
PULL OR ALTER CASING  MULTIPLE  MULTIPLE	☐ CASING TEST AND		
COMPLETION	CEMENT JOB		
OTHER:	OTHER:		
13. Describe proposed or completed operations. (Clear	ly state all pertinent details, and giv	e pertinent dates, including estimated	date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.  THE OIL CONSERVATION DIVIS:			
BE NOTIFIED 24 HOURS PRIOR			
		IG OF PLUGGING OPERA	
Charles de Carlo Daniel			دوقسیم ټاني د ښا د، عا
See attached for Procedure	e and Wellbore Schematic to F	olug and Abandon Well	
THE OIL CONSERVATION DIVISION	N MUST		
BE NOTIFIED 24 HOURS PRIOR	TO THE		
DE NOTIFIED 24 HOOTIGE MAN	ATIONS.		
I hereby certain that the information above is true and con	mplete to the best of my knowledg	e and belief. I further certify that any pi	t or below-
grade tank has been will be constructed or closed according to NM			
SIGNATURE		ry Analyst DATE 05	/16/06
Type or print name Anna Tarpey	E-mail address:	Telephone No. 832-	204-2760
For State Use Only	OC FIELD REPRESENT	ATIVE II/STAFF MANAGER	
$\mathcal{A}_{i}$			9 2006
APPROVED BY Solutions of Approval, if any:	TITLE	DATE	
Conditions of Approval, it any.			



## State A A/C-1 #39 Jalmat Field Lea County, NM

May 15, 2006

## **Plug and Abandonment Procedure**

- 1. MIRU plugging rig. ND wellhead. NU BOP. TIH with workstring and 4-3/4" bit to ~3475'. POH w/tbg and bit.
- 2. RU wireline and set CIBP at ~3470'. Dump 35' of cement on top of CIBP.
- 3. TIH w/open ended tubing to PBTD and load hole with 10 ppg gelled brine.
- 4. Mix and spot 200' base of salt cement plug from 3260' to 3060' (23 sx of class A).
- 5. Perforate 5-1/2" casing at 1725'. Mix 200' top of salt cement plug (55 sx class A). Pump through perfs at 1725' leaving top of cement inside casing at 1525'.
  - 6. Perforate 5-1/2" casing @ 350'. Mix surface plug (96 sx class A). Squeeze through perfs at 350', attempting to circulate cement to surface. Leave top of cement inside casing at surface.
    - 7. Cut off wellhead, cap well and install P&A marker.
    - 8. Clean location for OCD inspection.

WOC + TAG



