when the 2 Charles The Association Director				
Submit 3 Copies To Appropriate District	State of New Me			Form C-10
District I	Energy, Minerals and Natur	ral Resources		Revised March 25, 199
625 N. French Dr., Hobbs, NM 87240 District II			WELL API NO.	
11 South First, Artesia, NM 87210	OIL CONSERVATION	DIVISION		025 - 36220
<u>District III</u> 000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco		5. Indicate Type of Lease	
District IV	Santa Fe, NM 87	505	STATE	
040 South Pacheco, Santa Fe, NM 87505			6. State Oil & C	
SUNDRY NOTIC	ES AND REPORTS ON WELLS		7. Lease Name	V-05343
O NOT USE THIS FORM FOR PROPOSALS TO DRILL (APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	OP TO DEEDENI OP DI LICI DACIZ TO A DIERENTIN	RESERVOIR. USE	Name:	or Unit Agreement
. Type of Well:	PROPOSALS.)		r unie.	
Oil Well 🔲 Gas Well	Other		Stat	e Com 9
Name of Operator			8. Well No.	
I.L. Brown Operating L.L.C	• OGRID # 21	3179		1
. Address of Operator			9. Pool name or	Wildcat
00 West Louisiana, Midland	, Texas 79702		Feather N	Morrow, North
Well Location	nt and a start of the second	······································		
Unit Letter H	1650? Sections the Nor			
	1650' feet from the Nor	th line and	990' feet from	the <u>East</u> line
Section 9 To	ownship 15 - S Range	32 - E NI	MPM L	ea County
	1. Elevation (Show whether DR			
	4303' GL, 4	1320' KB		
11. Check App	propriate Box to Indicate Na	ture of Notice, R	Report or Other	Data
NOTICE OF INTI	ENTION TO:		SEQUENT REI	
ÉRÊORM REMEDIAL WORK 🗖 🛛 I	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
	CHANGE PLANS	COMMENCE DRIL	LING OPNS. 🗖	
				PLUG AND ABANDONMENT
ULL OR ALTER CASING		CASING TEST/ CE		
ULL OR ALTER CASING	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp		ABANDONMENT
ULL OR ALTER CASING	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp		ABANDONMENT
ULL OR ALTER CASING THER THER escribe proposed or completed operations: (ULE 1103. For Multiple Completions: Attac	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp		ABANDONMENT
ULL OR ALTER CASING THER THER escribe proposed or completed operations: (ULE 1103. For Multiple Completions: Attac	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp		ABANDONMENT
ULL OR ALTER CASING THER THER escribe proposed or completed operations: (JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp		ABANDONMENT
ULL OR ALTER CASING THER THER escribe proposed or completed operations: (JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#,	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp pertiment dates, including on or recompilation.		ABANDONMENT
ULL OR ALTER CASING THER THER escribe proposed or completed operations: (f JLE 1103. For Multiple Completions: Attack ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138"	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation.		ABANDONMENT
ULL OR ALTER CASING THER escribe proposed or completed operations: (i JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation.		
ULL OR ALTER CASING THER THER tescribe proposed or completed operations: (JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138" Pickled tubing and spot acid of Perforated the Morrow with a	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation.		ABANDONMENT mation ing any proposed work). SEI MUL 2003 MUL 2003 K
ULL OR ALTER CASING THER escribe proposed or completed operations: ((JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp pertiment dates, including on or recompilation. nt to 12,495'. 3% KCI water. 2,344' to 12,364'.	EMENT JOB	ABANDONMENT
ULL OR ALTER CASING THER escribe proposed or completed operations: (TLE 1103. For Multiple Completions: Attac completion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. ', 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. nt to 12,495'. 3% KCI water. 2,344' to 12,364'.	EMENT JOB	ABANDONMENT mation ing any proposed work). SE MUL 2003 MUL 2003 K
ULL OR ALTER CASING THER escribe proposed or completed operations: (JLE 1103. For Multiple Completions: Attac Dompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10 Flowed and swabbed back loa	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7, 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. nt to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build	EMENT JOB	ABANDONMENT mation ing any proposed work). SE MUL 2003 MUL 2003 K
ULL OR ALTER CASING THER escribe proposed or completed operations: (f) ULE 1103. For Multiple Completions: Attack completion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du	MULTIPLECOMPLETION Clearly state all pertinent details; and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7, 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok imped 35' cement on CIBP at 5	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. nt to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build	EMENT JOB	ABANDONMENT mation ing any proposed work). SE MUL 2003 MUL 2003 K
ULL OR ALTER CASING THER escribe proposed or completed operations: (ULE 1103. For Multiple Completions: Attac Dempletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138" Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10 Flowed and swabbed back loa	MULTIPLECOMPLETION Clearly state all pertinent details; and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7, 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok imped 35' cement on CIBP at 5	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. nt to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build	EMENT JOB	ABANDONMENT mation ing any proposed work). SE MUL 2003 MUL 2003 K
ULL OR ALTER CASING THER escribe proposed or completed operations: (i JLE 1103. For Multiple Completions: Attack ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du	MULTIPLECOMPLETION Clearly state all pertinent details; and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7, 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok imped 35' cement on CIBP at 5	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. nt to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build	EMENT JOB	ABANDONMENT mation ing any proposed work). SEI MUL 2003 MUL 2003 K - Hobbs
ULL OR ALTER CASING THER escribe proposed or completed operations: ((JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete	MULTIPLECOMPLETION	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. and to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build 12,295' in 2 runs w	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start pressure. vith a bailer.	ABANDONMENT mation ing any proposed work). SEI MUL 2003 MUL 2003 K
ULL OR ALTER CASING THER rescribe proposed or completed operations: (JLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid on Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 10 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete hereby certify that the information at	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok imped 35' cement on CIBP at 5 to the Wolfcamp. bove is true and complete to the bo	CASING TEST/ CE OTHER comp pertiment dates, including on or recompilation. The second second second second second second second second second second second	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start en per barrel pressure. with a bailer.	ABANDONMENT mation ing any proposed work). SEI MUL 2003 MUL 20
ULL OR ALTER CASING THER escribe proposed or completed operations: (0) TLE 1103. For Multiple Completions: Attack completion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid on Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 100 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete ereby certify that the information at GNATURE	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok imped 35' cement on CIBP at 5 to the Wolfcamp. bove is true and complete to the be 	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. and to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build 12,295' in 2 runs w	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start en per barrel pressure. with a bailer.	ABANDONMENT mation ing any proposed work). SE MUL 2003 MUL 200
ULL OR ALTER CASING THER THER rescribe proposed or completed operations: ((JLE 1103. For Multiple Completions: Attack ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid of Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 100 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete hereby certify that the information at GNATURE	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various chok imped 35' cement on CIBP at 5 to the Wolfcamp. bove is true and complete to the be 	CASING TEST/ CE OTHER comp pertiment dates, including on or recompilation. The second second second second second second second second second second second	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start g estimated date of start g estimated date of start date of start g estimated date of start g	ABANDONMENT mation ing any proposed work). SET MUL 2003 MUL 20
ULL OR ALTER CASING THER Describe proposed or completed operations: (I) TLE 1103. For Multiple Completions: Attack Ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid on Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 100 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete nereby certify that the information at GNATURE /pe or print name Robert McNa his space for State use)	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various choke imped 35' cement on CIBP at 3 to the Wolfcamp. bove is true and complete to the be 	CASING TEST/ CE OTHER comp pertiment dates; including on or recompilation. and to 12,495'. 3% KCI water. 2,344' to 12,364'. 1500 SCF Nitroge tes and SI to build 12,295' in 2 runs w est of my knowledge <u>Petroleum Engin</u>	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start pressure. with a bailer. e and belief. neer DA e No. 915 – 68	ABANDONMENT mation ing any proposed work). SEI ML 2003 ML 200
ULL OR ALTER CASING THER rescribe proposed or completed operations: ((JLE 1103. For Multiple Completions: Attack ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid on Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 100 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete mereby certify that the information at GNATURE	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7 10007' and wiper plug/ ceme n bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various choke imped 35' cement on CIBP at 3 to the Wolfcamp. bove is true and complete to the be 	CASING TEST/ CE OTHER comp pertiment dates, including on or recompilation. The first states including on or recompilation. KCI water. 2,344' to 12,364'. 1500 SCF Nitroget ses and SI to build 12,295' in 2 runs w est of my knowledget <u>Petroleum Engin</u> Telephone	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start pressure. with a bailer. e and belief. neer DA e No. 915 – 68	ABANDONMENT mation ing any proposed work). SER ML 2003 NL 200
ULL OR ALTER CASING THER escribe proposed or completed operations: (i) TLE 1103. For Multiple Completions: Attac ompletion Summary: 6-16-03 to NU BOP and PU 2-7/8", 6.4#, Drilled out stage tools at 9138' Pickled tubing and spot acid on Perforated the Morrow with a Set packer at 12,253' with 20 p Acidized Morrow perfs with 100 Flowed and swabbed back loa Set 10K CIBP at 12,295 ft. Du Prepare to recomplete nereby certify that the information at GNATURE	MULTIPLECOMPLETION Clearly state all pertinent details, and give th wellbore diagram of proposed completion 7-01-03 L-80 YB tubing. 7 10007' and wiper plug/ ceme In bottom. Displaced hole with 3 4" casing gun at 4 SPF from 12 pts and NU wellhead. 00 gal 7½ % Morrow acid with d. Tested flow on various choked imped 35' cement on CIBP at 3 to the Wolfcamp. bove is true and complete to the be 	CASING TEST/ CE OTHER comp pertiment dates, including on or recompilation. The first states including on or recompilation. KCI water. 2,344' to 12,364'. 1500 SCF Nitroget ses and SI to build 12,295' in 2 runs w est of my knowledget <u>Petroleum Engin</u> Telephone	EMENT JOB Dete in Morrow fo g estimated date of start g estimated date of start pressure. with a bailer. e and belief. neer DA e No. 915 – 68	ABANDONMENT mation ing any proposed work). SEE

4