Submit 3 Copies' To Appropriate District State of New Mexico	Form C 102
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Form C-103 Revised March 25, 1999
District I	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III	<u>30-025-36036</u> 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec. NM 87410 1220 South St. Francis Dr.	STATE STATE
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name:
 Type of Well: Oil Well Gas Well X Other Name of Operator 	Hampton 1
Chesapeake Operating, Inc.	8. Well No.
3. Address of Operator	001
P.O. Box 18496, Oklahoma City, OK 73154-0496 4. Well Location	9. Pool name or Wildcat Wildcat Morrow
4. Well Location	
Unit Letter N: 660 feet from the South line and	2050 feet from the West line
Section 1 Township 15S Range 35E	NMPM Lea County
10. Elevation (Show whether DR. RKB, RT. GR. etc.	c)
GR : 3966.7' 11. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO	Parata Al
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK	$K \qquad \square \text{ALTERING CASING } \square$
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING DI MULTIPLE DI CASING TEST AN COMPLETION CASING TEST AN CEMENT JOB	
OTHER: OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and gives starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompilation.	L] e pertinent dates, including estimated date of llbore diagram of proposed completion or
See attached workover procedure and schematic	· .
	93031-7-
	JUL 2003
	A LULIVED O
	Hobbs T
	-7-02618171919141460-
hereby certify that the information above is true and complete to the best of my knowledge	
SIGNATURE UNIV Malu TITLE Asset Manager	
ype or print name Andrew J. McCalmont	DATE_07/30/03
This space for State use)	Telephone No. (405) 848-8000
A STATUS AND A STATUS AND A STATUS II/STAT	FMANAGER
LPPPROVED BY Law W. Wink OC FIELD REFRESENTATIONS OF Approval, if any: (DATEAUG 0 4 2003
the second	AUG 0 4 2003

Hampton #1-1 WORKOVER PROCEDURE

- 1) Move in well service company. Kill pressure as required with 2% KCL. NDWH and NUBOP. Unset Model R @ 13,165' and POOH w/ tubing and packer.
- 2) MIRU wireline service unit. RIH w/ 5.5" 17# CIBP and set @ 13,165' (above Morrow). Bail 2 sx of cement on top plug.
- 3) RIH w/ 5-1/2" Model R packer, SN, and 2-7/8" tubing to 12,475'. Space out tubing. Break circulation and circulate 2% KCL around backside. Set packer and land tubing with 10,000# compression. Pressure test annulus to 2000#.
- 4) NDBOPE. NUWH. Swab FL down to 5000' from surface.
- 5) RU lubricator and RIH w/ 2" wireline conveyed gun and perforate the Atoka w/ 4 SPF, .42" hole, 60 deg. phasing from 12,516 – 24' (32 holes). Correlate to OH Neutron-Density log dated 12/14/02.
- 6) Swab well in as required. Flow test to clean up well. Pressure backside to 2000# and break down zone w/ one tubing volume of 2% KCL water to establish rate. Acidize w/ 500 gal of 7-1/2% HCL foamed w/ 2.6 tons of CO2 containing 245 gal of methanol and additives per service company specifications. Displace w/ 72 bbl of 2% KCL foamed w/ 15.2 tons of CO2. Flow test well.
- 7) Frac well as warranted. POOH w/ tubing and packer. Establish pad rate and frac the Brunson with a 28,000 gal Binary system carrying 31,100 pounds of 20/40 mesh Sintered Bauxite. Treat via 5-1/2" casing at 10.5 BPM foam rate with an anticipated well head treating pressure of 7,500 psi per Service Company specifications. Flow back to clean up well.
- 8) RIH w/ tubing and packer. Set packer @ 12,475'. Swab/flow test well. Put well on production.



· · · · b

CURRENT WELLBORE SCHEMATIC CHESAPEAKE OPERATING, INC.

