Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resou	urces Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III	ON <u>30-025-32625</u> 5. Indicate Type of Lease
1000 Rio Brazos Rd. Aztec NM 87410	STATE X FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	VA-2883
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Button Up AYD State Com 8. Well Number
1. Type of Well: Oil Well Gas Well X Other	o. wen Number
2. Name of Operator	
Yates Petroleum Corporation	9. OGRID Number 025575
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth Street - Artesia, NM 88210	Wildcat Canyon
4. Well Location	
Unit Letter <u>C</u> : 600 feet from the North line and 2305 feet from the West line	
Unit Letter <u>C</u> : '600 feet from the <u>North</u> line and <u>2305</u> feet from the <u>West</u> line	
Section 10 Township 9S Range 3	2E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT,	GR, etc.)
4444' GR	
12. Check Appropriate Box to Indicate Nature of I	
	AL WORK ALTERING CASING
TEMPORARILY ABANDON	NCE DRILLING OPNS. 🗌 PLUG AND 🛛 🗱
PULL OR ALTER CASING DIMULTIPLE DI CASING	ABANDONMENT
COMPLETION CEMENT	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
$\vec{B} = 6-20-03$ - Moved in and rigged up pulling unit and plugging equipment. Shut down for	
a g gnight.	
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
5 g tubing equipment and floor. POOH with 2-7/8" tubing and packer. RIH with tubing and	
g Son/off tool to 5000'. Shut well in for night.	
 g g g g g g g g g g g g g g g g g g g	
g is 26-25-2003 - RIH with tubing set CIBP and set CIBP at 9890'. Shut well in for night.	
a g g6-26-2003 - Circulated hole with plugging mud. Capped CIBP with 10 sacks of class C	
명 려 "Neat cement from 9890-9791'. POOH with tubing to 4000'. Shut well in for night.	
6 27-2003 - Finished POOH with tubing. Shut well in for night.	
É 5 66-28-30-2003 - Rigged up wireline. RIH and perforated 5-1/2" ca \$i ng at 6300'. POOH ↓ and rigged down wireline. RIH with packer and tubing and set packer at 6008'. Pressured	
up to 1500 psi. POOH with packer and tubing. RI	Ding and set packer at 6008'. Pressured
I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE:	
SIGNATURE Storme Daries TITLE	DATE
Type or print name E-mail address:	Telephone No.
(This space for State use) OC FIELD REPU	μ(00 ³
APPPROVED BY How Willing TITLE AUG 0 5 2002	
Conditions of approval, if any:	

YATES PETROLEUM CORPORATION Button Up AYD State Com #1 Section 10-T9S-R32E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

Spotted 25 sacks Class C Neat cement from 6364-6117'. POOH with tubing. Shut well in for night. WOC. 7-1-2003 - RIH with tubing and tagged cement at 6047'. POOH with tubing. Rigged up wireline. RIH and perforated 5-1/2" casing at 3756'. POOH and rigged down wireline. RIH with packer and tubing and set packer at 3462'. Pressured up to 1500 psi. POOH with packer and tubing. RIH with tubing open ended to 3821'. Spotted 25 sacks Class C Neat cement from 3821-3574'. POOH with tubing. Shut well in for night. WOC. 7-2-2003 - RIH with tubing and tagged cement at 3592'. POOH with tubing. Rigged up wireline. RIH and perforated 5-1/2" casing at 2334'. POOH and rigged down wireline. RIH with packer and tubing and set packer at 2024'. Pressured up to 1500 psi. POOH with packer and tubing. RIH with tubing open ended to 2386'. Spotted 25 sacks Class C Neat cement from 2386-2136'. POOH with tubing. WOC 4 hours. Rigged up wireline. RIH and tagged cement at 2158'. POOH and rigged down wireline. Shut well in for night. 7-3-2003 - Rigged up wireline. RIH and perforated 5-1/2" casing at 451'. POOH and rigged down wireline. RIH with packer and tubing and set packer at 32'. Squeezed with 70 sacks Class C Neat cement from 451-351'. WOC 4 hours. Rigged up wireline. RIH with wireline through tubing - did not tag. POOH and rigged down wireline. Squeezed with 70 sacks Class C Neat cement from 451-351'. Shut well in for night. WOC. 7-4-2003 - Rigged up wireline. RIH through tubing - did not tag. POOH and rigged down wireline. Squeezed with 70 sacks Class C Neat cement from 451-351'. WOC 4 hours. Rigged up wireline. RIH and tagged cement at 336'. POOH and rigged down wireline. POOH with tubing and packer. Rigged down tubing equipment and floor. Nippled down BOP. RIH with tubing to 64'. Circulated hole with 10 sacks Class C Neat cement Shut well in for night. WOC.

7-5-7-2003 - Shut down for holiday.

7-8-2003 - Dug out cellar. Cut off wellhead. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED 050 FINAL REPORT. Plugging completed July 7, 2003.

5 SQQOH $\begin{pmatrix} \ddots \\ & \ddots \\ & & \\ & & \\ & & \\ & & \\ & & & & \\ & & & \\ & & & & \\ & & & & \\ & & & \\ & & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & & \\ & & & & \\ & &$ <u>^_!/ED</u> £002 **ƏUA**

619202152