State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONS	SERVATION DIVISION	
1626 N. Courst Dr. Habba NNA 00240	O South St. Francis Dr. unta Fe, NM 87505	WELL API NO. 30-025 -07363- 0.7/-36
DISTRICT II	ŕ	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		STATE FEE *
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NOTICES AND REPORTS O	i	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DI DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (F		NORTH HOBBS (G/SA) UNIT
	her Injector	8. Well No. 331
Name of Operator Occidental Permian Ltd.		9. OGRID No. 157984
3. Address of Operator		10. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 50 4. Well Location	5/397-8200	
Unit Letter J : 1650 Feet From The SOUT	<u>TH</u> 1650 Feet	From the 2223 EAST Line
	S-S Range 38-E	NMPM LEA County
11. Elevation (Show whether L 3645 GL	OF, RKB, RT GR, etc.)	V5
Pit or Below-grade Tank Application or Closure		istance from hearest surface water
Pit Type Depth of Ground Water Distance fro	m nearest fresh water wellDi	istance from liearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume _	bbls; Construction Material	
	te Nature of Notice, Report, or Other	
NOTICE OF INTENTION TO:	SUBS	SEQUENT, REPORT OF:
		
PERFORM REMEDIAL WORK PLUG AND ABANDON	X REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG & ABANDONMENT
		PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: It details, and give pertinent dates, include	PLUG & ABANDONMENT JOB Ling estimated date of starting any proposed work)
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagram	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: It details, and give pertinent dates, include	PLUG & ABANDONMENT JOB
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagram. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ fram of proposed completion or recomplet each with cement.	PLUG & ABANDONMENT JOB Ling estimated date of starting any proposed work) cion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagram. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to see the complete of the complete of the complete of the complete of the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft. and attempt to circulate cement to see the cap at 2400 ft.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ fram of proposed completion or recomplet each with cement.	PLUG & ABANDONMENT JOB Ling estimated date of starting any proposed work) cion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagram. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ fram of proposed completion or recomplet each with cement. surface in 4-1/2"x7 annulus through CI	PLUG & ABANDONMENT JOB Ling estimated date of starting any proposed work) cion. CR.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagration. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to s4. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attered for the perforation of the perforation of the perforation of the perforate 4-1/2" at 200 ft and attered for the perforation of the perforate 4-1/2" at 200 ft and attered for the perforation of the perforati	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI empt to circulate cement to surface, lea	PLUG & ABANDONMENT IOB Ing estimated date of starting any proposed work) ion. CR. Living 4-1/2 full of cmt.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attered for the set of the se	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI- empt to circulate cement to surface, lea	PLUG & ABANDONMENT JOB Ling estimated date of starting any proposed work) CR. Living 4-1/2 full of cmt. VISION MUST
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attered for the set of the se	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI- empt to circulate cement to surface, lea	PLUG & ABANDONMENT JOB Ling estimated date of starting any proposed work) CR. Living 4-1/2 full of cmt. VISION MUST
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attempt to circulate diagram. THE COMPLET COMP	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: Int details, and give pertinent dates, includ fram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI empt to circulate cement to surface, lead OIL CONSERVATION DIVIDITIED 24 HOURS PR	PLUG & ABANDONMENT DOB Ding estimated date of starting any proposed work) CR. Eving 4-1/2 full of cmt. VISION MUST IOR TO THE
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attempt to circulate diagram. THE COMPLET COMP	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: at details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI- empt to circulate cement to surface, lea	PLUG & ABANDONMENT DOB Ding estimated date of starting any proposed work) CR. Eving 4-1/2 full of cmt. VISION MUST IOR TO THE
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. 4. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attered in the set of the	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: It details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. surface in 4-1/2"x7 annulus through CI empt to circulate cement to surface, lea OIL CONSERVATION DIV OTIFIED 24 HOURS PR WINING OF PLUGGING O	PLUG & ABANDONMENT JOB Jing estimated date of starting any proposed work) CR. Living 4-1/2 full of cmt. VISION MUST JOR TO THE PERATIONS.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attempt to circulate diagram. THE COMPLET COMP	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: It details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. surface in 4-1/2"x7 annulus through CI empt to circulate cement to surface, lea OIL CONSERVATION DIV OTIFIED 24 HOURS PR WINING OF PLUGGING O	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Eving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. The below-grade tank has been/will be constructed or
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagration 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to standard Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attered. Install dry hole marker with well data. 7. Remove anchors and clean up location. THE COMPANDED BEIN BEGIN	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOTHER: at details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI empt to circulate cement to surface, lead oil CONSERVATION DIVIDITIED 24 HOURS PROVING OF PLUGGING OF PLUGGI	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Inving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. In below-grade tank has been/will be constructed or DCD-approved plan
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to standard Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attended in the standard of the st	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: It details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI cempt to circulate cement to surface, lead of the completion of	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Inving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. In below-grade tank has been/will be constructed or DCD-approved plan
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrams). Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to see 4. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attended in the second of the secon	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOTHER: Int details, and give pertinent dates, includer ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CIVE conservation DIVENTIFIED 24 HOURS PROVINING OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF TITLE Engineering Advises:	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Aving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. To below-grade tank has been/will be constructed or DCD-approved plan TELEPHONE NO. 505-397-8200
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to standard Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attended in the standard of the st	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOTHER: Int details, and give pertinent dates, includer ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CIVE conservation DIVENTIFIED 24 HOURS PROVINING OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF TITLE Engineering Advises:	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Aving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. To below-grade tank has been/will be constructed or DCD-approved plan TELEPHONE NO. 505-397-8200
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrations. 1. Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to s4. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and atte 6. Install dry hole marker with well data. 7. Remove anchors and clean up location. THE COBE NOTICE OF STATE OF S	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOTHER: Int details, and give pertinent dates, includer ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CIVE conservation DIVENTIFIED 24 HOURS PROVINING OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF TITLE Engineering Advises:	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Aving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. To below-grade tank has been/will be constructed or DCD-approved plan TELEPHONE NO. 505-397-8200
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertiner SEE RULE 1103. For Multiple Completions: Attach wellbore diagrated in Notify NMOCD. 2. Set CIBP's at 4090 and 4000 above top perforations. Test and cap 3. Perforate 4-1/2" csg at 2400 ft. and attempt to circulate cement to set. Notify NMOCD of pressure test. 5. If cement not circulated in step 3, perforate 4-1/2" at 200 ft and attered. Install dry hole marker with well data. 7. Remove anchors and clean up location. THE COMBEN. BEGIN I hereby certify that the information above is true and complete to the best of my know closed according to MOCD guidelines agency a general permit SIGNATURE TYPE OR PRINT NAME David Nelson E-mail addr. For State Use Only APPROVED BY	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER: It details, and give pertinent dates, includ ram of proposed completion or recomplet each with cement. Surface in 4-1/2"x7 annulus through CI cempt to circulate cement to surface, lead of the completion of	PLUG & ABANDONMENT JOB Ing estimated date of starting any proposed work) CR. Aving 4-1/2 full of cmt. VISION MUST IOR TO THE PERATIONS. To below-grade tank has been/will be constructed or DCD-approved plan TELEPHONE NO. 505-397-8200