submit 3 copies to Appropriate District Office	-	tate of New Mexico nd Natural Resources Department	Form C-103 Revised 1-1-89		
DISTRICT I. P.O. Box 1980, Hobbs, NM 88 DISTRICT II. P.O. Box Drawer DD, Artesia, N DISTRICT III. 1000 Rio Brazos Rd., Aztec, NI	²⁴⁰ P. IM 88210 Santa Fe, N	RVATION DIVISION .O. Box 2088 New Mexico 87504-2088	WELL API NO. 30-025-35501 5. Indicate Type of Lease STATE FEE 6. State Oil / Gas Lease No.		
SUN (DO NOT USE THIS FORM	DRY NOTICES AND REPORT	R TO DEEPEN OR PLUG BACK TO ATION FOR PERMI	7. Lease Name or Unit Agreement Name J.R. PHILLIPS		
1. Type of Well: OIL WELL 2. Name of Operator			8. Well No. 16		
3. Address of Operator 15	SMITH RD, MIDLAND, TX 7970	15	9. Pool Name or Wildcat MONUMENT ABO		
	Township 20-S	n The <u>NORTH</u> Line and <u>2273</u> Range <u>37E</u> NM nether DF, RKB, RT,GR, etc.) 3575'			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	TENTION TO: PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPE CASING TEST AND CEMEN			
OTHER:		OTHER:	ADD PERFS		

^{12.} Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON U.S.A. INC. INTENDS TO ADD PERFS IN THE MONUMENT ABO, ACIDIZE, & PUT ON ROD PUMP. THE SUBJECT WELL HAS BEEN FLOWING UNTIL IT RECENTLY STOPPED PRODUCING. WELL IS CURRENTLY SHUT-IN .

THE INTENDED PROCEDURE, AND CURRENT AND PROPOSED WELLBORE DIAGRAMS ARE ATTACHED FOR YOUR APPROVAL.

			A 15 16 17 18 79 20 21 P2 23 24 15 16 17 18 79 20 21 P2 23 24 15 16 17 18 79 20 21 P2 23 24 25 20 21 P2 23 24 25 20 20 25 20 20 25 20 20 25 20 20 25 20 20 20 25 20 20 20 20 20 20 20 20 20 20 20 20 20	
I hereby certify that the infogration above is true and co	mplete to the best of my knowledge and belief.			-
SIGNATURE SIGNATURE	IN KETOC TITLE	Regulatory Specialist	DATE7/18/2006	-
	Denise Pinkerton		Telephone No. 432-687-7375	_
(This space for State Use) APPROVED CONDITIONS OF APPROVAL, IF ANY:	TILE	PETROLEUM ENGIN	DATE JUL Des Sur Inde 2018 1.0	-

JR Phillips #16 Monument Abo Section 6, T20S, R37E, Unit F Lea County, NM 30-025-35501

Add Abo Perfs Completion Procedure (use 2% KCl FW for all fluids put on well):

- Displace flowline w/ fresh water. Have Field Specialist close valve at header. Pressure test line according to type. All polypipe (SDR7 and SDR11) will be tested to 100 psi. All steel lines will be tested to 500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If tests good, bleed off pressure and open valve at header. Document this process in the morning report.
- 2. MIRU Key PU & RU. Bleed pressure from well & kill down casing with 2% KCl water. NDWH NUBOP. Test BOP to 1,000 psi when possible. Release Pkr and POOH w/ 2-3/8" Tbg. Evaluate Tbg while POOH.
- 3. PU and GIH w/ 3-7/8" MT bit on 2-3/8" WS and tag for fill (PBTD 6967'). POOH & LD bit.
- 4. RIH w/ 4-1/2" pkr w/ on/off tool and profile to 6800'. Set pkr. Load and test backside to 500 psi. RU swab and swab well recording fluid volumes, rates, pressures, and fluid levels and report to engineer. Note: Pay close attention to the strength of gas. Release pkr and POOH.
- 5. RIH w/ 3-7/8" bit on 2-3/8" WS to 6967'. Drill on and push CIBP to 7047' (TOS). Spot 10' cmt at 7047'. Note: Do not spot more than 10' of cmt as bottom perf will be at 7035'. Allow cement to setup. RIH and tag cement. POOH & LD bit.
- 6. RIH w/ GR & 3-1/8" slick guns loaded w/ 23 gram charges 2 JSPF w/ 120° phasing tied back to Schlumberger's Platform Express Log dated 5/30/2001 as follows:

Top Perf	Bottom Perf	Net Feet	Total Holes
6978	6986	8	16
7004	7010	6	12
7019	7023	4	8
7028	7035	7	14

- RIH w/ 4-1/2" treating pkr on 2-3/8" WS to 6750' testing tubing to 4500 psi. Set pkr @ 6750'. Load and test BS to 500 psi.
- 8. MIRU DS acid truck. Pump 5,000 gals 15% NEFE anti-sludge HCl acid at a max rate of 6 BPM and max treating pressure of 4,500 psi dropping 180 1.3 SG balls

spaced evenly thru job. Displace with 2% KCl water – do not overdisplace. Record ISIP, 5, 10, & 15 minute SIP's. RD DS

Note: Pickle tubing before acid job if rep determines necessary.

- 9. RU swab and swab well. Report recovered fluid volumes, pressures, and fluid levels. Release pkr and POOH.
- 10. RIH w/ 2-3/8" production tbg as per ALS recommendation. NUWH. RIH w/ rods and pump as per ALS. Space out and hang off.
- 11. Turn well over to production.

Engineer – Keith Lopez 432-687-7120 Office 432-631-3281 Cell 432-661-6156 Home



epared by	K M Jackson	Updated By: LC)PK
Date:	6/23/2003	Date: 7/4/2	2006



Remarks: See the well history and failure history attached

pared by: K M Jackson Date: 6/23/2003

.

٩

.

Updated By: LOPK Date: 7/4/2006