Form 3160-5 (April 2004)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGER

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5.	Le	ase S	erial	No.	

NM-14332

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

Do not use the abandoned w	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well X	NMNM94500 8. Well Name and No.	
2. Name of Operator Kaiser	Federal CK Com #1 9. API Well No.	
3a Address P. O. Box 21468,	30-025-27473 10. Field and Pool, or Exploratory Area W. Bilbrey (Atoka)	
4. Location of Well (Footage, Sec.,		
SE NE (1980' FNL &	11. County or Parish, State  Lea/NM	
12. CHECK A	PPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize  Alter Casing  Casing Repair  Change Plans  Convert to Injection  Deepen  Production (S  Reclamation  Recomplete  Recomplete  Temporarily A  Water Disposa	Well Integrity Other

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
- MIRU WSU & WL rig. Set CIBP inside 2 3/8" tbg in Bkr FAB pkr @ 13577'. Pressure test tbg to 500#. If needed, dump 5' cmt on CIBP & retest. Cut off tbg as deeply as possible (top of cmt). If tbg did not hold pressure, POOH w/ tbg. If tbg held pressure, POOH w/l jt to insure thg is free. Pump down thg with wtr. Monitor BS. Load hole with plug mud.
- Spot 50' cmt plug on top of FAB packer. POOH laying down tbg to 11465'.
- Spot 50 sxs cmt at 11465' 11365'. POOH laying down tbg to 4200'.
- Locate free pt on 7 5/8" casing (est. 4000'). Cut off & LD. GIH w/2 3/8" tbg & fill hole with plug mud.
- Spot 50 sxs cmt @ 4100' 3900' (100' in and out of csg stub). POOH w/tbg.
- 7. Spot 15 sxx cmt @ 50' - 5'.
- Weld on cap w/ID marker. Move off equipment & restore location.

Approximate starting date: 11/1/06			) e - ) lib	1116 <b></b>
<ol> <li>I hereby certify that the foregoing is true and correct Name (Printed/Typed)</li> </ol>	1		12	Receive
Charlotte Van Valkenburg	Title	Technical (	Coordin	nator
Signature . Tan Tulkerburg	Date	8/2/06	13	
THIS SPACE FOR FEBERAL OR STATE OFFICE USE				
Approved by Lasey M. Layessa.  Conditions of approval, if any, see attached. Approval of this notice does not warra		Title Petr E	79r	Date 8/21/2006
certify that the applicant holds legal or equitable title to those rights in the subject le which would entitle the applicant to conduct operations thereon.		Office CF	0	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.

(Instructions on page 2)

SEE ATTACHED FUR CONDITIONS OF APPROVAL

## Conditions of Approval Federal CK Com #1

The following items are to be added to the procedure for the P&A. Note the attached drawing and NMOCD guidelines.

- 1. A plug is required at the 7 5/8" shoe. This could be combined with the plug located across the top of the liner.
- 2. This plug should also be tagged.
- 3. The plug across the liner top is required to be 50' above the top of the liner.
- 4. A plug is also required across the DVTool. This plug is also to be tagged.
- 5. A plug is required across the 10 3/4" shoe and should be tagged.
- 6. A plug is required across the 16" shoe and should be tagged.
- 7. Two additional plugs are required in the casing to meet the "not more than 3000' NMOCD guideline."

Sundry 8/2/06

A Plug or	ross shoe		16" 500' circulated
A Plug oc tog		No. of the last of	The second second
<del></del>			
			<u> </u>
Stubg	149 4/00'-3900'	NY XXXXX	TOC 4500 temps log
A P/40 OC	one shoe-tog		Toc 4500 temp, 109
V	4637 Delaware		
			2/
11			- 23/8 t/29
		7	
A D/	15 DV To 1 20 1 (09)		
1 9 9670	e/ther side or 25 m		0470 17117
	8530 Bone Spring		8479 DVT00/
	<u> </u>		
XPINO @)			
1/2/5	1465-113651 Ficient - tag		
1			
. !1	plug @ shoe		- 41/2" 11365'
299			
Y	11810 Wolfermp.		75/8"11893'
		3 1 2	
1	13082 Strong		9to/19 perfs 13630-13640
. The class of the contract of	13378 Atoto		Perfo 134/6 - 14340 Initial
	13905 Morrow 14928 Bornett	P. Committee of the com	370 13965 TO 15016