Office	State of New Me		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		May 27, 2004 WELL API NO.
District II			30-025-24879
1301 W. Grand Ave., Artesia, NM 88210 District III			5. Indicate Type of Lease FEDERAL
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8		6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM			0. State Off & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTOR			7. Lease Name or Unit Agreement Name
		LANGLIE JAL UNIT	
		2	8. Well Number 060 WIW
2. Name of Operator PHOENIX HYDROCARBONS OPERATING CORPORATION			9. OGRID Number 188483
3. Address of Operator P O BOX 3638, MIDLAND, TX 79702			10. Pool name or Wildcat LANGLIE MATTIX, 7 RVRSQ
4. Well Location			· · · · · · · · · · · · · · · · · · ·
Unit Letter I : 18	330feet from the _SOUTH		
Section 5	Township 25S 11. Elevation (Show whether DR	<u>_</u>	NMPM LEA County NM
	3220 GR		
Pit or Below-grade Tank Application 🗌 o			
Pit typeDepth to Groundwa			tance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	onstruction Material
12. Check A	Appropriate Box to Indicate N	ature of Notice, l	Report or Other Data
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
		COMMENCE DRIL	— — —
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗌
OTHER: RETEST		OTHER	
 Describe proposed or compl of starting any proposed wo or recompletion. 	leted operations. (Clearly state all rk). SEE RULE 1103. For Multip	pertinent details, and le Completions: Att	l give pertinent dates, including estimated dat ach wellbore diagram of proposed completion
of starting any proposed wo or recompletion.	rk). SEE RULE 1103. For Multip	pertinent details, and le Completions: Att	l give pertinent dates, including estimated dat ach wellbore diagram of proposed completion
of starting any proposed wo or recompletion.	rk). SEE RULE 1103. For Multip se packer and POOH with tubing.	le Completions: Att	ach wellbore diagram of proposed completion
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa	le Completions: Att	ach wellbore diagram of proposed completion -Notipy OCD Z4HRS
of starting any proposed wo or recompletion. 1. MIRU. Release 2. TIH with redr 3. Conduct MIT 4. TIH with plug	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. essed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor	le Completions: Att	-Notipy OCD ZUHRS IN ADVANCE
of starting any proposed wo or recompletion. 1. MIRU. Relea: 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te	le Completions: Att ls to test go to step 4. ations (3425'-3724'). ak.	ach wellbore diagram of proposed completion -NOTIPY OCD ZYHRS IN ADVANCE
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM starting of the starting of	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement.	le Completions: Att ls to test go to step 4. ations (3425'-3724'). ak.	ach wellbore diagram of proposed completion -NOTIPY OCD ZYHRS IN ADVANCE
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a press	rk). SEE RULE 1103. For Multip see packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze.	le Completions: Att ls to test go to step 4. ations (3425'-3724'). ak.	ach wellbore diagram of proposed completion -Notrpy OCA Z4HRS IN ADVANCE rlamide polymer. If leak is greater
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pres 8. TIH and retric 9. TIH with pacl	rk). SEE RULE 1103. For Multip see packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug. ker and tubing.	le Completions: Att ls to test go to step 4. ations (3425'-3724'). ak.	ach wellbore diagram of proposed completion -Notrpy OCA Z4HRS IN ADVANCE rlamide polymer. If leak is greater
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pres 8. TIH and retric 9. TIH with pacl	rk). SEE RULE 1103. For Multip see packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug.	le Completions: Att ls to test go to step 4. ations (3425'-3724'). ak.	lamide polymer. If leak is greater
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retrie 9. TIH with pacl 10. Conduct MIT	rk). SEE RULE 1103. For Multip see packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug. ker and tubing. and return well to injection.	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry	ach wellbore diagram of proposed completion -Notrpy OCA Z4HRS IN ADVANCE rlamide polymer. If leak is greater
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retric 9. TIH with pacl 10. Conduct MIT Note: Work will common	rk). SEE RULE 1103. For Multip see packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug. ker and tubing.	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry	ach wellbore diagram of proposed completion -Notrpy OCA Z4HRS IN ADVANCE Plamide polymer. If leak is greater
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retric 9. TIH with pacl 10. Conduct MIT Note: Work will common	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug. ker and tubing. and return well to injection.	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry	ach wellbore diagram of proposed completion -Notrpy OCA ZUHRS IN ADVANCE rlamide polymer. If leak is greater
of starting any proposed wo or recompletion. 1. MIRU. Release 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retrice 9. TIH with pacl 10. Conduct MIT Note: Work will common weeks after NMOCD ap	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. reve plug. ker and tubing. and return well to injection. ence as soon as possible after NMOCD oproval as this has been usual waiting p	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry approval. We would e period for a rig.	ach wellbore diagram of proposed completion -NOTIPY OCA ZURS IN ADVANCE Plamide polymer. If leak is greater estimate the timing to be to 6 SEC to 7 SEC
of starting any proposed wo or recompletion. 1. MIRU. Release 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retrice 9. TIH with pacl 10. Conduct MIT Note: Work will common weeks after NMOCD ap	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. reve plug. ker and tubing. and return well to injection. ence as soon as possible after NMOCD oproval as this has been usual waiting p	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry approval. We would e period for a rig.	ach wellbore diagram of proposed completion -Norrpy OCA Z4HRS /N ADVANCE Plamide polymer. If leak is greater estimate the timing to be 3 to 6 SEC and belief. I further certify that any pittor below
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retrice 9. TIH with pacl 10. Conduct MIT Note: Work will comme weeks after NMOCD ap I hereby certify that the information a grade tank has been/will be constructed or	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. reve plug. ker and tubing. and return well to injection. ence as soon as possible after NMOCD oproval as this has been usual waiting p	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry approval. We would e period for a rig.	ach wellbore diagram of proposed completion -NOTIFY OCA ZURS In ADVANCE Plamide polymer. If leak is greater estimate the timing to be 3 to 6 SEC and belief. I further certify that any pittor below-
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retrice 9. TIH with pacl 10. Conduct MIT Note: Work will comme weeks after NMOCD ap I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Billy Sneed	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug. ker and tubing. and return well to injection. ence as soon as possible after NMOCD poproval as this has been usual waiting p above is true and complete to the b closed according to NMOCD guidelines	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry approval. We would e period for a rig. est of my knowledge [], a general permit []	Ach wellbore diagram of proposed completion -Norrpy OCA ZURS Itamide polymer. If leak is greater estimate the timing to be to 6 SSS and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 8/24/06
of starting any proposed wo or recompletion. 1. MIRU. Releas 2. TIH with redr 3. Conduct MIT 4. TIH with plug 5. POOH with p 6. If leak is less than ½ BPM s 7. Drill out a pre 8. TIH and retrice 9. TIH with pace 10. Conduct MIT Note: Work will comme weeks after NMOCD ap I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE	rk). SEE RULE 1103. For Multip se packer and POOH with tubing. ressed packer, test tubing going in hole and return well to injection. If well fa g and packer and set plug above perfor acker testing casing to locate casing le than ½ BPM squeeze leak with Gel Te squeeze leak with cement. ressure test squeeze. eve plug. ker and tubing. and return well to injection. ence as soon as possible after NMOCD poproval as this has been usual waiting p above is true and complete to the b cosed according to NMOCD guidelines TITLE	le Completions: Att ils to test go to step 4. ations (3425'-3724'). ak. ch Mara-Seal polyacry approval. We would e period for a rig. est of my knowledge [], a general permit [] Engineer bsneed@t3mid.com	Ach wellbore diagram of proposed completion -Norrpy OCA ZHERS /N ADVANCE lamide polymer. If leak is greater estimate the timing to be to to to be to

i

ÂÜG	2	8	2006	
-----	---	---	------	--