

DATE OCT 10 2006

MACK ENERGY

TIPTON #15

Sec 30 T16S R32E 2310FEL 330FSL

- 1 Notify BLM 24 Hrs in advance of plugging
- 2 Set 4 1/2" Pkr 1730 squeeze 150sks down csg
- 3 Perf squeeze 100sks @ 1080 Top salt
- 4 Perfs @ 328 Squeeze 100sks 50'above below shoe
- 5 Set 60' 10sks plug at top
- 6 Install Dry hole Marker

BEFORE




8 5/8" 24# J-55 @ 328' c/w 250sks

Parted 1830'

Perfs 3824-4037'

4 1/2" 9.5# @ 4091' c/w 200sks

AFTER



60' Cmt Plug

8 5/8" 24# J-55 @ 328' c/w 250sks

Perfs @ 328 Squeeze 100sks 50'above below shoe

Perf @ 1080 TS squeeze 100sks

Set 4 1/2" Pkr 1730 squeeze 150sks down csg

Parted 1830'

Perfs 3824-4037'

4 1/2" 9.5# @ 4091' c/w 200sks

9/25/2006 MIRU, unseat pump POH, rig up on tubing, stuck pump water down csg filled up not circulating rig up on tubing pressure up to 600# holding leave bind on till AM.

9/26/2006 Tbg still stuck rig up Rotary wire line stuck on SN cut off at 3910' rig wireline down, POH 2 3/8" tubing no holes layed down. Rig up fishing tools, hyd jars, bumper sub Rih on 2 7/8" tubing jarred on rest of day did not make over 26" SDFD.

9/27/2006 POH fishing tools RIH with 3 1/2" wash overpipe wash over to btm, POH, Rig up fishing tools Rih latch on to fish, pulled out 1/2 jts, full jt, SN 4' Perf sub, 1jt mudanchor open ended, Rih with 2 7/8" tubing hit tight spot at 1830' would not go past, cancel acid job, Picup 3 1/2" Tapered Mill RIH tag 1830' start reaming. SDFN.

9/28/2006 Rig up start reaming from 1830' to 1934' just bring up some formation now no more iron, POH, RIH open ended with 2 7/8" tubing hit at 1830' (MUST HAVE PARTED OR COLLASPE CSG) tried to work thru got thur w/1 jt almost got stuck POH, RIH with 2 3/8" tbg smaller tag 1830' turn tubing some go thru 1jts start up swivel and circ down tubing up csg taking water switch down csg and up tubing brining up lots of cuttings work thru to 2080' acts like fell thru run 4more jots but had to turn each time to go thru hitting on tbg callars got to 2144' and take all weight and would not go thur washing or turning, POH laydown tubing and rods. GET READY TO PLUG AND ABANDON.