

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32805
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1113-1
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	200
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTION

2. Name of Operator
CHEVRON USA INC

3. Address of Operator
15 SMITH RD, MIDLAND, TX 79705

4. Well Location
Unit Letter C : 1236 Feet From The NORTH Line and 1875 Feet From The WEST Line
Section 6 Township 18-S Range 35-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: REPAIR & RETURN TO INJECTION ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON U.S.A. INC. INTENDS TO PULL THE SUBJECT WELL, REPAIR AS NEEDED, AND RETURN TO INJECTION. THE WELL FAILED A MIT. IT IS ALSO RECOMMENDED THAT ADDITIONAL PERFORATIONS BE ADDED IN THE LOWER SAN ANDRES TO SUPPORT OFFSET PRODUCER, AND ACID STIMULATE THE PERFORATIONS.

THE INTENDED PROCEDURE AND WELLBORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

DATE 10/10/2006

TYPE OR PRINT NAME Denise Pinkerton

Telephone No. 432-687-7375

(This space for State Use)

APPROVED Gary W. Wink
CONDITIONS OF APPROVAL, IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGER
TITLE

DATE

OCT 12 2006

9/7/2006

CVU #200 injector


Failed MIT on CO2 injector_ Could be pkr problem, HIT, or csg leak.

Procedure

1. Notify **Larry Ridenour** to set up injection profile to be run ~ 2 weeks after completion of this workover.
2. Verify what equipment is in the hole with the well file in Buckeye NM office. Discuss w/ OS, ALR and pumpers prior to RU regarding any unknown issues about this well. (Records indicated 2 3/8" injection tbg (maybe Duoline) w/ pkr @ 4169')
3. MIRU PU and RU. Set frac tanks.
4. Pump 2 3/8" tbg capacity w/ 10# brine to determine kill weight needed. Kill well as necessary.
5. Release injection packer.
6. TOH w/ 2 3/8" injection tbg and packer. Note if see HIT or packer problem. {if have to replace inj tbg, will utilized same size inj tbg} (note any scale, etc and report to Denise Wann ASAP)
7. TIH/ 4 3/4" bit and scrapper on 2 7/8" workstring.
8. Clean out to 4786' (PBTD).
9. TIH w/ 5 1/2" RBP and packer on 2 7/8" workstring. Test csg to 500#. Isolate casing leak and establish rate and pressure into leak. TOH.
 - Set 5 1/2" RBP ~4150' or as needed on 2 7/8" workstring and top RBP w/10' sand. TOH.
 - TIH w/ 5 1/2" cement retainer on 2 7/8" workstring and set as need.
 - RU DS and cement squeeze as needed per DS recommendation.
 - TIH/ 4 3/4" bit, DC's on 2 7/8" workstring.
 - Drill out cement and test squeeze. Resqueeze if needed.
 - Drill and clean out to 4786'.
10. RU Wireline Services. TIH w/ 3 1/8" perforating gun and perforate 2 spf, 120 degree phasing with Premium charges as per Engr and Geologist recommendation.
 - 4663'-4709' 46' 94 holes
 - 4738'-4776' 38' 78 holes
11. MIRU Stimulation Services and Sonic Hammer Services.
12. TIH w/ Sonic Hammer on 2 7/8" workstring. Water wash perforations going in the hole using 8.6 # cut brine ~500 bbls from 4253'-4776'. (If calcium sulfate scale is seen, will utilize SH to pump sulfate convertor.) Acidize wash perforations 4776'-4253' coming out of hole w/ 5000 gals 15% HCL (Utilize ~2000 gals across bottom, newly opened interval 4663-4776' and 3000 gals across interval 4253'-4602') (Max pressure 500# on the casing during treatment) {NOTE: if unable to pump into perforations and casing pressure exceeds 500#, will pull SH Tool and RU to pump acid + rock salt under packer.}
13. Drop bar and swab back load as possible. TOH.
14. TIH w/ 5 1/2" injection packer and 2 3/8" injection tbg ~4160' as per Bobby Hill. recommendation.
15. Return well to injection.

Denise Wann

CVU #200
API No. 30-025-32805



JDW 8/31/2006