

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30.015.21962</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: <b>Empire Abo Unit "F"</b>
8. Well Number <b>332</b>
9. OGRID Number <b>000778</b>
10. Pool name or Wildcat <b>Empire Abo</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		7. Lease Name or Unit Agreement Name: <b>Empire Abo Unit "F"</b>
2. Name of Operator <b>BP America Production Company</b>		8. Well Number <b>332</b>
3. Address of Operator <b>P.O. Box 1089 Eunice NM 88231</b>		9. OGRID Number <b>000778</b>
4. Well Location Unit Letter <b>E</b> : <b>2582</b> feet from the <b>N</b> line and <b>150</b> feet from the <b>W</b> line Section <b>34</b> Township <b>17S</b> Range <b>28E</b> NMPM County <b>Eddy</b>		10. Pool name or Wildcat <b>Empire Abo</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

BP America Production Company plans to perform a workover of this well to attempt to return the well to production. BP requests permission for an extension of TA status for this well, which expires on 10.14.06.

Please refer to attached Workover Procedure.


Denied - Reference NMOCD  
Rule 19.15.4.203.C

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Vicki Owens TITLE Administrative Assistant DATE 10.04.06  
E-mail address: owensv12@bp.com  
Type or print name Vicki Owens Telephone No. 505.394.1650

**For State Use Only**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of Approval, if any:



bp

EAU F-332

Page 1

## WORKOVER PROCEDURE

### EAU F-332: Add perfs, spot acid, recomplete.

**DATE:** 4/18/06      **PAY KEY #:**

**WELL:** EAU F-332      **DRILLED:** 7/5/78 (Spud)      **FIELD:** EAU      **COUNTY:** Eddy, NM

**BY:** Kyle Golson      **TD:** 6369      **PBTD:** 6192      **DATUM:** KB: 10.5

<b>CASING:</b>	<u>SIZE</u>	<u>WEIGHT</u>	<u>GRADE</u>	<u>SET @</u>	<u>SX CMT</u>	<u>TOC</u>
<b>SURFACE:</b>	8 5/8"	24#	K-55	643'	225	NA
<b>PRODUCTION:</b>	5.5"	15.5#	K-55	6368'	1235	

**TUBING:** 2 3/8, 4.7#, 8rd, J-55 1jt 31.58'

**MUD ANCHOR:**

**PUMP:**

**PACKER:**

**PERFORATIONS:**

**HISTORY AND BACKGROUND:**

**SCOPE OF WORK:** Add perfs, spot acid, rih new rod design.

## PROCEDURE

### Pull Pump, Rods, & Tbg' Tag/Cleanout WB with W/O Rig:


1. COMPLETE SAFETY MEETING AND JSAS PRIOR TO RU PU.
2. SPOT TRUCK AND BLOWDOWN PIT & SHUT IN UNIT. HOOK UP TO BLOWDOWN PIT & BLEED WELL DOWN.

Hazard	Effect	Mitigation
Gas, H2S, or fluid release	Possible injury or death to personnel, damage to equipment & environment	<ul style="list-style-type: none"> <li>&gt; Pre job inspection of hose and piping equipment</li> <li>&gt; Check all connections &amp; make sure all are tight</li> </ul>

Hazard	Effect	Mitigation
High pressure pumping equipment	Possible injury or death to personnel, damage to equipment	<ul style="list-style-type: none"> <li>&gt; Line of fire practices</li> <li>&gt; Pressure test lines</li> </ul>

3. MIRU PU

Hazard	Effect	Mitigation
H2S	Possible injury or death to	<ul style="list-style-type: none"> <li>&gt; Monitor H2S levels continuously</li> <li>&gt; Pre job inspection of H2S equipment and Breathing equipment</li> </ul>



	personnel, or other people damage to equipment or wellbore or environment	<ul style="list-style-type: none"> <li>➤ Available phone contacts in case gas escapes into environment</li> <li>➤ All employees H2S trained.</li> </ul>
High pressure pumping equipment	Possible injury or death to personnel, damage to equipment	<ul style="list-style-type: none"> <li>➤ Line of fire practices</li> <li>➤ Pressure test lines</li> </ul>
Pulling Unit Failure Objects falling from derrick	Possible injury or death to personnel, damage to equipment or wellbore	<ul style="list-style-type: none"> <li>➤ Inspection of derrick</li> <li>➤ Pre job inspection of rig after RU.</li> </ul>

4. INSTALL BOP
5. POOH W/ 1 JT. 2 3/8" 8RD EUE J-55 TBG.

### Perforate 3 intervals 5822-40, 5852-68, 5890-5934' w/ 2 jspf.

1. PU 2 3/8" TBG, CSG SCRAPER & BIT.
2. RIH W/ SCRAPER & BIT, TAG CIBP @ 6192. POOH.

Hazard	Effect	Mitigation
High pressure pumping equipment	Possible injury or death to personnel, damage to equipment	<ul style="list-style-type: none"> <li>➤ Line of fire practices</li> <li>➤ Pressure test lines</li> </ul>
Dropped pipe in hole	Possible damage to well	➤ Pipe handling practices – slips, clamps, tongs, complete MU/BO before lifting as appropriate
Drop pipe in derrick	Possible injury or death to personnel, damage to equipment	<ul style="list-style-type: none"> <li>➤ Line of fire practices</li> <li>➤ Inspection of lifting equipment</li> </ul>
Loss of well control	Possible injury to personnel, damage to wellbore, damage to environment	<ul style="list-style-type: none"> <li>➤ Install pressure control – BOP's (change pipe rams)</li> <li>➤ Have TIW valve on floor – capable of stabbing in 4 1/2" LTC &amp; full opening</li> <li>➤ Frequent BOP drills</li> </ul>
Falling from height	Possible injury or death to personnel	<ul style="list-style-type: none"> <li>➤ Use work platform</li> <li>➤ 100% tie-off</li> </ul>

3. RU E-LINE & LUBRICATOR. USING EXISTING SCHLUMBERGER PERFORATING DEPTH CONTROL LOG, 1/14/77, PERFORATE 5822-40', 5852-68', & 5890-5934' @ 2 JSPF (3 1/8" SLICK GUNS, .42" ENTRY HOLE & 36.7" PENETRATION ON 4 WL RUNS) USING GREY WL.
4. RD E-LINE & LUBRICATOR. PU RBP, BALL CATCHER, & TREATING PKR (FROM HUDSON PKR) & RIH W/ 2 3/8" TBG & TOOLS.
5. ISOLATE LOWER ZONE (5890-5934) WITH RBP & TREATING PACKER.
6. ACIDIZE ZONE WITH 1500 GAL 15% HCL (SEE ATTACHED HALLIBURTON ACID JOB.)
  - a. FLUSH WITH 150 GAL HCL.
  - b. PUMP 1200 GAL HCL DROPPING 125 BALLS, SPACED EVENLY.
  - c. FLUSH WITH 150 GAL HCL.

- d. FLUSH WITH FULL LOAD OF WATER (TUBING LOAD + CASING BETWEEN PKR & RBP) APPROX 25 BARRELS OF 2% KCL WATER.
7. RELEASE RBP & TREATING PKR, ISOLATE TOP 2 ZONES FROM 5822-5868'.
8. ACIDIZE ZONE WITH 1300 GAL 15% HCL (SEE ATTACHED HALLIBURTON ACID JOB)
- a. FLUSH WITH 150 GAL HCL.
- b. PUMP 1000 GAL HCL DROPPING 100 BALLS, SPACED EVENLY.
- c. FLUSH WITH 150 GAL HCL.
- d. FLUSH WITH FULL LOAD OF 2% KCL WATER, APPROX 24 BBL.
8. RELEASE RBP & PKR, POOH W/ TOOLS & TBG.

### RIH w/ Production Equipment

1. RIH W/ 2 3/8" TBG, SET SN @ 6000' W/ 2 7/8" X 4' PS W/ BP.
2. PU RODS (SEE ATTACHED RODSTAR SUMMARY) & PUMP.
3. LOAD & TEST.

Hazard	Effect	Mitigation
Gas, H2S, or fluid release	Possible injury or death to personnel, damage to equipment & environment	<ul style="list-style-type: none"> <li>➤ Pre job inspection of hose and piping equipment</li> <li>➤ Check all connections &amp; make sure all are tight</li> </ul>
Loss of well control	Possible injury to personnel, damage to wellbore, damage to environment	<ul style="list-style-type: none"> <li>➤ Install pressure control – BOP's (change pipe rams)</li> <li>➤ Have TIW valve on floor – capable of stabbing in 4 1/2" LTC &amp; full opening</li> <li>➤ Frequent BOP drills</li> </ul>
Falling from height	Possible injury or death to personnel	<ul style="list-style-type: none"> <li>➤ Use work platform</li> <li>➤ 100% tie-off</li> </ul>
Pulling Unit Equipment Failure Objects falling from derrick	Possible injury or death to personnel, damage to equipment or wellbore	<ul style="list-style-type: none"> <li>➤ Inspection of derrick</li> <li>➤ Pre job inspection of rig after RU.</li> </ul>
Hazard	Effect	Mitigation
H2S	Possible injury or death to personnel, or other people damage to equipment or wellbore or environment	<ul style="list-style-type: none"> <li>➤ Monitor H2S levels continuously</li> <li>➤ Pre job inspection of H2S equipment and Breathing equipment</li> <li>➤ Available phone contacts in case gas escapes into environment</li> <li>➤ All employees H2S trained.</li> </ul>
Pinch Point	Possible injury to personnel	<ul style="list-style-type: none"> <li>➤ Have proper ppe. Avoid line of fire. Use proper tools.</li> </ul>
Moving Equipment	Possible injury or death to personnel	<ul style="list-style-type: none"> <li>➤ Keep hands &amp; other body parts away from moving parts</li> <li>➤ Ensure wearing no loose clothing</li> </ul>
High pressure pumping equipment w/corrosive fluid (15% Acid)	Possible injury or death to personnel, damage to equipment or wellbore or environment	<ul style="list-style-type: none"> <li>➤ Line of fire practices</li> <li>➤ Pressure test lines repair all leaks before pumping acid</li> <li>➤ HAZ Mat Training</li> <li>➤ Available phone contacts in case of environmental spill</li> </ul>
H2S during Acid Flowback procedures:	Possible injury or death to personnel, or other people damage to equipment or wellbore or environment	<ul style="list-style-type: none"> <li>➤ Monitor H2S levels continuously &amp; Wind direction</li> <li>➤ Pre job inspection of H2S equipment and Breathing equipment</li> <li>➤ All employees H2S trained.</li> <li>➤ Safety precautions around return outlets during sampling of swabbed liquids or monitoring returns.</li> <li>➤ Precautions around swab tanks where H2S can come out of solution and concentrate above the surface of the water.</li> </ul> <p>Dangerously high levels of H2S have been recorded after acid stimulations for iron</p>

Prepared by: Kyle Golson

REVIEWED BY:

APPROVED BY: \_\_\_\_\_

