Do not u abandon	UNITED STATES DEPARTMENT OF THE BUREAU OF LAND MAN DRY NOTICES AND REF use this form for proposals t ed well. Use Form 3160-3 (A	INTERIOR AGEMENT PORTS ON WELLS o drill or to re-enter an APD) for such proposals.	BBS FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. LC-046295 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If O'nit of CA/Agreement, Name and/of No.
			8. Well Name and No.
2. Name of Operator XTO Energy Inc.			Arrowhead Grayburg Unit #148 9. API Well No.
3a. Address 200 N. Loraine, Ste 800, Midland, Tx 79701		3b. Phone No. (include area code) 432-620-6724	30-025-31393 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Arrowhead Graybors 262>
Sec 1, T22S, R36E, 785	" FNL & 1905' FWL		30-025-31393 10. Field and Pool, or Exploratory Area Arrowhead Grayby 26.2> 11. County or Parish, State Lear, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER SALA			
TYPE OF SUBMISSION TYPE OF ACTION			
Notice of Intent Acidize Notice of Intent Alter Casing Subsequent Report Casing Repair Final Abandonment Notice Convert to Injection		Fracture Treat Reclama	on (Start/Resume) 2 Water Shut-Off tion Well Integrity 5 Hete Construction Constr
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 10/11/06 MIRU Nabors PU (Johnny). ND WH. NU BOP. Rel pkr. POOH LD cmt lined tbg & pkr. MI & rack 3,800' 2-7/8" N80 WS. PU & RIH w/4-3/4" bit, scraper, bit sub, x-over & 118 jts 2-7/8" N80 WS. Tag fill @ 3,768'. PU & leave tools swinging above perfs. SWI & SDON.			
<pre>10/12/06 POOH w/tbg & tools. PU & RIH w/4-3/4" bit, bit sub, x-over, 6 - 3-1/2" DC's & 111 jts 2-7/8" N80 WS. Tag fill @ 3,768'. RU swivel. Est circ w/30 bbls 9# brine wtr. CO iron & scale to 3,850'. Circ hole clean. RD swivel. POOH w/tbg & LD DC's. PU & RIH w/4-3/4" bit, scraper, bit sub, x-over & 122 jts 2-7/8" N80 WS. PU & leave tools swinging above perfs. SWI & SDON.</pre>			
14. I hereby certify tha Name (Printed/T)	t the foregoing is true and correct		
DeeAnn	· · .]	Title Regulatory	
Signature De	J-KI	Date	ACCEPTED FOR RECORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
certify that the applicant l which would entitle the a Title 18 U.S.C. Section 100	adv, are attached. Approval of this notic bolds legal or equitable title to those right pplicant to conduct operations thereon. It and Title 43 U.S.C. Section 1212, make i or fraudulent statements or representation	s in the subject lease Office	0 7 2006 WESLEY W. INGRAM Willfully to make to any appartment of agency of the United

.

(Instructions on page 2)

GWW

Arrawhend Grayburg Unit = 148

- 10/13/06 POOH w/tbg & tools. PU & RIH w/Sonic Hammer tool. Sonic Hammered Grayburg perfs w/340 bbls 9# brine wtr from 3,695' to 3,825'. AIR - 5 BPM. AIP - 1,500 psig. Circ hole clean. POOH LD 2-7/8" WS & tools. RU Gray WL trk. PU & RIH w/5-1/2" CIBP. Set CIBP @ 3,830'. POOH w/WL & tools. PU & RIH w/WL set BJ 5-1/2" Inj pkr. Set pkr @ 3,712'. POOH w/WL & tools. SWI & SDON.
- 10/14/06 PU & RIH w/1.78 "F" SS profile nipple, T-2 on/off tool, 3 jts 2-3/8", 4.7#, J-55, EUE, 8rd IPC/externally coated tbg, 5-1/2" BJ PC-1 tandem tension pkr, 114 jts 2-3/8", 4.7#, J-55, EUE, 8rd IPC tbg, 4', 6' & 10' 2-3/8" IPC tbg subs. Latched onto BJ 1x pkr @ 3,712' & SWO. Unlatch off of on/off tool. RU Lobo pmp & vac trks. Circ TCA w/70 bbls pkr fluid. Latch onto on/off tool. Set tension pkr @ 3,616'. ND BOP. NU WH. Press TCA to 380 psig for 35". Held ok. Called Maxie w/NMOCD to witness MIT. NMOCD could not be on location. Press tbg to 1,600 psig & pmp out plug. RD Lobo trks. SWI & SDON. Will RWTI in am.
- 10/17/06 RDMO Nabors PU. RU Lobo acid trk. A. Grayburg perfs fr/3,714'-3,824' w/2,000 gals 20% NEFE HCL acid in 4 stgs of 500 gal acid w/5 bbls 9# brine diversion between each acid stg. Flush to btm of pkr w/21 bbls 9# brine wtr. AIR - 2.4 BPM. AIP - 810 psig. ISIP - 485 psig. 5" SIP - 125 psig. 7" - vac. Max/Min press - 880 psig/vac. RD Lobo Acid trk. RWTI.

Chart attached

