

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-025-34565

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

KEACH

8. Well Number # 1

9. OGRID Number

232825

10. Pool name or Wildcat

NADINE; SA, PADDOCK-BLY.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator ROBERTS SWD, LLC.

3. Address of Operator PO BOX 358, HOBBS, NM 88240

4. Well Location

Unit Letter O : 467 feet from the SOUTH line and 2310 feet from the EAST line

Section 4 Township 20S Range 38E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3576 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type STEEL Depth to Groundwater 40 Distance from nearest fresh water well 5086 Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: P+A ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHMENT



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE TITLE OWNER DATE

LEE M. ROBERTS

Type or print name

For State Use Only

APPROVED BY: Gary W. Wink TITLE

Conditions of Approval (if any)

E-mail address:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

Telephone No. 505-631-5765

DATE JAN 29 2007

J&L Land Farm (November 4, 2006)
Keach #1

Rig up pulling unit. Lay down 49- 7/8 rods and 119-3/4 rods. Put on bop. Pull out of hole with 131 joints 2 3/8 tubing, 5 1/2 tubing anchor, seat nipple and mud joint. Run in the hole with 5 1/2 cast iron bridge plug and tubing. Set cast iron plug at 4175 ft. (130 joints). Circulate oil and gas from well bore (90 bbls. fresh water). Test cast iron plug to 500psi. Pull cast iron plug setting tool. Run in hole with tubing to top of plug. Took bop off of well. Flange well back up. Rig pulling unit down. Send pulling unit to yard.

December 29, 2006

Rig up pulling unit install bop.

January 2, 2007 & January 3, 2007

Wait on BJ Services. Rig up BJ break circulation with fresh water. Pump 25 sac cement plug on top of cast iron plug set at 4175. Lay down 9 joints 2 3/8 tubing to 3918. Circulate 80 bbls. of 10 lb brine gel to surface.. Lay down pipe and stand rest of tubing in derrick.

Rig up wireline perforate 2 shots at 1660 ft. Rig down wireline. Run tubing to 1690. Pump 35 sac cement plug. Pull tubing out of well. Pressure up on well bore to 1000 psi. Shut down for the day.

Run tubing in well tag cement plug at 1395 feet. Lay down rest of tubing. Rig up wireline and perforate 6 holes at 350 feet. Take off bop. Rig up BJ, break circulation on surface. Circulate cement to surface. Rig down BJ. Pull wellhead flange. Unbolt surface head and pull surface flange off. Cut off surface head. Put on dry hole marker. Rig down unit.