Submit 3 Copies To Appropriate District Office	State of New N	Form C-103			
District I	Energy, Minerals and Na	WELL API NO.	Revised June 10	0, 2003	
1625 N. French Dr., Hobbs, NM 88240 District II					
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATIO	30-025-34829 5. Indicate Type	of Lease		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			FEE	
District IV	Santa Fe, NM 87505		6. State Oil & G		-
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name of	or Unit Agreement Na	ame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Townsend State		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number		
1. Type of Well:			8. Well Number		
Oil Well Gas Well Other					
2. Name of Operator			9. OGRID Number		
Devon Energy Production Company, LP			6137		
3. Address of Operator 20 North Broadway Oklahoma City, Oklahoma 73102-8260			10. Pool name or Wildcat Big Dog; Strawn ,South (96690)		
4. Well Location	_ Dig Dog, Strawn	,30um (30030)			
4. Well Education					
Unit LetterJ:_3927'_	feet from the _North	line and _1940'	_feet from theEa	astline	
			_	_	
Section 2		Range 35E	Lea	County	
	 Elevation (Show whether L GR; 4133' KB 	JK, KKB, K1, GK, etc.	.)		
		Nature of Notice	Report or Other	r Data	•
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO:			SEQUENT RE		
PERFORM REMEDIAL WORK		REMEDIAL WOR		ALTERING CASIN	σП
_	CHANGE PLANS		ILLING OPNS.	PLUG AND	
_	-		_	ABANDONMENT	_
	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB	ND 📙		
,	JOINIFLETION	CEMENT JOB			
OTHER:		OTHER:			
13. Describe proposed or complete of starting any proposed work or recompletion.					
•					
<u>12/12/06-12/23/06:</u> MIRU. POOH w/p					
with 10 ppg mud. Cut 5-1/2" production casing at 9360'. Unable to pull casing free. Spot 30 Sx cement across cut from 9092' to 9410'.					
Tagged cement plug at 9102'. Cut 5-1/2" production casing at 8200'. POOH and lay down 5-1/2" production casing. Set 30 Sx cement					
stub plug from 8110' to 8250'. Tagged TOC at 8110'. Set 30 Sx cement plug from 7183' to 7300'. Set 30 Sx cement plug at 4656'. Tagged TOC at 4650'. Only 6' fill. Spot 30 Sx cement plug at 4650'. Tagged TOC at 4490'. This covers 8-5/8" casing shoe @ 4606'.					
Set 30 Sx cement plug from 2715' to 28					
shoe at 440'. Set 20 Sx cement plug from		33		er Suran See	Ü
44440= 0 . 111 . 1 . 00 . 1 1 . 1			66	1200 1011 E	
<u>1/11/07:</u> Cut wellhead off and set dry h	nole marker. Well plugged and	d abandoned.	(3 ⁰	TO THE	
			/~		.\
			1/	386) A
	Approved as to plugging o	of the Well Bore.	18	82.2 "	
	Liability under bond is ret	ained until		00	
I hereby certify that the information about	ovenitatere sust contrible tist com	pleted f my knowledg	ge and belief. 🖔		
SIGNATURE Komme D.	Slack TITLE: En	gineering Technician	DAT	TE1/11/07	
Type or print name Ronnie G. Slack	E-mail address: Ronn	nie.Slack@dvn.com	Telenhon	ne No. 405-552-4615	
(This space for State use)			2 310 p 110 11		
\mathcal{A}	10 1			FEB 0 2 2	יחחי
APPPROVED BY Acuto La Conditions of approval, if any	Dinde ochieby	REPRESENTATIVE II	STAFF MANAGE	DATE	
~					

