

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I  
1625 N. French Dr., Hobbs, NM 88240

1220 South St. Francis Dr.  
Santa Fe, NM 87505

DISTRICT II  
1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.

30-025-07527

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

North Hobbs (G/SA) Unit  
Section 32

8. Well No. 131

9. OGRID No. 157984

10. Pool name or Wildcat Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G101) for such proposals.)

1. Type of Well:

Oil Well ☒

Gas Well ☐

Other ☐

2. Name of Operator

Occidental Permian Ltd.

3. Address of Operator

HCR 1 Box 90 Denver City, TX 79323

4. Well Location

Unit Letter L : 2310 Feet From The South 330 Feet From The West Line

Section 32

Township 18-S

Range 38-E

NMPM

Lea County

11. Elevation (Show whether DF, RKB, RT GR, etc.)

3634' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type \_\_\_\_\_ Depth of Ground Water \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water

Pit Liner Thickness \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

Multiple Completion ☐

OTHER: Squeeze/OAP/Acidize & CTI ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: \_\_\_\_\_ ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Kill well. Pull ESP equipment. Test liner to 1000 PSI.

2. Set RBP @±1400' & rig down for wellhead change out.

3. RU & pull RBP. Run bit & scraper to PBTD @4248'.

4. PB with sand to 4145'. Set CICR @4000'.

5. Squeeze perfs.

6. Drill out squeeze & test to 1000 PSI. CO to PBTD.


7. Perforate well.

8. Acid treat with 15% HCL PAD acid.

9. Run in hole with injection equipment.

10. Test casing & chart for NMOCD.

Injection in well will commence per Division Order R-6199-B.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE

Mendy A. Johnson

TITLE

Administrative Associate

DATE

01/30/2007

TYPE OR PRINT NAME

Mendy A. Johnson

E-mail address:

mendy\_johnson@oxy.com

TELEPHONE NO.

806-592-6280

For State Use Only

APPROVED BY

Tony W. Wink

OG FIELD REPRESENTATIVE II/STAFF MANAGER

CONDITIONS OF APPROVAL IF ANY:

FEB 1 2007