Form 3160-5 (September 2001)

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

## UNITED STATES

N.M. Oil Cons. Division 1625 N. Franch Dr.

Hobbs, NM 88240

FORM APPROVED OMB No. 1004-0135

> GOURLEY ROLEUM ENGIN

DEPARTMENT OF THE INTERIOR Expires January 31, 2004 BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM 16139 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well Oil Well XX Gas Well Other 8. Well Name and No. Name of Operator Vaca Ridge 4 Fed Com Well #2 Robert E. Landreth 9. API Well No. <sup>3a</sup> Address 505 N. Big Spring, Ste. 507 Midland, Texas 79701 3b. Phone No. (include area code) 30-025-29558 432-684-4781 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Pitchfork Ranch (Atoka) 1980' FEL and 660' FNL of Section 4, T25S, R34E 11. County or Parish, State Lea Co., NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize ☐ Deepen Production (Start/Resume) Water Shut-Off ☐ Notice of Intent ☐ Alter Casing ☐ Reclamation ☐ Fracture Treat Well Integrity Casing Repair ☐ New Construction ☐ Recomplete Subsequent Report Other Change Plans Plug and Abandon ☐ Temporarily Abandon ☐ Final Abandonment Notice Convert to Injection Plug Back ☐ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 7/09/03 RIH w/ 2 3/8" & 2 7/8" tbg to 13,842'. Spot 20 sxs @ 13,842'-13,577'. POOH & WOC 5 hrs. Tagged fill at 12,232'. 7/15/03 7/17/03 Spot 35 sxs @ 12,232'. WOC 5 hrs & TAG @ 11,588'. POOH w/tbg & SDFN. RIH w/ 5 9/16" Gauge Ring to 10,799'. POOH w/ Wireline. RIH w/tbg. Spot 35 Exs @ 2500 POOH 7/18/03 RIH & TAG @ 9,362'. POOH & Spot 40 sxs @ 7,221'. WOC 4 hrs & TAG @ 6,900'. POOH & Spot 45, sxs @ 7/21/03 5,166'. POOH. RIH & TAG @ 4,918'. NDBOD. Weld on 7" pull nipple. Cut csg @ 4,200' but could not pull. RIH w/tbg. 7/22/03 RIH & Spot 40 sxs @ 4,253'. WOC 3 hrs. RIH & TAG @ 4,016'. Cut csg @ 3,400'. LD 22 jts 7" csg. 7/23/03 7/24/03 LD remaining 7" csg. RIH & Spot 45 sxs @ 3,457'. POOH 7/25/03 RIH & TAG @ 3,305'. POOH & Spot 45 sxs @ 1,502'. POOH & Spot 45 sxs @ 674'. POOH & WOC 4 hrs. RIH & TAG @ 540'. POOH & Spot 20 sxs @ 60' to surface. Rig down. Cut off wellhead & anchors. Install dry hole marker. Level pit & cellar. Hole loaded w/mud laden fluid as per BLM specifications. Plugging operations witnessed by Marlan Deaton w/BLM. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Approved as to plugging of the well bace.

Lability under bond is retained until little.

Respect restriction is competed. Tammy Kennedy Signature August 28, 2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title