	-				
Submit 3 copies to Appropriate District Office	State of Nev Energy, Minerals and Natural		Form C-10 Revised 1-		
	OIL CONSERVAT	TON DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2		30-025-32159		
DISTRICT II P.O. Box Drawer DD, Artesia, NM 88210	Santa Fe, New Mex	ico 87504-2088	5. Indicate Type of Lease		
DISTRICT III			STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.		
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROP DIFFERENT RESER) (FORM C-	7. Lease Name or Unit Agreement Name B.F. HARRISON 'B'				
1. Type of Well: OIL GAS WELL ₩ WELL	OTHER				
2. Name of Operator			8. Well No.		
CHEVRON US	AINC		18		
3. Address of Operator 15 SMITH RD, MIDLAND, TX 79705			9. Pool Name or Wildcat TEAGUE GLORIETA-UPPER PADDOCK, SOUTHV	WEST	
4. Well Location Unit LetterD:	990 Feet From The NC	DRTHLine and _660	Feet From TheWESTLine		
Section 9	Township23-SO	_Range <u>37-EA</u> N	IPM LEA COUNTY		
	10. Elevation (Show whether DF, R	KB, RT,GR, etc.) GR-3319',	, KB-3331'		
11. Check App	propriate Box to Indicate N	lature of Notice, Report	, or Other Data		
NOTICE OF INTENTION	N TO:	SL	JBSEQUENT REPORT OF:		
	PLUG AND ABANDON	REMEDIAL WORK			
	CHANGE PLANS		ERATION		
PULL OR ALTER CASING	· · · · ·	CASING TEST AND CEMEN	NT JOB		
OTHER: CMT SQZ HORIZONTAL I	LATERAL & COMPLETE	OTHER:			
 Describe Proposed or Completed Oper proposed work) SEE RULE 1103. 	ations (Clearly state all pertinen	t details, and give pertinent d	ates, including estimated date of starting any		
CHEVRON U.S.A. INC. INTENDS TO CM GLORIETA/PADDOCK RESERVOIR.	T SQZ THE HORIZONTAL LAT	ERAL IN THE SUBJECT WE	LL & RECOMPLETE DEEPER IN THE		
THE INTENDED PROCEDURE, & CURRENT & PROPOSED WELLBORE DIAGRAMS ARE ATTACHED FOR YOUR APPROVAL.					
A PIT WILL NOT BE USED FOR THIS WORKOVER. A STEEL FRAC TANK WILL BE UTILIZED.					
			1919141-2122232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829302 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-363112829 1919141-21-212232425-3631 1919141-21-212232425-3631 1919141-21-212232425-3631 1919141-21-212232425-3631 1919141-21-212232425-3631 1919141-21-2122324 1919141-21-2122324 1919141-21-2122324 191914-21-2122 191914-21-212 191914-212 1919		
I hereby certify that the information above is true and complete to the SIGNATURE		gulatory Specialist	DATE <u>12/13/2006</u> Telephone No. 432-687-73	75	
TYPE OR PRINT NAME Den	nise Pinkerton				
(This space for State Use) APPROVED CONDITIONS OF APPROVAL, IF ANY:	Cliande DISTRICT S	UPERVISOR/GENERAL	MAMAGER DATE FEB 2 1 2007		

Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 11/14/2006. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and **open valve** at header. Document this process in the morning report.
- 3. MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. POH with rods and pump. Remove WH. Install BOP's and test as required. POH with 2 7/8" tbg string. LD TAC.
- 4. PU and GIH with 4 ³/₄" MT bit and 2 7/8" work string to PBTD at 4986'. POH with 2 7/8" work string and bit. LD bit.
- 5. PU & GIH with 5 ½" sqz pkr on 2 7/8" work string to 4900'. Set pkr at 4900'. Pressure test pkr, sqzd perfs, and csg to 350 psi. If csg tests good, pump down tbg and establish injection rate and pressure into horizontal lateral using 8.6 PPG cut brine water. Report injection rate and pressure to WEO Engineer for cement design/tool type. Note: If csg will not test satisfactorily, GIH with RBP and pkr and pressure test sqzd perfs separately (3896-3994' and 4686-4874') to determine which set has broken down. Discuss test results with Engineering before proceeding. Release pkr. POH with 2 7/8" work string and pkr. LD pkr. PU & GIH with 5 ½" tbg-set CICR on 2 7/8" work string to 5500 psi. Set CICR at 4900'. Pressure test pkr and csg to 350 psi. Note: Do not exceed 350 psi casing pressure due to cmt sqzd perfs from 3896-3994' and 4686-4874'. Leave pressure on casing while cmt squeezing. Establish injection rate into horizontal lateral from 4980-6150' MD. Report injection rate and pressure for cement design/tool type.
- 6. RU DS Services cementing equipment. Cement squeeze horizontal lateral using Class C cement mixed to 14.8 PPG w/ 1.35 CFY. Attempt to achieve at least 1000 psi surface squeeze pressure. Sting out of CICR. Reverse out excess cement. POH

with 2 7/8" work string and stinger. LD stinger. RD and release DS Services cementing equipment. Shut well in and WOC overnight.

- 7. Open well and bleed off any pressure. PU and GIH with 4 ³/₄" MT bit, DC's, and stabilizers on 2 7/8" work string to top of CICR at 4900'. Drill out CICR and cement to top of CIBP at 4986'. Reverse circulate well clean from 4986' using 8.6 PPG cut brine water. Pressure test casing and sqzd lateral to 350 psi. If lateral leaks, repeat cmt sqz procedure. Note: Since well is a producer, a slight pressure loss is acceptable. Drill out CIBP at 4986'. Cleanout 5 ¹/₂" casing and 4 ³/₄" open-hole to TD at 5400'. Reverse circulate well clean from 5400', if possible. POH with 2 7/8" work string and BHA. LD BHA.
- 8. PU & GIH 5 ¹/₂" treating pkr on 2 7/8" work string to approximately 4900'. Set pkr at 4900'. Pressure test casing and sqzd perfs to 350 psi. Leave pressure on casing during acid job and monitor for communication.
- 9 MI & RU DS Services. Acidize open-hole interval from 5000-5400' with 6,000 gals antisludge 15% HCl acid *** at a maximum rate of 6 BPM and a maximum surface pressure of 3500 psi. Pump job as follows:

Pump 1,500 gals acid at 6 BPM
Pump 1,000 gals gelled 10 PPG brine containing 1500 lbs GRS at 6 BPM
Pump 1,500 gals acid at 6 BPM
Pump 1,000 gals gelled 10 PPG brine containing 1500 lbs GRS at 6 BPM
Pump 1,500 gals acid at 6 BPM
Pump 1,000 gals gelled 10 PPG brine containing 1500 lbs GRS at 6 BPM
Pump 1,000 gals gelled 10 PPG brine containing 1500 lbs GRS at 6 BPM
Pump 1,000 gals gelled 10 PPG brine containing 1500 lbs GRS at 6 BPM

Displace acid with 8.6 PPG cut brine water -- do not overdisplace. Record ISIP, 5, 10, & 15 minute SIP's. RD and release DS Services. <u>Note:</u> Pickle tubing in 1 run of 500 gals acid, prior to acidizing perfs. Pickle acid is to contain only 1/2 gal A264 and 1 gal W53.

*** Acid system is to contain:	1 GPT A264	Corrosion Inhibitor
	8 GPT L63	Iron Control Agent
	2 PPT A179	Iron Control Aid
	20 GPT U66	Mutual Solvent
	2 GPT W53	Non-Emulsifier

- 10 Shut well in for 2 hours for acid to spend. Open well and flow/swab back spent treatment fluids. Recover 100% of spent acid and load before SI well for the night. Report oil cut, recovered fluid volumes, pressures, and/or swabbing fluid levels.
- 11 Open well. Pump down tbg with 8.6 PPG cut brine water to kill well, if necessary. Release pkr. POH with 2 7/8" work string and packer. LD pkr.

- 12 PU 4 ³/₄" MT bit and GIH on 2 7/8" work string to TD at 5400'. If fill is encountered, MI & RU air unit and cleanout to 5400' using foam. POH with 2 7/8" work string and MT bit. LD MT bit.
- 13. PU and GIH w/ BP mud anchor jt of 2 7/8" tbg, 2 7/8" x 4' perforated sub, SN, 1 jt 2 7/8" EUE 8R J-55 IPC tbg, 46 jts 2 7/8" EUE 8R J-55 tbg, TAC, and 122 jts 2 7/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 3800', with EOT at 5300' and SN at 5265'.
- 14. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit.
- 15. Turn well over to production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.

AMH 11/15/06



.



.