Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS				J. Lease Senai No.
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals				NMNM-65194 6. It Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE				7
				7. Unit or CA Agreement Name and No.
1a. Type of Well 🗌 Oil Well 🗹 Gas Well 🔲 Other				8 Well Name and No.
2. Name of Operator				Paloma Blanco 17 Federal Com 2
DEVON ENERGY PRODUCTION COMPANY, LP				9. API Well No.
3. Address and Telephone No.				30-025-38024
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198				10. Field and Pool, or Exploratory
4. Location of Well (Report location clearly and in accordance with Federal requirements)*			Strawn 12. County or Parish 13. State	
600 FSL 1980 FWL Unit N				
N 17 23S 34E  CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NO				
TYPE OS SUBMISSION	CHECK APPROPRIATE D	OX(S) TO INDICATE NA		YPE OF ACTION
☐ Notice of Intent	Acidize	Deepen	Productio	tion (Start/Resume)
	Alter Casing	Fracture Treat	Reclamat	
Subsequent Report	☐ Casing Repair☐ Change Plans	New Construction Plug and Abandon	Recomple Tempora	plete
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Dis	·
give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed once lesting has been completed. Final Abandonment Notices shall be filed oncy after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection).  11/10/06 - 1/16/07:  RU PU. Unload tubing and RIH with bit. Tagged at 13,698'. RIH with gun and packer and set packer. Perforate Morrow at 13,418-13,155'. Tested packer and casing to 1000 psi - held good. RD BOP and tree up well. Tested tree to 10,000 psi - held good. Swab well dry. RU and acidize w/ 1500 gallons 7.5% HCl with methanol. Swab well. NID ree and NU BOP. Release packer and POOH with tubing and packer. Frac Morrow with 14,565# 18/40 Ultraprop. Swab well. RIH with tubing and packer and set packer at 13,032'. Swab well down to packer. MIRU PU. Pumped 2% KCl down tubing. ND tree and NU BOP. Released packer. POOH with tubing and packer. Lay down packer. RU W/L. RIH with CIBP and set at 13,120'. Loaded casing with 2% KCl and tested CIBP to 1000 psi - held good. Dumped 35' of cement on top of plug. RIH with guns and perforated Strawn at 11,892-12,312'; 45 holes. RU W/L to set packer. RIH with packer and plug. Set packer at 11,860'. ND BOP and NU wellhead. Tested casing and packer to 1000 psi - held good. Pump out plug and acidize Strawn with 4500 gallons 15% HCl. Flow well back. Released packer. POOH with tubing and packer. Frac Strawn formation w/ 240,000 gallons lighting 3000 frac fluid w/ 302,500# Versaprop 18/40 and 7,250 # AcFrac black plus 40/70 sand. Flushed w/ 18,917 gallons 10# linear gel. Flowed well back. RIH with pump out plug and packer. Set packer at 11,860'. Latched onto packer and released. Tested casing to 1000 psi - held good.  10/10/10/10/10/10/10/10/10/10/10/10/10/1				
Signed	Name _ Title	Norvella Ada Sr. Staff Engineering	irfis	Date2/9/2007
(This space for Federal or State Office use		_		
Approved by Conditions of approval, if any:	Title	Goologist	<u></u>	Date