Submit 3 Copies T Office	o Appropriate District	State of New Menergy, Minerals and National State of New Menergy, Minerals and National State of New Menergy, Minerals and			Form C-103 May 27, 2004
District I 1625 N. French Dr	., Hobbs, NM 87240	Lifeigy, Windrais and Iva	iarar resources	WELL API NO.	
District II				30-025-063	
District III	District III 1220 South St. Francis Dr.			5. Indicate Type of Le	FEE
District IV		Santa Fe, NM	87505	6. State Oil & Gas Lea	
1220 S. St. Francis	Dr., Santa Fe, NM 87505			6. State Off & Gas Lea	ase No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Uni Eunice Monument Sc	
1. Type of Well: Oil Well X Gas Well Other				8. Well Number 175	
2. Name of Operator				9. OGRID Number	
XTO Energ				005380	
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701				10. Pool name or Wild Eunice Monuments &	
4. Well Location		2	Amorty-San Andres		
4. Well Location  Unit Letter N : 660 feet from the South line and 1980 feet from the West line					
Unit Lette	er <u>N</u> :	leet from the	outh line and	1900/19 feet from the	
Section	32	Township 20S	Range 37E	NMPM	Santy F Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
Pit or Below-grade Tank Application or Closure					
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest specific water well Distance from nearest fresh water well Distance from					
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				_	ALTERING CASING
TEMPORARILY	ABANDON 🔲	CHANGE PLANS	COMMENCE DRILL		PLUG AND
PULL OR ALTER CASING  MULTIPLE CASING TEST AND CEMENT JOB					ABANDONMENT
	ability under bond	d is retained small	OEMENT GOD		
OTHER:	surface restoration	is completed.	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
3/10/07		tbg OE. Tagged TOC @ 3,60	00'. Mixed mud & ci	rc TCA to surf. Spot	ted 35 sxs of cmt
3/13/07	@ 3,600'. POOH w/40 jts of 2-7/8" tbg. Opened up well. WH had press on 7" & 9-5/8". RIH w/tbg. Tagged TOC @3,442'. PUH & spotted 25 sx of cmt w/2% CaCl fr 2,560'-2,340'. RIH & tagged TOC @ 2,340'. RIH & perf'd @ 1,219'. RIH w/pkr				
		Std circ between 7" x 9		). Kin & pert a @ i	,219 . KIH W/pKr
3/14/07	Opened up well. No gas or flow on well. Bull plug on intermediate was leaking. Replaced plug. Nipple on other side was leaking. Performed Hot Work Permit. Repaired nipple. Sqzd 50 sx of cmt @ 1,219'.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE Kusty Ward TITLE Regulatory Analyst DATE 03/28/07					
SIGNATURE	1			risty ward@xtoenergy	
Type or print name Kristy Ward  Telephone No. 432-620-6740					
APPROVED BY ONLY DATE DATE					
APPROVED BY		-WMP OFFELD	IREALESENTATIVE IV	DAT	
Conditions of A <sub>1</sub>	oproval, if and:				APR 02 2007

## Eunice Monument South Unit #175 Plug & Abandon Cont'd.

- Opened up well. RIH w/tbg. Tagged TOC @1,049'. Well was gassing on back side. Notified NMOCD rep Buddy Hill of work procedures being done on well, he approved. RIH & perf'd. @ 1,000'. POOH w/WL. RIH w/pkr & tbg to 950'. Pmpd 50 sx of cmt. Rel pkr. POOH w/tbg. LD pkr.
- Opened up well. No flow & no gassing on csg. RIH & tagged TOC @ 814'. RIH & perf'd. @ 316'. RIH w/pkr & 1 jt of 2-7/8" tbg. Pmpd 100 sx of cmt in 7" & 7" x 9-5/8" csg to surf. RDMO P&A equip. Welder to cut off WH & anchors. Backhoe to cover cellar.

## **WELL DATA SHEET**

