State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION	
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-07382
DISTRICT II	, Santa 1 0,		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210			STATE FEE X
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	10.000		
SUNDRY NO	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Name
1	ROPOSALS TO DRILL OR TO DEEPEN		North Hobbs (G/SA) Unit
	APPLICATION FOR PERMIT" (Form G	101) for such proposals.)	Section 20
1. Type of Well:	Gas Well Other	·	8. Well No. 231
Oil Well X 2. Name of Operator	Gas Well Other	emporarily Abandoned	9. OGRID No. 157984
Occidental Permian Ltd.		=122	137701
3. Address of Operator	203	56	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, T.	X 79323	20/	
4. Well Location	/ <u>&</u>	R 93	
Unit Letter K : 2310 Feet From The South Section 20 Township S8-S Rate N 38-E NMPM Lea County			
Section 20	Township 38-S	8 RADE N 38.	-E NMPM Lea County
13449	11. Elevation (Show whether DF, R.		
1.50 (1.00)	3645' GL		
Pit or Below-grade Tank Application	or Closure		
		() () () () () () () () () ()	Distance from nearest surface water
			ı
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction N	laterial
12. Chec	k Appropriate Box to Indicate Na	ture of Notice, Report, or	Other Data
NOTICE OF IN			SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	
TEINIT OTARIET ABARBON	CHANGET EARC	OCIMINE NOE BINEELING OF	110:
DULL OD ALTED CACING	Multiple Completion	CACING TEST AND CEME	NT IOD
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEME	
PULL OR ALTER CASING OTHER:	Multiple Completion	CASING TEST AND CEME OTHER: Deepen & retu	
OTHER: 13. Describe Proposed or Completed C	perations (Clearly state all pertinent	OTHER: Deepen & retu	tes, including estimated date of starting any
OTHER: 13. Describe Proposed or Completed Comproposed work) SEE RULE 1103	perations (Clearly state all pertinent of For Multiple Completions: Attachy	OTHER: Deepen & retu	tes, including estimated date of starting any
OTHER: 13. Describe Proposed or Completed Comproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case	perations (Clearly state all pertinent of For Multiple Completions: Attachy	OTHER: Deepen & retu	tes, including estimated date of starting any
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars.	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK.	OTHER: Deepen & return details, and give pertinent darwellbore diagram of proposed	tes, including estimated date of starting any d completion or recompletion.
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circle	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. ent from 3920-3955'. Drill on CIBI of Clean & RD power swivel.	OTHER: Deepen & return details, and give pertinent darwellbore diagram of proposed	tes, including estimated date of starting any
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. ent from 3920-3955'. Drill on CIBI of Clean & RD power swivel. w/Kutrite shoe. Tag @4135'.	OTHER: Deepen & returned details, and give pertinent day wellbore diagram of proposed. P. Drill loose & pushed to 4	tes, including estimated date of starting any decompletion or recompletion. 1125'. Tag w/bit @4134'. Drill out CIBP. Clean
OTHER: 13. Describe Proposed or Completed Comproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circle 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the same of the same of the same out sand the same out same out sand the same out sand the same out s	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. ent from 3920-3955'. Drill on CIBI of Clean & RD power swivel. w/Kutrite shoe. Tag @4135'.	OTHER: Deepen & returned details, and give pertinent day wellbore diagram of proposed. P. Drill loose & pushed to 4	tes, including estimated date of starting any d completion or recompletion.
OTHER: 13. Describe Proposed or Completed Comproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circle 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe.	perations (Clearly state all pertinent of For Multiple Completions: Attachving & BOP to 1000 PSI. OK. Internal of the state of the sta	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed. P. Drill loose & pushed to 4. 50'. Tag top of fish @4158	tes, including estimated date of starting any decompletion or recompletion. 1125'. Tag w/bit @4134'. Drill out CIBP. Clean 18'. Wash over to 4165'. Circ clean. RD power
OTHER: 13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'.	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of Clean & RD power swivel. W/Kutrite shoe. Tag @4135'. ght spot from 4135-4140', 4148-41 power swivel & wash over from 41 Lost circulation. RU HES cement	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed. P. Drill loose & pushed to 4. 50'. Tag top of fish @4158. 165' to 4179'. POOH w/sh truck. Pump 63 bbl 14.8# c	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. element. Well began circulating Drill cement from
OTHER: 13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circle 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Internal of the state of the st	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed. P. Drill loose & pushed to 4. 50'. Tag top of fish @4158. 65' to 4179'. POOH w/sh truck. Pump 63 bbl 14.8# commation from 4217-4284'.	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. The sement. Well began circulating. Drill cement from Quit making hole. RIH w/new bit & continue
OTHER: 13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circe 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'.	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Internal of the state of the st	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed. P. Drill loose & pushed to 4. 50'. Tag top of fish @4158. 65' to 4179'. POOH w/sh truck. Pump 63 bbl 14.8# commation from 4217-4284'.	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. element. Well began circulating Drill cement from
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through to swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD p	perations (Clearly state all pertinent of the perations of the perations of the perations of the perations of the peration of	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed P. Drill loose & pushed to 4 50'. Tag top of fish @4158 165' to 4179'. POOH w/sh ruck. Pump 63 bbl 14.8# commation from 4217-4284'. *** additional day.	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power one. where the recompletion of the
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through to swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD p	perations (Clearly state all pertinent of the perations of the perations of the perations of the perations of the peration of	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed P. Drill loose & pushed to 4 50'. Tag top of fish @4158 165' to 4179'. POOH w/sh ruck. Pump 63 bbl 14.8# commation from 4217-4284'. *** additional day.	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. The sement. Well began circulating. Drill cement from Quit making hole. RIH w/new bit & continue
OTHER: 13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circles and Collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD possible for the swivel.	perations (Clearly state all pertinent at For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Internal of the state of the st	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed P. Drill loose & pushed to 4 50°. Tag top of fish @4158 (65° to 4179°. POOH w/shruck. Pump 63 bbl 14.8# commation from 4217-4284°. **** additional day wedge and belief. Further certification or an (attached) alternation or an (attached) alternation.	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power one. We we will be gan circulating. Drill cement from Quit making hole. RIH w/new bit & continue at a on attached sheet*** by that any pit or below-grade tank has been/will be
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circle 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD properties of the switch of	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In true and complete to the best of my known in the state of the set of my known in the set of the set of my known in the set of the set of my known in the set of the set of my known in the s	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed P. Drill loose & pushed to 4	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power one. We we will be gan circulating. Drill cement from Quit making hole. RIH w/new bit & continue at a on attached sheet*** by that any pit or below-grade tank has been/will be
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circle 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD properties of the switch of	perations (Clearly state all pertinent at For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Internal of the state of the st	OTHER: Deepen & return details, and give pertinent day wellbore diagram of proposed P. Drill loose & pushed to 4 50°. Tag top of fish @4158 (65° to 4179°. POOH w/shruck. Pump 63 bbl 14.8# commation from 4217-4284°. **** additional day wedge and belief. Further certification or an (attached) alternation or an (attached) alternation.	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. 425 tement. Well began circulating Drill cement from Quit making hole. RIH w/new bit & continue ata on attached sheet*** 425 that any pit or below-grade tank has been/will be the OCD-approved
13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD proposed according to NMOCD guidelines.	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In the structure of the best of my known is the structure of the best of my known is the structure of the structure of the second of the structure of the second	OTHER: Deepen & return details, and give pertinent data wellbore diagram of proposed. P. Drill loose & pushed to 4. 50'. Tag top of fish @4158. 65' to 4179'. POOH w/sh truck. Pump 63 bbl 14.8# cormation from 4217-4284'. *** additional data wedge and belief. Further certification or an (attached) alternation plan	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. Weement. Well began circulating Drill cement from Quit making hole. RIH w/new bit & continue ata on attached sheet*** Ty that any pit or below-grade tank has been/will be twe OCD-approved E Associate DATE 04/10/2007
13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test case 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD proposed according to NMOCD guidelines.	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In true and complete to the best of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some switch structure of the set of my known some switch set of my known set of mail address:	OTHER: Deepen & return details, and give pertinent data wellbore diagram of proposed of the details, and give pertinent data wellbore diagram of proposed of the deep diagram of proposed of the deep diagram of proposed of the deep diagram of the d	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. Joint Making hole. RIH w/new bit & continue ata on attached sheet*** by that any pit or below-grade tank has been/will be twe OCD-approved 12
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through to swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD proposed according to NMOCD guidelines I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. For State Use Only	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In true and complete to the best of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some switch structure of the set of my known some switch set of my known set of mail address:	OTHER: Deepen & return details, and give pertinent data wellbore diagram of proposed of the details, and give pertinent data wellbore diagram of proposed of the deep diagram of proposed of the deep diagram of proposed of the deep diagram of the d	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. Joint Making hole. RIH w/new bit & continue ata on attached sheet*** by that any pit or below-grade tank has been/will be twe OCD-approved 12
13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD proposed according to NMOCD guidelines I hereby certify that the information above it constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. For State Use Only APPROVED BY	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In true and complete to the best of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some switch structure of the set of my known some switch set of my known set of mail address:	OTHER: Deepen & return details, and give pertinent data wellbore diagram of proposed of the details, and give pertinent data wellbore diagram of proposed of the deep diagram of proposed of the deep diagram of proposed of the deep diagram of the d	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power one. We we will be gan circulating. Drill cement from a Quit making hole. RIH w/new bit & continue at a on attached sheet*** Ty that any pit or below-grade tank has been/will be the occupance of the occupance occupance of the occupance occupance occupance occupance occupance
OTHER: 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD proposed according to NMOCD guidelines I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A.	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In true and complete to the best of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some switch structure of the set of my known some switch set of my known set of mail address:	OTHER: Deepen & return details, and give pertinent data wellbore diagram of proposed of the details, and give pertinent data wellbore diagram of proposed of the deep diagram of proposed of the deep diagram of proposed of the deep diagram of the d	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power one. We we will be gan circulating. Drill cement from a Quit making hole. RIH w/new bit & continue at a on attached sheet*** Ty that any pit or below-grade tank has been/will be the occupance of the occupance occupance of the occupance occupance occupance occupance occupance
13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 1. RUPU & RU. NU BOP. Test cas 2. RIH w/bit & drill collars. 3. RU power swivel & drill out ceme out sand & Hydromite to 4158'. Circ 4. POOH w/bit & drill collars. RIH 5. RU power swivel, wash through the swivel. POOH w/Kutrite shoe. 6. RIH w/2nd shoe, tag @4165'. RU 7. Drill new hole from 4179-4213'. 4013-4208'. Drill cement/formation drilling to 4365'. Circ clean. RD proposed according to NMOCD guidelines I hereby certify that the information above it constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. For State Use Only APPROVED BY	perations (Clearly state all pertinent of For Multiple Completions: Attach ving & BOP to 1000 PSI. OK. Int from 3920-3955'. Drill on CIBI of clean & RD power swivel. W/Kutrite shoe. Tag @4135'. In ght spot from 4135-4140', 4148-41 In power swivel & wash over from 41 Lost circulation. RU HES cement of the mix from 4208-4217'. Drill new for ower swivel. In true and complete to the best of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some swivel. In the structure of the set of my known some switch structure of the set of my known some switch set of my known set of mail address:	OTHER: Deepen & return details, and give pertinent data wellbore diagram of proposed of the details, and give pertinent data wellbore diagram of proposed of the deep diagram of proposed of the deep diagram of proposed of the deep diagram of the d	tes, including estimated date of starting any discompletion or recompletion. 4125'. Tag w/bit @4134'. Drill out CIBP. Clean 8'. Wash over to 4165'. Circ clean. RD power oe. Joint Making hole. RIH w/new bit & continue ata on attached sheet*** by that any pit or below-grade tank has been/will be twe OCD-approved 12

NHU 20-231 04/10/07

- 8. RU wireline & log well from 4360-3300'. RD wireline.
- 9. RIH w/7" packer set @3988' & perform 3 stage block job w/3000 gal of 15% PAD acid & 1500 lbs of rock salt. Flush w/50 bbl fresh water.
- 10. RU pump truck & pump 100 gal of 6490 mixed with 100 bbl of fresh water. Flush w/500 bbl of fresh water. RD pump truck.
- 11. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4007'.
- 12. ND BOP & NU tree.
- 13. RDPU & RU. Clean location.

RUPU 02/21/07 RDPU 03/13/07