State of New Mexico Energy, Minerals and Natural Resources Department


Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025	-05476
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210			5. Indicate Type of Lease STATE X	FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			North Hobbs (G/SA) Unit Section 24	
1. Type of Well:			8. Well No. 121	
Oil Well Gas Well Other Injector			0.000000	
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			
4. Well Location				
Unit Letter E : 1650	Feet From The North	990 Feet	From The West	- Line
Section 24	Township 18-S	Range 26-E	NMPM	Lea County
	11. Elevation (Show whether DF, Rk 3672' GL	(B, RT GR, etc.)		and the second s
Pit or Below-grade Tank Application	or Closure			
		earest fresh water well		urface water
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check NOTICE OF INTE	Appropriate Box to Indicate Na ENTION TO:	ture of Notice, Report, or O SUBS	other Data EQUENT REPORT O	₫; F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN		ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN		
	Multiple Completion			X
OTHER:				
 Describe Proposed or Completed Opproposed work) SEE RULE 1103.1 RUPU & RU. Test casing to 600# ND wellhead & NU BOP. POOH v Dump 11 buckets of pea gravel & fl RIH w/scraper & tag @4238'. POO RIH w/open ended tubing & tag per RIH w/cement retainer set @4175'. Super CBL. Sting out of retainer. RIH w/bit & drill collars. Tag @34 Wash out pea gravel down to 4300' POOH w/bit & drill collars. 	For Multiple Completions: Attach v for 30 minutes. OK. v/tubing & injection packer. lush w/40 bbls. OH w/scraper. a gravel @4250'. POOH w/tubing RU HES. Mix & pump 100 sxs (40'. Drill out cement & retainer for the state of the	vellbore diagram of proposed of the control of Premium plus w/.3 Halide,	ompletion or recompletion. , 150 sxs Premiun plus w/2	
		***additional data on attac	K-	6199-B
I hereby certify that the information above is t constructed or	rue and complete to the best of my know	ledge and belief. Ifurther certify t	hat any pit or below-grade tank h	nas been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	
SIGNATURE MUNCLY	Tijohman	TITLE Administrative	Associate DATI TELEPHONE NO. TATIVE IVSTAFF DATE DATE	4/25/07
	ohnson F-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	AGER6-592-6280
For State Use Only	1. 1. 1		STATIVE IVSTAFF AVE	
APPROVED BY TANK	way	OC FIELD REPRESEN	DAT	TE
CONDITIONS OF APPROVAL IF ANY:		-		
•				MAY 1 5 2007

NHU 24-121 04/25/2007

- 10. RU wireline & perf from 4247-4250' @1 JSPF. RD wireline.
- 11. RIH w/treating packer set @4182'. \overline{RU} HES & pump 500 gal of acid, 500# gelled rock salt block, 1000 gal of acid, 500# gelled rock salt block & 500 gal of acid. Open bypass & reverse out. POOH w/ treating packer.
- 12. RIH w/notched collar set @4012'.
- 13. RU power swivel & wash out salt from 4012-4300'. Circ clean. POOH w/notched collar. RD power swivel.
- 14. RIH w/7" G-6 packer w/1.875 F-nipple on 130 jts of 2-7/8" Duoline 20 tubing. Packer set @3959'.
- 15. ND BOP & NU wellhead.
- 16. Test casing to 680# for 30 minutes and chart for the NMOCD.
- 17. RDPU & RU. Clean location.

RUPU 03/23/2007 RDPU 04/06/2007



Month Hope mit

tering and the second second

Anger.

Marica We all