Submit 3 Copies To Appropriate Distric	t State of New	Mexico 29 30 31 - 7	3	Form C-103
Office District I	Energy, Minerals and N	latura Resources	2007	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		6V PS	WBC API NO. 30-025-2	
District II	OIL CONSERVATION	ONODIVISIONO .	30-025-2	1781
1301 W. Grand Ave., Artesia, NM 8821 District III	1220 South St. F	Trafficis Dr. Sive	5. Indicate Type of Lease STATE State Oil & Gas Lease 6.	se
1000 Rio Brazos Rd., Aztec, NM 87410	Sonto Fo. NIM	PORCOS PROCESTOS	6. State Oil & Gas Lea	FEE
District IV	Santa Fe, INIV.	1 9 SDO2 1 HOND	6. State Oil & Gas Lea	ise No.
1220 S. St. Francis Dr., Santa Fe, NM 8	OTICES AND DEPORTS ON WE	110	3. B 100 Zease Name or Unit	A arrament Names
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESERVOIR. USE "APP PROPOSALS.)	OTICES AND REPORTS ON WEI POSALS TO DRILL OR TO DEEPEN OR PLICATION FOR PERMIT" (FORM C-101	PLUG BACKSTO ALLOLGI FOR SUCH	New Mexico "BV" NC	T-2
1. Type of Well: Oil Well	Gas Well Other		8. Well No. 1	
2. Name of Operator			9. OGRID Number	
CrownQuest Operation	ng LLC		21319	90
3. Address of Operator			10. Pool name or Wildo	eat ,
PO Box 53310, Midla	nd, TX 79710		Lazy "J" Pen	nsylvanian
4. Well Location			•	
Unit Letter E	: 1980 feet from the North	line and 660	feet from the	West line
Section 36	Township 13S	Range 13E		ounty Lea
	11. Elevation (Show whether I	DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank App				
Pit type Depth to Gre		rest fresh water well		rface water
Pit Liner Thickness:	mil Below-Grade Tank: Volum	e bb	ols; Construction Material	
12. Chec	k Appropriate Box to Indicate	Nature of Notice, I	Report or Other Data	
	11 1		•	
	INTENTION TO:		SEQUENT REPOR	
PERFORM REMEDIAL WORK		REMEDIAL WORK		RING CASING
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐	COMMENCE DRIL		DA 🛛
PULL OR ALTER CASING	☐ MULTIPLE ☐	CASING/CEMENT	JOB 🖂	
	COMPLETION			
	COMPLETION			
OTHER:	COMPLETION	OTHER:		
			ve pertinent dates, includ	ing estimated date of
13. Describe proposed or comp	leted operations. (Clearly state all p	pertinent details, and give		
13. Describe proposed or comp starting any proposed work		pertinent details, and give		
13. Describe proposed or comp starting any proposed work recompletion.	oleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple 0	pertinent details, and give		
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e	oleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of equipment.	pertinent details, and giv Completions: Attach w	ellbore diagram of propo	sed completion or
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rin	oleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple or equipment.	pertinent details, and given completions: Attach was and set @ 7600'.	ellbore diagram of propo	sed completion or
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol	oleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Cle w/ mud laiden fluid, (110 bbls).	pertinent details, and give Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN.	ellbore diagram of propo	sed completion or
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and	equipment. ng to 7600'. POH. RIH w/ 4 1/2 Cle w/ mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI	pertinent details, and given completions: Attach was been completed and set @ 7600'. I POH w 70 jts. SDFN.	ellbore diagram of propor Dumped bailed 35' on to	op of plug. RIH w/ 2
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg.	equipment. le w/ mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44	pertinent details, and given completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5	ellbore diagram of propor Dumped bailed 35' on to 5/8 shoe. POH w/ tbg. SI	op of plug. RIH w/ 2
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'.	equipment. The second of the	pertinent details, and given completions: Attach was and set @ 7600'. I POH w 70 jts. SDFN. FN. 60 across stub and 8 5 laiden fluid. Spot 40 st	ellbore diagram of propositions Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN.	op of plug. RIH w/ 2
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'.	equipment. In the second of t	pertinent details, and given completions: Attach was and set @ 7600'. I POH w 70 jts. SDFN. FN. 60 across stub and 8 5 laiden fluid. Spot 40 st	ellbore diagram of propositions Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN.	op of plug. RIH w/ 2
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb	equipment. In the properties of the properties	pertinent details, and given completions: Attach was and set @ 7600'. I POH w 70 jts. SDFN. FN. 60 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN.	op of plug. RIH w/ 2 DFN. RIH w/ tbg. to 415'.
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb	equipment. In the second of t	pertinent details, and given completions: Attach was and set @ 7600'. I POH w 70 jts. SDFN. FN. 60 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN.	op of plug. RIH w/ 2 DFN. RIH w/ tbg. to 415'.
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'.	equipment. In the properties of the properties	pertinent details, and given completions: Attach was and set @ 7600'. I POH w 70 jts. SDFN. FN. 60 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN.	op of plug. RIH w/ 2 DFN. RIH w/ tbg. to 415'.
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'.	equipment. In the properties of the properties	pertinent details, and gir Completions: Attach w BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 160 across stub and 8 5 I laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off	ellbore diagram of proportions Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. Wellhead, Install Dry H	op of plug. RIH w/ 2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'.	equipment. In the properties of the properties	pertinent details, and give Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 60 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of t	op of plug. RIH w/ 2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore.
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'.	equipment. In the properties of the properties	pertinent details, and give Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. SN. 60 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off Approach.	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the try under bond is retain	op of plug. RIH w/ 2 DFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. and until
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'.	equipment. In the properties of the properties	pertinent details, and give Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. SN. 60 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off Approach.	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of t	op of plug. RIH w/ 2 DFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. and until
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple or requipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between g. CWI SDFN. POH to 60'. Spot 25 sx. cement to	pertinent details, and give Completions: Attach we are also and set @ 7600'. I POH w 70 jts. SDFN. FN. 1600 across stub and 8 5 laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off Liabili surface.	Dumped bailed 35' on to 5/8 shoe. POH w/ tbg. SI sx. cement. SDFN. casing head and BOP. wellhead, Install Dry Hoved as to plugging of the treatment of the complete restoration is complete restoration.	op of plug. RIH w/ 2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. ned until eted.
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of the equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between g. CWI SDFN. POH to 60'. Spot 25 sx. cement to	pertinent details, and gir Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5 I laiden fluid. Spot 40 stan 13 3/8 and 8 5/8. NU surface. POH. Cut off Appro- Liabilis surface	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the ty under bond is retained restoration is completed. I further certify that any	op of plug. RIH w/ 2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. ned until eted. pit or below-grade tank
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple or requipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between g. CWI SDFN. POH to 60'. Spot 25 sx. cement to	pertinent details, and gir Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5 I laiden fluid. Spot 40 stan 13 3/8 and 8 5/8. NU surface. POH. Cut off Appro- Liabilis surface	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the ty under bond is retained restoration is completed. I further certify that any	op of plug. RIH w/ 2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. ned until eted. pit or below-grade tank
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of the equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between g. CWI SDFN. POH to 60'. Spot 25 sx. cement to	pertinent details, and gir Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5 I laiden fluid. Spot 40 stan 13 3/8 and 8 5/8. NU surface. POH. Cut off Appro- Liabilis surface	Dumped bailed 35' on to 1/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the ty under bond is retained restoration is completed. I further certify that any an (attached) alternative OC	op of plug. RIH w/ 2 DFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. ned until eted. pit or below-grade tank D-approved plan
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of the equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between g. CWI SDFN. POH to 60'. Spot 25 sx. cement to	pertinent details, and gir Completions: Attach was BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5 I laiden fluid. Spot 40 stan 13 3/8 and 8 5/8. NU surface. POH. Cut off Appro- Liabilis surface	Dumped bailed 35' on to 1/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the ty under bond is retained restoration is completed. I further certify that any an (attached) alternative OC	op of plug. RIH w/ 2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. ned until eted. pit or below-grade tank
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Cle w/ mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI. to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/ mud. ND casing head. Cement between g. CWI SDFN. POH to 60'. Spot 25 sx. cement to the best sed according to NMOCD guidelines. TITL	Dertinent details, and give Completions: Attach we completions: Attach we complete the completions: Attach we complete the	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the treatment of the restoration is completed. I further certify that any an (attached) alternative OC	op of plug. RIH w/2 DFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. ned until eted. pit or below-grade tank D-approved plan TE 5-25-07
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off. I hereby certify that the information has been/will be constructed or closs SIGNATURE.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of the equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class of the w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between the complete to 60'. Spot 25 sx. cement to above is true and complete to the best according to NMOCD guidelines. E-mail a	BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5 I laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off Appro Liabili surface of my knowledge and beli], a general permit The surface of the s	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the treatment of the restoration is completed. I further certify that any an (attached) alternative OC	op of plug. RIH w/2 DFN. RIH w/ tbg. to 415'. Hole Marker. Clean The Well Bore. The ded until ted. The below-grade tank D-approved plan The below-grade tank The below-grade tank The below-grade tank The below-grade tank The below-grade tank
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of the equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class of the w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between the complete to 60'. Spot 25 sx. cement to above is true and complete to the best according to NMOCD guidelines. E-mail a	BP and set @ 7600'. I POH w 70 jts. SDFN. FN. 600 across stub and 8 5 I laiden fluid. Spot 40 sen 13 3/8 and 8 5/8. NU surface. POH. Cut off Appro Liabili surface of my knowledge and beli], a general permit The surface of the s	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the treatment of the restoration is completed. I further certify that any an (attached) alternative OC	op of plug. RIH w/2 DFN. RIH w/ tbg. to 415'. Hole Marker. Clean The Well Bore. The ded until ted. The below-grade tank D-approved plan The below-grade tank The below-grade tank The below-grade tank The below-grade tank The below-grade tank
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off. I hereby certify that the information has been/will be constructed or closs SIGNATURE April 10 Company 10 Compan	equipment. In the properties of the properties	Dertinent details, and give Completions: Attach we completions: Attach we complete the set @ 7600'. It is a possible to the set of t	Dumped bailed 35' on to 1/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the try under bond is retained restoration is completed. I further certify that any an (attached) alternative OC TECH DATE Telephone Note 11/STAFF MANAGEMENT.	op of plug. RIH w/2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. hed until eted. pit or below-grade tank D-approved plan TE 5-25-07 No. Y 3 0 2007
13. Describe proposed or comp starting any proposed work recompletion. 4/02/07 MI Rig Up plugging e 4/03/07 RIH w 4 1/2 gauge rir 3/8 tbg. to 7550, circulated hol 4/04/07 POH w/ tbg. Cut and 4/05/07 NU BOP. RIH w/ tbg. 4/06/07 Tagged plug @ 3989'. 4/09/07 Tagged plug @ 1527'. Spot 40 sx cement. POH w/ tb 4/10/07 Tagged plug @ 292'. I Location, RD Move off. I hereby certify that the information has been/will be constructed or closs SIGNATURE.	pleted operations. (Clearly state all plants). SEE RULE 1103. For Multiple of the equipment. Ing to 7600'. POH. RIH w/ 4 1/2 Class of the w/mud laiden fluid, (110 bbls). POH with 4430' 4 1/2 casing. SDI to 4465' Spot 80 sx. cement @ 44. POH to 1650'. Load hole w/mud. ND casing head. Cement between the complete to 60'. Spot 25 sx. cement to above is true and complete to the best according to NMOCD guidelines. E-mail a	Dertinent details, and give Completions: Attach we completions: Attach we complete the set @ 7600'. It is a possible to the set of t	Dumped bailed 35' on to 8/8 shoe. POH w/ tbg. SI sx. cement. SDFN. I casing head and BOP. I wellhead, Install Dry Hoved as to plugging of the treatment of the restoration is completed. I further certify that any an (attached) alternative OC	op of plug. RIH w/2 OFN. RIH w/ tbg. to 415'. Hole Marker. Clean the Well Bore. hed until eted. pit or below-grade tank D-approved plan TE 5-25-07 No. Y 3 0 2007