Form 3160-5 (June 1990)	DEPARTMENT (OCD-HOBBS DISTATES OF THE INTERIOR ND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
Do not use this	form for proposals to drill o	D REPORTS ON WELLS or to deepen or reentry to a different reservoir. ERMIT—" for such proposals	NM-14496 6. If Indian, Allottee or Tribe Name
1. Type of Well	SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agreement Designation
Oil Gas Well 2. Name of Operator	8. Well Name and No.		
Fasken Oil and Ra	Ling Federal No. 1 9. API Weil No.		
3. Address and Telephone 303 W. Wall, Suite	30-025-28064 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Bone Spring
1980' FNL, 1980' FEL, Sec. 31, T19S, R34E			11. County or Parish, State Lea, NM
		O INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
	TYPE OF SUBMISSION TYPE OF ACTION		
_	of Intent	Abandonment Recompletion	Change of Plans New Construction
	bandonment Notice	Plugging Back Casing Repair Altering Casing	Non-Routine Fracturing Water Shut-Off Conversion to Injection
13 Describe Proposed or C	Completed Operations (Clearly and Indiana)	Other ment details, and give pertinent dates, including estimated date of starting	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Fasken Oil and Ra attached procedure This well has been abandon. The well A rig and the neces recompletion atten	anch, Ltd. proposes to recomplete and schematic. I temproraily abandoned for a numer must be back online or plugginusary equipment to perform this apt to me at (432) 687-1570.	ete the subject well into the Bone Springs interval from the Bone Springs in	s well before having to plug and
4. I hereby certify that the Signed WWW (This space for Federal of Approved by Conditions of approval,		Regulatory Affairs Coordinator	OVED 6/11/2007
itle 18 U.S.C. Section 1001 representations as to any r	, makes it a crime for any person knowing natter within its jurisdiction.	gly and willfully to make to any department or agency of the Uhild S	tates any false, fictinous or traudulent statements
GWW		*See Instruction on Reverse Side FREDER PETROLI	RICK WRIGHT EUM ENGINEER

Workover Procedure Ling Federal No. 1 API: 30-025-28064 1980' FNL, 1980' FEL, Sec 31, T19S, R34E Lea County, NM AFE 1301

Objective: 2nd attempt to block squeeze and recomplete to 1st Bone Spring

API: 30-025-28064 KB: 22' above GL

Completed March 30, 1983

TD: 13,690'

PBTD: 9450' Cmt Retainer and CIBP 12200' w/35' cmt (Sep 30, 2000)

13-3/8" @ 400' KB w/450 sx circ 191 sx.

9-5/8" 36 & 40#/ft @ 5221'KB w/2600 sx circ 892 sx.

5-1/2": 17 & 20#/ft (bottom 3841') N-80 @ 13,690' DV @ 9367' 1st stg 325 sx HLW "H"+ 300 sx "H", 2nd stg w/ 1100 sx HLW "C" + 200 sx "C". TOC 3920' by Temp. TOC below DV 11,320' by CBL (Jan, '96)

Tubing: None PKR: None

Perfs: Bone Spring: 9500' (4 sqz hls), 9587'-93' (6h), 9638'-44' (6h), 9800' (4 sqz hls)

Note: Oct 1997 workover, perfs 9587'-9644' communicated to 9500' sq holes during acid job.

Strawn abandoned: 12,229-12,240 (23 holes).

Morrow abandoned: 13190'-13522' (162 holes) overall


- 1. Set matting board and pipe racks. Set open top blowdown tank. DO NOT DIG PIT UNLESS A PIT PERMIT HAS BEEN ISSUED TO MIDLAND OFFICE.
- Make sure rig mast anchors have been pull tested in last 24 months. If not, test anchors and install tags.
- 3. RUPU.
- 4. Receive 9800' 2-7/8" 6.5#/ft EUE 8rd N-80 tubing.
- 5. RU pump truck and pressure test casing to 1500 psi with fw.
- 6. RIW with cement retainer stinger on 2-7/8" tubing to top of CR at 9450', gently tag top of cement retainer.
- 7. RU stripper and pump truck. Establish circulation w/ 1-1/2-2 bpm down tubing and out tubing/casing annulus and slowly wash down into top of cement retainer using fresh water.
- 8. If circulation is lost on annulus make sure to establish injection rate into perforations at 1-2 bpm and report results to Midland office. RU on tubing casing annulus and pressure to 550 psi and monitor during cement job. If unable to sting into retainer notify Midland office.
- Establish injection rate at maximum pressure of 2000 psi into squeeze holes at 9500' and perfs 9587'-93' (6h), 9638'-44' (6h) with 10 bfw..
- 10. RU cement pump truck and squeeze perfs 9500' and 9587'-93' (6h), 9638'-44' (6h as per recommendation to follow.

- 11. Attempt to obtain 2000-3000 psi squeeze pressure if possible. Sting out of retainer and leave +/-6' cement on top of retainer. Reverse tubing clean and POW with tubing and setting tool.
- 12. SWI to WOC for 24-48 hours.
- 13. RIW with 4-5/8" bit, bit sub, 6-3-1/2" drill collars, XO, and 2-7/8" workstring to tag TOC. RU reverse drilling equipment. RU JU stripper and power swivel.
- 14. Establish circulation and start drilling cement. Drill out cement, retainer and remainder of cement.
- 15. After falling out of cement continue to RIW w/ 2 additional joints. Circulate well clean and close pipe rams. Pressure test casing and squeeze holes to 2500 psi for 35 minutes. Report results to Midland office.
- 16. After getting a good test on squeeze holes POW and LD BHA. Clean and release reverse unit.
- 17. RU wireline co. Perforate Bone Spring sand zone using 3-1/8" casing gun at 9,608'-9,631' w/1JSPF, 120° phased (48 holes) by Schlumberger Compensated Neutron-Litho Density log dated March 8, 1983.
- 18. RIW with 5-1/2" HD Arrowset IX packer, 4-1/2" X 2-3/8" X 1.78" "F" profile TOSSD, 2-7/8" tubing and set packer at +/-9520' (be sure to be below 9500' squeeze holes).
- 19. RU Acid pump truck, Trap 500 psi on csg-tbg annulus. Attempt to break down Bone Spring perfs 9,603'-9,631' with 750 gal 7-1/2% NEFE HCL at 1- 2 bpm with max treating pressure 1000 psi. Acid to contain:
 - 2 gal/M Clay Master-5C
 - 4 gal/M LT-32, surfactant
 - 1 gal/M I-22, organic inhibitor
 - 7 gal/M Ferrotrol-300L
 - 8 gal/M Acetic Anhydride Blend 1 gal I-22, corr. inhib.
- 20. Swab back load and acid water. Evaluate for further stimulation.
- 21. Release packer and RIW below bottom perforation. POW with tubing and packer.
- 22. RIW w/ SN, 10 jts 2-7/8" tubing, TAC, and tubing.
- 23. Run insert pump and rods. Set pumping unit.
- 24. Build tank battery and place well on production.
- 25. Return well to production.

CWB/cgt

(LingFed1 AFE1301 pro rev cgt cwb 6-7-07)

Ling Federal No. 1



cwb 6/8/2007 LingFed1 wb diagram.xls