

Submit 3 Copies To Appropriate District  
 Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis, Santa Fe, NM  
 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised May 08, 2003

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-025-35529	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Gach "31" State	
8. Well Number 1	
9. OGRID Number 217817	
10. Pool name or Wildcat Vacuum: Morrow	
<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator ConocoPhillips Company	
3. Address of Operator 4001 Penbrook St. Odessa TX 79762	
4. Well Location Unit Letter <u>O</u> : <u>990</u> feet from the <u>South</u> line and <u>1650</u> feet from the <u>East</u> line Section <u>31</u> Township <u>17 S</u> Range <u>34 E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4102'KB, 4083' GL, & 4101' DF	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK  PLUG AND ABANDON   
 TEMPORARILY ABANDON  CHANGE PLANS   
 PULL OR ALTER CASING  MULTIPLE COMPLETION

SUBSEQUENT REPORT OF:

REMEDIAL WORK  ALTERING CASING   
 COMMENCE DRILLING OPNS  PLUG AND ABANDONMENT   
 CASING TEST AND CEMENT JOBS

OTHER: Reperf & test

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU wireline using a 5000 psig lubricator. Pressure test lubricator to 3000 psig. Reperforate Morrow "Uncas Sand" 13,227-13,233 w/6 SPF (36 holes, 0.33" diameter, 60 phasing) using 3-3/8" High Shot Density (HSD) casing gun (20,000 psig rating) as per Schlumberger Tripple Detector Litho-Density Compensated Neutron / GF Log date 9/8/01 and Computalog Acoustic Cement Bond Gamma Ray CCL Log dated 10/25/01. RDMO wireline.

\*\*\*Continued on back\*\*\*

SEP 23 2003  
 RECEIVED  
 Hobbs  
 OGD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Alva Franco TITLE HSE&Regulatory Assistant DATE 09/16/2003

Type or print name Alva Franco Telephone No. (432)368-1665  
 (This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE SEP 23 2003  
 Conditions of approval, if any

2. RIH w/ one 2 3/8" wireline re-entry guide, one 2 3/8" x 1.875" "XN" profile nipple, one 2 3/8" L-80 tubing sub, one 5" x 2 3/8" 10K retrievable packer, one 4 1/2" x 2 3/8" XL On-Off Tool w/ 1.875" "X" profile nipple, one 2 7/8" 8rd box – 2 3/8" pin x-over, one 2 7/8" jt L-80 6.5# tubing, one 2 7/8" x 2.313" "X" profile nipple, and 2 7/8" L-80 6.5# tubing. Set packer at 13,300'+/-.
3. RU swab equipment and swab tubing to restore production from lower Morrow perforations 13,482-13,487'. RD swab equipment.
4. MIRU wireline using a 5000 psig lubricator. Pressure test lubricator to 3000 psig. RIH w/ gauge ring to 13,311'+/-. POOH w/ gauge ring. RIH & set blanking plug with equalizing ports in 2 3/8" x 1.875" "XN" profile nipple. Bleed off tubing pressure to verify blanking plug is holding. RDMO wireline.
5. Release 2 7/8" tubing from on/off tool. Move end of tubing to 13,200'+/-.
6. RU swab equipment and swab tubing and annulus fluid to restore production. RD swab equipment.
7. RDMO DDU and clean location. Produce well to sales for 3 days.
8. MIRU wireline using a 5000 psig lubricator. Pressure test lubricator to 3000 psig. RIH w/ gauge ring to 13,200'+/-. POOH w/ gauge ring.
9. RIH w/ one electronic pressure gauge and one Amerada pressure gauge. Obtain a deadweight flowing wellhead pressure. RIH making static gradient stops at the following depths: surface, 5,000', 10,000', 12,000', 13,000', 13,100', 13,150', and 13,200'.
10. Set gauges in 2 7/8" x 2.313" "X" profile nipple at 13,170'+/-. Release gauges and POOH. Continue to flow well until it has been confirmed at surface that gauges have been released and wireline has been rigged down. Shut in well for 72 hours or until surface P has stabilized.
11. MIRU wireline using a 5000 psig lubricator. Pressure test lubricator to 3000 psig. Obtain a deadweight wellhead shut-in pressure. RIH w/ retrieving tool and POOH with gauges making gradient stops at the following depths: 12,000', 10,000', 8,000', 4,000', and surface. RDMO wireline. Produce well to sales.
12. Deliver data to Tim Harrington (832-468-2207) in Houston office (Office WL3-6044) and Jack Lowder (432-368-1609) in Odessa office for evaluation to either stimulate the Morrow "Uncas Sand" or resume production from lower Morrow perforations.

*Jack T. Lowder*

Jack T. Lowder  
8/28/03