Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 rio Brazos Rd, Aztec, NM 87410	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-31735 5. Indicate Type of Lease STATE STATE FEE 6. State Oil & Gas Lease No. LG-7655
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Watkins 32 State
			8. Well No.
			1 9. Pool name or Wildcat Lusk N Bone Spring
4 Well Location Unit Letter <u>F</u> :1980 Feet From The North Line and 1650 Feet From The West Line			
Section 32		e 32E NMPM hether DF, RKB, RT, GR, etc.)	Lea County
Check Appropriate Box To Indicate Nature Of Notice, Report, Or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: <u>SQ2, CS</u>	CHANGE PLANS	REMEDIAL WORK	ALTERING CASING
 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. A sharp increase in water production was seen in late August through early September 2003. The well was pulled and tested to determine the location of the suspected casing leak. On 9/18/03 the leak was isolated in the interval 4445'-4510'. A pump rate was established at 2 BPM with 500 psi and circulation was obtained in the 8-5/8" x 5-1/2" annulus. The purpose of the following work is to squeeze cement the 5-1/2" casing. 			
 RU wireline unit and TIH with CIBP. Set CIBP at ~6900'. TOH with wireline. RIH with cement retainer on tubing. Set retainer at ~4350'. RU BJ Services. Squeeze cement with 180 sx. Class C per BJ Services Proposal # 215850801A. POH with tubing. WOC. RIH with drill bit on tubing. Drill out cement retainer and cement. Pressure test casing to 1000 psi. If casing tests, RIH and drill out CIBP. CO to 9000'. POH with tubing. RIH with original tubing detail. Swab tubing until well cleans up. ND BOP and NU WH. 			
RIH with rods and pump. Hang well on. RDMO PU.			
SIGNATURE TYPE OR PRINT NAME	a. Star	B OPERATIONS TECHNICIAN	DATE September 24, 2003 TELEPHONE NO. (405) 235-3611
(This space for State use) Approved by <u>Harry</u> Conditions of approval, if any:	D. Wink TITL	RICT SUPERVISOR/GENERAL MANA	GER <u>SEP 2 9 2003</u>

,