Submit 3 copies

State of New Mexico Energy Minerals and Natural Resources Department

Form C-103

District Office			Revised 1-1-89
<u>DISTRICT I</u>	OIL CONSERVA	ATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Bo		30-025-32159
DISTRICT II		1exico 87504-2088	5. Indicate Type of Lease
P.O. Box Drawer DD, Artesia, NM 88210			STATE FEE 🗹
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.
SUNDRY NOT	TICES AND REPORTS ON	IWELLS	
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO D	DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name
DIFFERENT RESEI (FORM)	RVOIR. USE "APPLICATION C-101) FOR SUCH PROPOSA	TFOR PERMI ALS.	B.F. HARRISON 'B'
1. Type of Well: OlL ✓ GAS WELL WELL			
2. Name of Operator	C OTTLK		8. Well No.
CHEVRON U	ISA INC		18
3. Address of Operator 15 SMITH R	D, MIDLAND, TX 79705		9. Pool Name or Wildcat TGEM; GLORIETAPADDOCK
4. Well Location			
Unit Letter D:	990 Feet From The	NORTH Line and 660	Feet From The <u>WEST</u> Line
Section 9	Township 23-SO	Range 37-EA N	MPM <u>LEA</u> COUNTY
	10. Elevation (Show whether D	F, RKB, RT,GR, etc.) GR-3319	', KB-3331'
11. Check A	ppropriate Box to Indica	te Nature of Notice, Repor	t, or Other Data
NOTICE OF INTENTION	ON TO:	l s	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PERATION PLUG AND ABANDONMENT
	•, w		
		CASING TEST AND CEME	NT JOB
PULL OR ALTER CASING OTHER: PLUGBACK OPEN HOLE 12. Describe Proposed or Completed Opproposed work) SEE RULE 1103.			dates, including estimated date of starting any
PULL OR ALTER CASING OTHER: PLUGBACK OPEN HOLE 12. Describe Proposed or Completed Opproposed work) SEE RULE 1103.	perations (Clearly state all per PLUGBACK THE OPEN HOLE OT BE USED FOR THIS PRO	OTHER: OTHER: E WITH CEMENT IN THE SUBJECTEDURE.	dates, including estimated date of starting any ECT WELL & RECOMPLETE DEEPER IN THE
PULL OR ALTER CASING OTHER: PLUGBACK OPEN HOLE 12. Describe Proposed or Completed Opproposed work) SEE RULE 1103. CHEVRON U.S.A. INC. INTENDS TO PGLORIETA/PADDOCK. A PIT WILL N THE INTENDED PROCEDURE, AND COMPLETE INTENDED PROCEDURE AND COMPLETE INTEN	perations (Clearly state all periodic perations) (Clearly state all periodic periodi	OTHER: Linent details, and give pertinent of the subject of the s	dates, including estimated date of starting any ECT WELL & RECOMPLETE DEEPER IN THE TTACHED FOR YOUR APPROVAL.
PULL OR ALTER CASING OTHER: PLUGBACK OPEN HOLE 12. Describe Proposed or Completed Opproposed work) SEE RULE 1103. CHEVRON U.S.A. INC. INTENDS TO PGLORIETA/PADDOCK. A PIT WILL N THE INTENDED PROCEDURE, AND COMPANY OF THE INTENDED PROCEDURE OF THE INTENDED PROCEDURE.	PLUGBACK THE OPEN HOLE OT BE USED FOR THIS PRO	OTHER: OTHER: E WITH CEMENT IN THE SUBJECTEDURE.	dates, including estimated date of starting any ECT WELL & RECOMPLETE DEEPER IN THE

B. F. Harrison B # 18H

Teague North Field

T23S, R37E, Section 9

WBS # UWDOL-R7001-EXP


Job: Cement Squeeze Lateral And Recomplete Deeper In Glorieta/Paddock

Procedure: (Revised 6/18/07, Plugback Open-Hole w/ Cement)

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 6/18/2007. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report.
- 3. MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. POH with rods and pump. Remove WH. Install BOP's and test as required. POH with 2 7/8" tbg string. LD TAC.
- 4. PU & GIH with 5 1/2" RBP and pkr on 2 7/8" production tbg string to 4900'. Set RBP at 4900'. Set pkr at 4890' and pressure test RBP to 1000 psi. PUH and set pkr at 3850. Pressure test csg and pkr to 500 psi.
- 5. GIH and swab fluid level down to pkr at 3850'. Wait 2 hours for fluid rise. If fluid comes into wellbore, continue swabbing and establish feed-in rate. Note: Discuss swab results with Engineering before continuing procedure.
- 6. Release pkr. LD and engage RBP at 4900'. Release RBP. POH with 2 7/8" tbg string, pkr, and RBP. LD RBP and pkr.
- 7. PU & GIH with 4 3/4" MT bit on 2 7/8" production tbg string to PBTD at 5192'. Establish reverse circulation using 8.6 PPG cut brine water. Reverse circulate well clean from 5192'. POH with 2 7/8" tbg string and bit. LD bit. GIH with open-ended 2 7/8" production tbg string to COTD at 5192'.
- 8. RU DS Services cementing equipment. Mix Class C cement at 14.8 PPG w/ 1.35 CFY. Pump down tbg and spot balanced open-hole cement plug from 5192' to 5130'. RD and release DS Services cementing equipment. POH with 2 7/8" tbg string. Shut well in and WOC overnight.

- 9. Open well and bleed off any pressure. PU and GIH with 4 3/4" MT bit on 2 7/8" tbg string to top of cement in 4 3/4" open-hole. Tag cement plug. If cement plug is tagged above 5130', drill out cement to 5130'. Reverse circulate well clean from 5130' using 8.6 PPG cut brine water. POH with 2 7/8" tbg string and bit. LD bit. Note: If cement plug is tagged below 5130', wait on swab results before adding additional cement. Also, do not exceed 350 psi casing pressure due to cement squeezed perfs fr/ 3896-3994' and 4686-4874'.
- 10. PU & GIH with 5 ½" pkr on 2 7/8" tbg string to approximately 4900'. Set pkr at 4900'. Pressure test casing and sqzd perfs to 350 psi.
- 11. Open well and swab test open-hole interval. Report oil cut, recovered fluid volumes, pressures, and/or swabbing fluid levels. Note: Discuss swab results with Engineering before continuing with procedure.
- 12. Release pkr. POH with 2 7/8" tbg string and packer. LD pkr.
- 13. PU and GIH w/ BP mud anchor jt of 2 7/8" tbg, 2 7/8" x 4' perforated sub, SN, 1 jt 2 7/8" EUE 8R J-55 IPC tbg, 4 jts 2 7/8" EUE 8R J-55 tbg, TAC, and 158 jts 2 7/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 4921', with EOT at 5116' and SN at 5079'.
- 14. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit.
- 15. Turn well over to production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.


AMH 6/18/07



harrisonb18h wb diagram xls 6/19/2007 11.33 AM

By: A. M Howell

PBTD: 5192' TVD: 5400' Updated: 6/18/2007



harrisonb18h wb diagram xls 6/19/2007 11 33 AM

By: A. M Howell

Updated: 6/18/2007