Office	ate of New Mexico inerals and Natural Resources INSERVATION DIVISION South St. Francis Dr. anta Ee, NM 87505	Form C-103 May 27, 2004				
District I Energy, IMI 1625 N. French Dr., Hobbs, NM 88240	inerals and Natural Resources	WELL API NO.				
District II		30-025-20712				
1301 W. Grand Ave, Artesia, NM 88210 OIL CON	ISERVATION DIVISION,	5. Indicate Type of Lease				
District III 1220 1000 Rio Brazos Rd., Aztec, NM 87410	South St. Francis Dr. 5	STATE FEE				
District IV Sa	anta Ee, NM 87505 2	6. State Oil & Gas Lease No.				
		A-1320				
87505 SUNDRY NOTICES AND REPO		7. Loose Name on Heit Assessment Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR	TO DEEPEN OR PLUG BACK TOWN	7. Lease Name or Unit Agreement Name				
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMI	Vacuum Glorieta East Unit Tract 1					
PROPOSALS.)	8. Well Number 10					
1. Type of Well: Oil Well Gas Well O						
2. Name of Operator	9. OGRID Number					
ConocoPhillips Company A	ATTN: Celeste Dale	217817				
3. Address of Operator	#247 Midland TV 70705 5406	10. Pool name or Wildcat				
	#247, Midland, TX 79705-5406	Vacuum Glorieta				
4. Well Location						
Unit Letter O : 330_feet from t	heSouth line and1,980	feet from theEastline				
Section 28 Tow	nship 17-S Range 35-E	NMPM County Lea				
11. Elevation (S	Show whether DR, RKB, RT, GR, etc.,					
	3,950' RKB					
Pit or Below-grade Tank Application or Closure						
Pit type_STEELDepth to GroundwaterDista	ace from nearest fresh water well Di	stance from nearest surface water_N/A				
Pit Liner Thickness: STEEL mil Below-Grade	e Tank: Volume 180 bbls;	Construction Material STEEL				
12. Check Appropriate Bo	x to Indicate Nature of Notice,	Report or Other Data				
iai oneen ippropriate Bo		report of other bata				
NOTICE OF INTENTION TO	o: SUB	SEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABA	ANDON 🔲 📗 REMEDIAL WOR	K ☐ ALTERING CASING ☐				
TEMPORARILY ABANDON CHANGE PLAN	IS 🔲 COMMENCE DRI	LLING OPNS.□ P AND A 🛛				
PULL OR ALTER CASING MULTIPLE COM	MPL ☐ CASING/CEMENT	T JOB				
OTHER:						
OTHER.	OTHER:	L_i				
		d give pertinent dates, including estimated date				
13. Describe proposed or completed operations.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion.	(Clearly state all pertinent details, and 103. For Multiple Completions: At					
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG	(Clearly state all pertinent details, and 103. For Multiple Completions: Att	tach wellbore diagram of proposed completion				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion.	(Clearly state all pertinent details, and 103. For Multiple Completions: Att	tach wellbore diagram of proposed completion				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug	(Clearly state all pertinent details, and 103. For Multiple Completions: At RAM. ging equipment. Set steel pit, SDFN	tach wellbore diagram of proposed completion				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug	(Clearly state all pertinent details, and 103. For Multiple Completions: At RAM. ging equipment. Set steel pit, SDFN	tach wellbore diagram of proposed completion				
 Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 	(Clearly state all pertinent details, and 103. For Multiple Completions: At RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla	tach wellbore diagram of proposed completion ass rods. ND wellhead, NU BOP. POOH w/				
 Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/r 	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POOH w/ rods.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032". RU ce	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POOH w/ rods.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/4" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN.	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POementer and set CIBP @ 6,032'. Circles	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POementer and set CIBP @ 6,032'. Circle, loaded hole, and pumped 25 sx C c	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'.				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 - 2,328'.	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POementer and set CIBP @ 6,032'. Circle, loaded hole, and pumped 25 sx C c POOH w/ tubing. RIH w/ wireline a	tach wellbore diagram of proposed completion ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/				
of starting any proposed or completed operations. of starting any proposed work). SEE RULE I or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POementer and set CIBP @ 6,032'. Circle, loaded hole, and pumped 25 sx C c POOH w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM	tach wellbore diagram of proposed completion ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 2¾" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2%				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. To	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POomenter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C c POOH w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and performance in the property of the complex content of the property of	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% brated casing @ 400', POOH w/ wireline. ND				
of starting any proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/ HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. T BOP and RIH w/ packer to 30'. Loaded hole, set pack	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform, and established circulation with 3	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 2¾" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. To	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform, and established circulation with 3	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% arated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor				
of starting any proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/ HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. The BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POomenter and set CIBP @ 6,032'. Circle, loaded hole, and pumped 25 sx C c POOH w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perforer, and established circulation with 3 surface. POOH w/ packer. RDMO.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23%" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% arated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until				
of starting any proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/ HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. T BOP and RIH w/ packer to 30'. Loaded hole, set pack	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POomenter and set CIBP @ 6,032'. Circle, loaded hole, and pumped 25 sx C c POOH w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perforer, and established circulation with 3 surface. POOH w/ packer. RDMO.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% arated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor				
of starting any proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/ HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. T BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marke	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOmenter and set CIBP @ 6,032". Circles, loaded hole, and pumped 25 sx C c POOH w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445". PUH and perform, and established circulation with 3 surface. POOH w/ packer. RDMO. T, backfilled cellar.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 2¾" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed.				
of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. To BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marker.	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOmenter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform and established circulation with 3 surface. POOH w/ packer. RDMO. To the property of the performance of the performanc	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 2¾" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed.				
of starting any proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/ HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. T BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marke	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOmenter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform and established circulation with 3 surface. POOH w/ packer. RDMO. To the property of the performance of the performanc	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 2¾" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed.				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE I or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 - 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 - 1,500'. WOC and POOH w/ packer. TBOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marke	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform and established circulation with 3 surface. POOH w/ packer. RDMO. Tr, backfilled cellar.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed.				
of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 2¾" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 – 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 – 1,500'. WOC and POOH w/ packer. To BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marker.	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform and established circulation with 3 surface. POOH w/ packer. RDMO. Tr, backfilled cellar.	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 2¾" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed.				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE I or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 - 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 - 1,500'. WOC and POOH w/ packer. TBOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marke	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perfect er, and established circulation with 3 surface. POOH w/ packer. RDMO. The property of the best of my knowledge to the best of my knowl	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed. cand belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan .E. (Triple N Services) DATE 06/28/07				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 - 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 - 1,500'. WOC and POOH w/ packer. The BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marker. I hereby certify that the information above is true and cograde tank has been/will be constructed or viosed according to 1 SIGNATURE	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perfect er, and established circulation with 3 surface. POOH w/ packer. RDMO. The property of the best of my knowledge to the best of my knowl	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed. cand belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan .E. (Triple N Services) DATE 06/28/07				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/ HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 - 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 - 1,500'. WOC and POOH w/ packer. T BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marke I hereby certify that the information above is true and c grade tank has been/will be constructed or losed according to 1 SIGNATURE Type or print name James F. Newman For State Use Only	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fibergla tubing to rods. POOH w/ rods. POementer and set CIBP @ 6,032'. Circle, loaded hole, and pumped 25 sx C c. POOH w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perform and established circulation with 3 surface. POOH w/ packer. RDMO. The property of the best of my knowledge with the performance of the best of my knowledge with the performance of the best of my knowledge with the performance of the best of my knowledge with the performance of the best of my knowledge with the performance of the best of my knowledge with the performance of the perfo	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% arated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed. c and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan . E. (Triple N Services) DATE 06/28/07 services.com Telephone No. 432-687-1994				
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE I or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAG 06/12/07 Tuesday MIRU Triple N rig #23 and plug 06/13/07 Wednesday Contacted NMOCD. Held sa 10 jts tubing, SDFN. 06/14/07 Thursday Held safety meeting. POOH w/HM tbg-set CIBP on 23/8" workstring to 6,032'. RU ce 6,032 - 5,662'. POOH w/ tubing to 4,413'. SDFN. 06/15/07 Friday Held safety meeting. RU cementer Loaded hole and pumped 25 sx C cmt 2,698 - 2,328'. wireline. RIH w/ packer to 1,270'. Loaded hole, set p CaCl ₂ 1,659 - 1,500'. WOC and POOH w/ packer. The BOP and RIH w/ packer to 30'. Loaded hole, set pack 400' to surface. Released packer and circulated cmt to Cut off wellhead and anchors, installed dry hole marker. I hereby certify that the information above is true and contact the start of the start	(Clearly state all pertinent details, and 103. For Multiple Completions: Att RAM. ging equipment. Set steel pit, SDFN fety meeting. POOH w/ 9 1" fiberglad tubing to rods. POOH w/ rods. POOH menter and set CIBP @ 6,032'. Circles, loaded hole, and pumped 25 sx C capooh w/ tubing. RIH w/ wireline a acker, and established rate of 2 BPM agged cmt @ 1,445'. PUH and perfect er, and established circulation with 3 surface. POOH w/ packer. RDMO. The property of the best of my knowledge to the best of my knowl	ass rods. ND wellhead, NU BOP. POOH w/ OH w/ 195 jts 23/8" production tubing. RIH w/ culated hole w/ mud, pumped 25 sx C cmt mt 4,413 – 4,043'. POOH w/ tubing to 2,698'. and perforated casing @ 1,659', POOH w/ @ 1,000 psi. Squeezed 75 sx C cmt w/ 2% orated casing @ 400', POOH w/ wireline. ND BPM @ 500 psi. Squeezed 125 sx C cmt Approved as to plugging of the Well Bor Liability under bond is retained until surface restoration is completed. cand belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan .E. (Triple N Services) DATE 06/28/07				

PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Lower 48 - Mid-Continent BU / Permian Operations

RKB@ 3950'

12-1/4" Hole

Date June 28, 2007

Max

Max

DF@ 3949' GL@

Subarea Buckeye Lease & Well No Vacuum Glorieta East Unit, Tract 01, Well 10 Legal Description 330' FSL & 1980' FEL, Sec 28, T17S, R35E New Mexico County Lea State Field Vacuum Glorieta Date Spudded Apr 15, 1964 Rig Released Apr 30, 1964 API Number 30-025-20712 Plugged 06/15/07 Status

Perf/sqz 125 sx C cmt 400' to surface

Drilled as Humble NM State K No. 21

State Lease A-1320

Lbs

Stimulation History:

	Interval	<u>Date</u>	<u>Type</u>	<u>Gals</u>	Sand	Press	<u>ISIP</u>	Rate Down
	6101-6117		Acetic Acıd	500				
	6101-6117	2/85	15% HCI	1,638				
		8/21/85	Perforate 6080-6138,	2 spf, 1	18 holes			
Top Salt @ ~1,600'	6080-6138	8/22/85	SOS Acid	6,000				
8-5/8" 24# J-55 @ 1609'	6080-6138	10/27/87	15% HCI	2,000				
Cmt'd w/850 sx, circulated		11/4/87	Perforate 6140-6158,	1 spf, 1	8 holes			
Perf/sqz 75 sx C cmt 1,659 - 1,445' TAGGED	6140-6158	11/5/87	15% Acid	1,000				

TRIPLE N
SERVICES INC MIDLAND, TX

PLUGS SET 06/12/07 - 06/15/07

- 1) Set CIBP @ 6,032', 25 sx C cmt 6,032 5,662'
- 2) 25 sx C cmt 4,413 4,043'
- 3) 25 sx C cmt 2,698 2,328'
- 4) Perf/sqz 75 sx C cmt 1,659 1,445' TAGGED
- 5) Perf/sqz 125 sx C cmt 400' to surface

Capacities 4-1/2" 9 5# csg 0.0912 ft3/ft 10 960 ft/ft3 5-1/2" 17# csg 0 1305 ft3/ft 7 661 ft/ft3 7" 20# csg 4 399 ft/ft3 0.2273 ft3/ft 7" 24# csg 4 567 ft/ft3 0 2189 ft3/ft 7-5/8" 26 4# csg 3 775 ft/ft3 0 2648 ft3/ft 8-5/8" 24# csg 0 3575 ft3/ft 2 797 ft/ft3 9-5/8" 36# csg 0 4340 ft3/ft 2 304 ft/ft3 13-3/8" 48# csg 1 134 ft/ft3 0 8817 ft3/ft 0 3382 ft3/ft 7-7/8" openhole 2 957 ft/ft3 8-3/4" openhole 2 395 ft/ft3 0 4176 ft3/ft 1 515 ft/ft3 0 66 ft3/ft 11" openhole

TOC 4-1/2" Csg @ 2636' (T.S.)

Base of Salt @ ~2,700' 25 sx C cmt 2,698 - 2,328'

25 sx C cmt 4.413 - 4.043'

Set CIBP @ 6,032', 25 sx C cmt 6,032 - 5,662'

Formation Tops: <u>Glorieta</u> 6080-6138 Tansıll 6101 6104 6106 Top Salt 6108 6110 6115 Yates Seven Rivers 6116 6117 Base Salt 6140-6158 Queen Grayburg 7-7/8" Hole San Andres 4-1/2" 9 5# & 11 6# J-55 @ 6230' Glorieta Cmt'd w/800 sx Paddock TOC @ 2636' (T S)

6211' TD 6230' Prepared by Triple N Services Inc. VGEU #01-10 WBDs xls

F

PBTD