Submit 3 Copies To Appropriate District Office Energy, Minerals and	New Mexico		Form C-103 May 27, 2004
District I 1625 N French Dr, Hobbs, NM46/240	a i vatarai ressources	WELL API	NO.
District II 1301 W. Grand Ave., Artesia, NM8821000 OIL CONSERVATION DIVISION			0-025-29586
District III 1220 South	St. Francis Dr.	STAT	Type of Lease TE □ FEE X
District IV	, NM 87505		& Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM 87505		o. State Oil	& Gas Lease No.
SUNDRY NOTICES AND REPORTS O (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOF PROPOSALS.)	EEPENOR PLUGBACK TO A		me or Unit Agreement Name: nument South Unit
1. Type of Well: Oil Well Gas Well Other Inject ion	222	8. Well Nur	nber 328 WIW
2. Name of Operator	3 1001 g g g g g g g	9. OGRID N	Jumber
XTO Energy, Inc.	THE THE	10 P1	005380
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701	a octo-Arrivo		me or Wildcat nument: Grayburg-San Andres
4. Well Location			
Unit Letter J: 2080' feet from the		1880' fe	eet from the <u>East</u> line
	21S Range 36E	NMPM	County Lea
11. Elevation (Show w	whether DR, RKB, RT, GR,	etc.)	
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank:	Volumebbls; Construc	tion Material	
12. Check Appropriate Box to In NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUI	SEQUENT	Other Data REPORT OF: ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRIL	_ING OPNS. [PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST ANI CEMENT JOB) [
OTHER:	OTHER: Tempora	ry Abandon	X
OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Nor recompletion.	te all pertinent details, and gi	ve pertinent dat	es, including estimated date
 Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOHw/CIBP to 524'. Tagged. POOH w/setting 	te all pertinent details, and gi Multiple Completions: Attac H w/117 jts of 4.7#, Jog tool.	ve pertinent dat ch wellbore diag 55, EUE, 8rd	es, including estimated date gram of proposed completion IPC tbg & pkr. RIH
 Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Nor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOR 	te all pertinent details, and gi Multiple Completions: Attac H w/117 jts of 4.7#, July 19 tool. 15 on 9 jts of 2-7/8" N80	ve pertinent dat th wellbore diag 55, EUE, 8rd	es, including estimated date gram of proposed completion IPC tbg & pkr. RIH P @ 524'. RU power swivel
 Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOH w/CIBP to 524'. Tagged. POOH w/setting 6-12-07 PU 4-3/4" bit, bit sub & 8 -3-1/2" DC 	te all pertinent details, and gind Multiple Completions: Attached W/117 jts of 4.7#, June 19 jts of 2-7/8" N80 of 9 jts of 2-7/8" N80 of 2-7/8	ve pertinent dat ch wellbore diag 55, EUE, 8rd WS. Tag CIB O CIBP. RD s O WS & LD 8 & rotate mi 4-3/4" bit o	es, including estimated date gram of proposed completion I IPC tbg & pkr. RIH P @ 524'. RU power swivel wivel. Push CIBP t/3770'. 3-1/2" DC. RIH w/4-3/4" 11 fr 507' to 570'. P00H
13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOH w/CIBP to 524'. Tagged. POOH w/setting 6-12-07 PU 4-3/4" bit, bit sub & 8 -3-1/2" DC & stripper hd. Pmp 10 bbls of fresh wt 6-13-07 Cont RIH pushing CIBP to 3,926'. POOH btm hole taper mill on 14 jts of 2-7/8 w/14 jts of 2-7/8" tbg. LD mill. RIH w WS to 3,780'. POOH w/121 jts of 2-7/8'.	te all pertinent details, and gi Multiple Completions: Attac Multiple Completions: Attac Multiple Completions: Attac Multiple Completions: Attac g tool. To n 9 jts of 2-7/8" N80 Multiple Completions: It will be stablish circ. It will multiple Multiple Completions Multiple Completions: Multiple Completions Multiple Completions: Multiple Completions Multiple Completions: Attac Multiple Complet	ve pertinent dat sh wellbore diag 55. EUE, 8rd WS. Tag CIB O CIBP. RD s O WS & LD 8 & rotate mi 4-3/4" bit o bit. ge and belief. I	es, including estimated date gram of proposed completion IPC tbg & pkr. RIH P @ 524'. RU power swivel wivel. Push CIBP t/3770'. 3-1/2" DC. RIH w/4-3/4" 11 fr 507' to 570'. P00H in 121 jts of 2-7/8" N80 further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Nor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOH w/CIBP to 524'. Tagged. POOH w/setting 6-12-07 PU 4-3/4" bit, bit sub & 8 -3-1/2" DC & stripper hd. Pmp 10 bbls of fresh wt 6-13-07 Cont RIH pushing CIBP to 3,926'. POOH btm hole taper mill on 14 jts of 2-7/8 w/14 jts of 2-7/8" tbg. LD mill. RIH w	te all pertinent details, and gi Multiple Completions: Attac Multiple Completions: Attac Multiple Completions: Attac Multiple Completions: Attac g tool. To n 9 jts of 2-7/8" N80 Multiple Completions: It will be stablish circ. It will multiple Multiple Completions Multiple Completions: Multiple Completions Multiple Completions: Multiple Completions Multiple Completions: Attac Multiple Complet	ve pertinent dat sh wellbore diag 55. EUE, 8rd WS. Tag CIB O CIBP. RD s O WS & LD 8 & rotate mi 4-3/4" bit o bit. ge and belief. I	es, including estimated date gram of proposed completion IPC tbg & pkr. RIH P @ 524'. RU power swivel wivel. Push CIBP t/3770'. 3-1/2" DC. RIH w/4-3/4" 11 fr 507' to 570'. P00H in 121 jts of 2-7/8" N80 further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOH w/CIBP to 524'. Tagged. POOH w/setting 6-12-07 PU 4-3/4" bit, bit sub & 8 -3-1/2" DC & stripper hd. Pmp 10 bbls of fresh wt 6-13-07 Cont RIH pushing CIBP to 3,926'. POOH btm hole taper mill on 14 jts of 2-7/8 w/14 jts of 2-7/8" tbg. LD mill. RIH w WS to 3,780'. POOH w/121 jts of 2-7/8'.	te all pertinent details, and gimultiple Completions: Attach Multiple Comp	ve pertinent date wellbore diagnostic by well	es, including estimated date gram of proposed completion IPC tbg & pkr. RIH P @ 524'. RU power swivel wivel. Push CIBP t/3770'. 3-1/2" DC. RIH w/4-3/4" 11 fr 507' to 570'. P00H on 121 jts of 2-7/8" N80 further certify that any pit or belowed) alternative OCD-approved plan DATE 07/27/07
13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Nor recompletion. 6-9-07 MIRU PU. ND WH & NU BOP. Rel pkr. POOH w/CIBP to 524'. Tagged. POOH w/setting 6-12-07 PU 4-3/4" bit, bit sub & 8 -3-1/2" DC & stripper hd. Pmp 10 bbls of fresh wt 6-13-07 Cont RIH pushing CIBP to 3.926'. POOH btm hole taper mill on 14 jts of 2-7/8 w/14 jts of 2-7/8" tbg. LD mill. RIH w WS to 3.780'. POOH w/121 jts of 2-7/8' I hereby certify that the information above is true and complete grade tank has been/yill be constructed or closed according to NMOCD g	te all pertinent details, and gimultiple Completions: Attach Multiple Comp	ve pertinent date wellbore diagnostic by well	es, including estimated date gram of proposed completion IPC tbg & pkr. RIH P @ 524'. RU power swivel wivel. Push CIBP t/3770'. 3-1/2" DC. RIH w/4-3/4" 11 fr 507' to 570'. P00H n 121 jts of 2-7/8" N80 further certify that any pit or belowed) alternative OCD-approved plan

APPROVED BY Conditions of Approval, if any:

This Approval of Temporary
Abandonment Expires


Eunice Monument South Unit #328 WIW Temporary Abandon Page 2 – Cont'd.

6/13/07 RIH w/5-1/2" CIBP & collar locator on 120 jts of 2-7/8" N80 WS. Set CIBP @ 3,754'. RU pmp & circ well. Test CIBP to 550 psig. Held ok.

6/14/07 RU pmp trk. Circ 100 bbls of pkr fluid. Tst csg to 590 psig for 30". Held ok. POOH LD 120 jts of 2-7/8" N80 WS. RIH w/121 jts of 2-3/8" J-55, IPC tbg. POOH LD 121 jts of IPC tbg. ND BOP. NU WH. RDMO PU. Well is TA'd.

This well is uneconomical for injection and it is recommended to TA the well until further evaluation. There are no offset producing wells to this injection well.

MIT Chart Attached.



then Miles - + 70

EUNILE MONUMENT SWITH UNIT #328

CHEST CHINNARD

THE CHINNARD

JULIAN SED SIISIOT

CHINNARD

THOUGH O AST

CHINNARD

THOUGH O AST

CHINNARD

SIISIOT

CHINNARD

CH