Exhibit A Kaiser-Francis Oil Co. South Bell Lake Unit #26 Sec 6-24S-34E Lea County, NM

a 14 4

Drilling Summary and Casing Program

- 1) Drilling Contactor
- Grey Wolf Rig #76 See attached specifications and BOP diagram.
- 2) Estimated Formation Tops

Delaware -5150'Bone Springs -8600'Wolfcamp Shale -11850'Strawn -12090'Atoka -12430' 1^{st} Morrow -13100' 4^{th} Morrow -13430'TD -13900'

3) <u>Water String</u>

Set conductor Drill 20" hole to 750' Set 16" 84# casing @ 750' w/ one centralizer every third joint. Circulate cement to surface w/ 380 sks lead and 390 sks tail cement. Wait on cement 12 hrs.

4) Surface Casing

Drill 14-3/4" hole to 5050' Set 10-3/4" 51# L-80 @ 5050' w/ one centralizer every other joint for the first 30 joints. Circulate cement to surface w/ 1180 sks lead (Interfill C 11 5 ppg) and 200 sks tail (Premium Plus 14.8 ppg) Wait on cement 12 hrs NU BOP

5) Intermediate Casing

Drill out shoe and test to10 ppg equivalent mud weight. Drill 9-1/2" hole to 11900' (or just in the top of the Wolfcamp Shale) Max mud weight expected is 9.2 ppg. Run open hole logs. Set 7-5/8" 39# P-110 @ 11900' DV tool set @ approximately 8000' depending on hole conditions. Run centralizers every third joint on bottom 500' and across any zones of interest as determined by log analysis

Cement 1st stage w/ 280 sks lead (Interfill H 11.9 ppg) and 150 sks tail (Premium 15.6 ppg) Cement second stage w/ 230 sks (Interfill H 11.5 ppg) Estimated cement top @ 4128'.

6) <u>Liner</u>

Wait on cement 12 hrs Drill out 7-5/8" shoe and test to a 12.5 ppg equivalent mud weight. Drill 6-1/2" hole to 13400' or 30' above the 4th Morrow Sand. Run open hole logs. Set 5-1/2" 17# P-110 ULT FJ liner @ 13400', liner top @ 11700', set with liner top packer and hanger. Cement liner w/ 125 sks Super H cement (13 0 ppg), set liner top packer Drill out cement down to liner top. Rig down and move off drilling rig.

- 7) Rig up completion rig. NU BOPs. Drill out 5-1/2" casing shoe w/ 4-1/2" bit to a total estimated depth of 13700' utilizing power swivel, snubbing unit, 2-7/8 drill pipe, down hole motor and nitrogen foam.
- 8) The well will be completed by setting a Baker WL packer w/ double glass disk in place at 13300' in the 5-1/2" liner. Wellhead pressure will be released, 2-3/8" tubing will be ran in the hole and latched to the packer with an on/off tool. This will be an open hole completion below the packer.



Grey Wolf Rig #76 BOP Stack

