Office	Copies To Appropriate District State of New Mexico Energy, Minerals and Natural Resources		s	Form C-103 May 27, 2004						
	Dr., Hobbs, NM 88240	Lifergy, winicials	unu i jatu		WELL AP	I NO.				
District II 1301 W Grand A	Internet II OIL CONSERVATION DIVISION		30-025-01	Type of Lease						
District III 1000 Rio Brazos	Istrict III 1220 South St. Francis Dr.				STATE STATE					
District IV		Santa Fe	e, NM 87	7505		l & Gas Lease No.				
1220 S St. Franc 87505	is Dr , Santa Fe, NM				B-2148					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						ame or Unit Agreement Name Ialjamar Unit				
PROPOSALS.)	ell: Oil Well	Gas Well 🗌 Other T	;		93	linder				
2. Name of O			· 		9. OGRID	Number				
Forest Oil Con										
3. Address of	Operator					ame or Wildcat				
707 17 th Stree	t, Suite 3600, Denver	, Colorado			Maljamar (GBR-SA				
4. Well Locat										
Unit	Letter: <u>L</u> feet	t from 1980 line and	d <u>Sout</u>	hfeet and _	660 from the	<u>West</u> line				
Sectio		Township 17S	Range		NMPM	County Lea				
		11. Elevation <i>(Show wh</i> 4150' G		, RKB, RT, GR	, etc.)	and the second				
Pit or Below-grad	e Tank Application 🗌 o									
Pit type	Depth to Groundwa	aterDistance from nea	rest fresh w	ater well	Distance from near	est surface water				
Pit Liner Thickne		Below-Grade Tank: Vol								
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 25202728 29										
	12 Check A					Other Data 2520272820				
		Appropriate Box to Inc		ature of Not	tice, Report or (Other Data 2526272829				
	NOTICE OF IN	Appropriate Box to Ind TENTION TO:	dicate N	ature of Not	tice, Report or (SUBSEQUEN ⁻	Dther Data 2526272829				
PERFORM RE		Appropriate Box to Ind TENTION TO: PLUG AND ABANDON	dicate N	ature of Not	tice, Report or (SUBSEQUEN ⁻ WORK	Dther Data 2526272829				
PERFORM RE	NOTICE OF IN EMEDIAL WORK Y ABANDON	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS	dicate N	ature of Not	tice, Report or (SUBSEQUEN [®] WORK E DRILLING OPNS	Dther Data 2526272829				
PERFORM RE	NOTICE OF IN EMEDIAL WORK Y ABANDON	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON	dicate N	ature of Not	tice, Report or (SUBSEQUEN [®] WORK E DRILLING OPNS	Dther Data 2526272829				
PERFORM RE	NOTICE OF IN EMEDIAL WORK Y ABANDON	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE	tice, Report or (SUBSEQUEN [®] WORK E DRILLING OPNS	Dther Data 2526272829				
PERFORM RE TEMPORARIL PULL OR ALT OTHER:	NOTICE OF IN EMEDIAL WORK Y ABANDON ER CASING	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C	tice, Report or (SUBSEQUEN [™] WORK E DRILLING OPNS MENT JOB Casing Repair⊠	Dther Data 2526272829 T REPORT OF: Div ALTERING CASING D. No PAND ACTIVE OF Hobbs CD				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril	NOTICE OF IN EMEDIAL WORK Y ABANDON ER CASING be proposed or compl	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C	tice, Report or (SUBSEQUEN [™] WORK E DRILLING OPNS MENT JOB Casing Repair⊠ s, and give pertine	Dther Data 2526272839 T REPORT OF: Div ALTERING CASING D. N P AND A Cived No Hobbs CD S. D. Hobbs CD S. D. Hob				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start	NOTICE OF IN EMEDIAL WORK Y ABANDON ER CASING be proposed or compl	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C	tice, Report or (SUBSEQUEN [™] WORK E DRILLING OPNS MENT JOB Casing Repair⊠ s, and give pertine	Dther Data 2526272829 T REPORT OF: Div ALTERING CASING D. No PAND ACTIVE OF Hobbs CD				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco	NOTICE OF IN MEDIAL WORK Y ABANDON ER CASING be proposed or completion.	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. Fo	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C	tice, Report or (SUBSEQUEN [™] WORK E DRILLING OPNS MENT JOB Casing Repair⊠ s, and give pertine	Dther Data 2526272839 T REPORT OF: Div ALTERING CASING D. N P AND A Cived No Hobbs CD S. D. Hobbs CD S. D. Hob				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07	NOTICE OF IN EMEDIAL WORK Y ABANDON ER CASING be proposed or compli- ting any proposed wo impletion. RU PU, chage 2-7/	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. Fo 8 slips to 2-3/8.	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C Dertinent detail le Completions	tice, Report or (SUBSEQUEN WORK DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore	Other Data PANDACING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CONDUCTION Nobbs				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07 9-13-07	NOTICE OF IN EMEDIAL WORK Y ABANDON ER CASING be proposed or compling any proposed wo mpletion. RU PU, chage 2-7/ ND WH had to cal	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. For 8 slips to 2-3/8. I welder to weld ear on do	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C Dertinent detail le Completions	tice, Report or (SUBSEQUEN WORK E DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore	Other Data TREPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CONTRACT AND ALTERING CASING				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07	NOTICE OF IN EMEDIAL WORK Y ABANDON ER CASING be proposed or compli- ting any proposed wo impletion. RU PU, chage 2-7/ ND WH had to call RU pmp truck test	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. For 8 slips to 2-3/8. I welder to weld ear on do RBP from 3900' to 3872'	dicate N	ature of Not REMEDIAL V COMMENCE CASING/CE OTHER: C Dertinent detail le Completions	tice, Report or (SUBSEQUEN WORK E DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore mose it. Set RBP @ om 916' to surface	Dther Data TREPORT OF: ALTERING CASING A Hobbs OCD ALTERING CASING A Hobbs ALTERING A HOBBS H				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07 9-13-07 9-14-07	NOTICE OF IN EMEDIAL WORK ABANDON ER CASING be proposed or complising any proposed wo ompletion. RU PU, chage 2-7/ ND WH had to call RU pmp truck test tested ok, leak from surface well head e	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. For 8 slips to 2-3/8. I welder to weld ear on do RBP from 3900' to 3872' n 916' to 947' pump in cs at out.	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C Dertinent detail le Completions heat WH to lo , ok test cgs fr @200# cir up a	tice, Report or (SUBSEQUEN WORK E DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore oose it. Set RBP @ om 916' to surface uround cgs, did out	Other Data TREPORT OF: ALTERING CASING N PANDACIVED Nobbs OCD State ALTERING CASING Nobbs OCD State State St				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07 9-13-07 9-14-07 9-17-07	NOTICE OF IN MEDIAL WORK Y ABANDON ER CASING be proposed or compli- ting any proposed wo mpletion. RU PU, chage 2-7/ ND WH had to call RU pmp truck test tested ok, leak from surface well head e Open well up, unse	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. Fo 8 slips to 2-3/8. I welder to weld ear on do RBP from 3900' to 3872' n 916' to 947' pump in cs at out. at arrow set pkr, POH 29	dicate N	ature of Not REMEDIAL COMMENCE CASING/CE OTHER: C Dertinent detail le Completions heat WH to lo , ok test cgs fr @200# cir up a down arrow se	tice, Report or (SUBSEQUEN WORK E DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore on 916' to surface uround cgs, did out	Other Data TREPORT OF: ALTERING CASING NOT ALTERING CASING NOT ALTERNATION NOT ALTERNAT				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07 9-13-07 9-14-07	NOTICE OF IN EMEDIAL WORK PABANDON ER CASING be proposed or completing any proposed wo empletion. RU PU, chage 2-7/ ND WH had to call RU pmp truck test tested ok, leak from surface well head e Open well up, unse ND BOP NU 6"-60 calcium chloride, ra	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. For 8 slips to 2-3/8. 1 welder to weld ear on do RBP from 3900' to 3872' n 916' to 947' pump in csi at out. at arrow set pkr, POH 29 00 flange, install 5-1/2" ce	dicate N	ature of Not REMEDIAL V COMMENCE CASING/CE OTHER: C Dertinent detail le Completions heat WH to lo , ok test cgs fr @200# cir up a down arrow se d on flange, st	tice, Report or (SUBSEQUEN WORK E DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore om 916' to surface round cgs, did out et pkr, close well in art pumping cemen	Other Data TREPORT OF: ALTERING CASING N PANDACIVED Nobbs OCD State ALTERING CASING Nobbs OCD State State St				
PERFORM RE TEMPORARIL PULL OR ALT OTHER: 13. Descril of start or reco 9-12-07 9-13-07 9-14-07 9-17-07	NOTICE OF IN MEDIAL WORK Y ABANDON ER CASING be proposed or completion RU PU, chage 2-7/ ND WH had to call RU pmp truck test tested ok, leak from surface well head e Open well up, unse ND BOP NU 6"-60	Appropriate Box to Ind TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly rk). SEE RULE 1103. For 8 slips to 2-3/8. 1 welder to weld ear on do RBP from 3900' to 3872' n 916' to 947' pump in csi at out. at arrow set pkr, POH 29 00 flange, install 5-1/2" ce	dicate N	ature of Not REMEDIAL V COMMENCE CASING/CE OTHER: C Dertinent detail le Completions heat WH to lo , ok test cgs fr @200# cir up a down arrow se d on flange, st	tice, Report or (SUBSEQUEN WORK E DRILLING OPNS MENT JOB Casing Repair s, and give pertine s: Attach wellbore om 916' to surface round cgs, did out et pkr, close well in art pumping cemen	Other Data TREPORT OF: ALTERING CASING NO ALTERING CASING NO PAND A CONCOL Nobbs OCD Second Second Concerns Nobbs OCD Second Second Concerns Second Concerns Nobbs OCD Second Concerns Second Concerns Nobbs OCD Second Concerns Second Concerns				

Cont'd on next page

÷

I hereby certify that the information above	is true and complete to the best of my knowleds	ge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or closed a	ccording to NMOCD guidelines 🖾, a general permit 🗋	or an (attached) alternative OCD-approved plan 🔲.
SIGNATURE indut	TITLE Sr. Regulatory Tech	DATE 9-31-07
Type or print name Cindy Bush	E-mail address: cabush@forestoil.com	Telephone No. 303-812-1554
APPROVED BY: Nauf WWW Conditions of Approval (if any):	OC FIELD REPRESENTATIV	E II/STAFF MANAGIDATE OCT 2 2 2007
Conditions of Approval (if any):		

Caprock Maljamar Unit #93 Page 2 Casing Repair

9-19-07 ND cement head NU BOP, pick up 6 drill collars w/4-3/4" bit NU stripper head, vacuum truck fill reverse pit w/100 bbls wtr. RIH 22 jts tag cement @ 885' started drilling & circulation fell out @ 960' run 2 jts to 1035' & test csg, 500# loss 55# in 30 min. Press again 300# loss 10# in 30 min, POH 26 jts & lay down 6 drill collars 3-1/2 RD reverse unit

9-20-07 NU pmp trk press csg 300# for 30 min. loss 6# release press. RBIH 122 jts 2-7/8" tbg, pick up from pipe rack, tag @3860' circulate sand w/45 bbls. Add 1jt & 10' sub tag @3900 circulate 60 bbls wtr clean sand out. Lach RBP open equalize valve, try to'unseat, but high press would set tit back, tied csg to flow line & left it bleeding.

9-21-07 Release RBP, POH 122 jts 2-7/8 tbg, LD pick up AD-1 pkr, RBIH 125 jts 2-3/8 ipc tbg, set pkr @ 3900 @3898@3902& 3871 press csg to 300# loss 20# in 5 min. POH tbg.

9-24-07 Change BOP RU tbg tester test tbg BIH 125 jts 2 3/8 ipc tbg replace 13 jts plastic coding was lost, small piece hanging testing tools, set pkr @3990' lost 30# in 10 min. Set in two different places & lost press the same, release pkr, set @3900, hook tbg to flow line.