Submit 3 Copies To Appropriate District Office District I	ffice State of New Mexico istrict I Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				<u>30-025-63000</u> 0307/4 5. Indicate Type of Lease		
1000 Rio Brazos Rd. Aztec. NM 87410					FEE	
District IV Santa Fe, NM 87505				6. State Oil & Gas Lease No. E-3140		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other				 Lease Name or Unit Agreement Name: Vacuum Abo Unit 		
2. Name of Operator ConocoPhillips Co.				8. Well No.		
3. Address of Operator				Btry. 2, Tr. 13, #19 9. Pool name or Wildcat		
4001 Penbrook, Odessa, TX 79762				Vacuum Abo Reef		
4. Well Location						
Unit Letter P : 9	990_feet from theSouth	h lir	ne and 990	feet from the	eEast	line
Section 5		185	Range 35E	NMPM	Lea County	,
	10. Elevation (Show w 3,958' C	GL				
11. Check	Appropriate Box to In	dicate Na	ature of Notice, I	Report or Other	Data	
	ITENTION TO:	-		SEQUENT RE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	3 🗌
	CHANGE PLANS		COMMENCE DRIL		PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D 🗌		
OTHER:			OTHER:			
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated de of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 						
See attached procedure &	THE COMMISSION HOURS PRIOR TO PLUGGING OPERA TO BE APPROVED.	, the bec tions fc	GINNING OF DR THE C-10 3	37	456789 ποσρ το το το το το το το το το το	1774R71
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE		TITLE	Engineer		_DATE10/10/03_	
Type or print name James F. New	man, P.E. Triple N Se	rvices, Inc	•	Tele	phone No. 432-687	-1994
(This space for State use)						
APPPROVED BY						

'n

ConocoPhillips

Proposed Plugging Procedure Page 1 of 2

Vacuum Abo Unit #13-19 Vacuum Abo Reef Field Section 5, T18S, R35E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

SI injector - Loc-Set packer w/ on/off tool and profile nipple @ 8,602', tubing in hole

- Notify BLM & OCD 24 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- 1. Set steel pit and flow well down as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP. Release loc-set packer and POOH standing back tubing.
- 3. RIH w/ tbg-set CIBP on injection tubing to 8,613'. RU cementer and set CIBP. Circulate hole w/ mud and pump 25 sx C cmt on CIBP 8,613 8,500'. Abo plug
- 4. POOH w/ tbg to 6,329' and pump 25 sx C cmt 6,329 6,229'. Glorieta plug
- 5. POOH w/ tbg to 4,395' and pump 25 sx C cmt 4,395 4,295'. Grayburg plug
- 6. RIH w/ wireline and cut 5½" casing @ 3,000', POOH w/ wireline. ND wellhead and RU csg tools, POOH w/ 5½" casing.
- 7. RIH w/ tbg to 3,050' and pump 40 sx C cmt w/ 2% CaCl₂ @ 3,050'. WOC and tag this plug. Casing stub and base of salt plug
- 8. POOH w/ tbg to 1,598' and pump 35 sx C cmt 1,598 1,498'. Top of salt plug
- 9. RIH w/ wireline and perforate casing @ 363'. POOH w/ wireline.
- **10.** RIH w/ 8-5/8" AD-1 packer to 180'. RU cementer and load hole w/ mud, set packer. Establish rate into perforations and squeeze 115 sx C cmt w/ 2% CaCl₂ 363 - 263'. WOC and tag this plug. **surface casing shoe plug**
- 11. RIH w/ wireline and perforate 8-5/8" casing @ 60'. POOH w/ wireline.
- **12.** ND BOP and NU wellhead. Establish circulation and 20 sx C cmt 60' to surface. **surface plug**



ConocoPhillips

Proposed Plugging Procedure Page 2 of 2

Vacuum Abo Unit #13-19 Vacuum Abo Reef Field Section 5, T18S, R35E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

13. SI well. RDMO. Clean steel pit and dispose of bottoms.

14. Cut off wellhead and anchors, level location. Leave location clean and free of trash.



