		`		
Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natu	ral Resources		May 27, 2004
1625 N French Dr , Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 1301 W. Grand Ave , Artesia, NM 88210	OIL CONSERVATION		30-025-37355 5. Indicate Type of Lease	
District III	1220 South St. Fran	ncis Dr.		TEE T
1000 R10 Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	5. State Oil & Gas Lease N	
1220 S. St. Francis Dr , Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Ag	reamont Nama
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			. Lease Name of Omit Ag	reement mame
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			New Mexico M State	-
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 51	~
2. Name of Operator			9. OGRID Number	
Range Operating New Mexico, Inc.			227588	-
3. Address of Operator			0. Pool name or Wildcat	
100 Throckmorton Street, Suite	∋ 1200, Fort Worth, TX 76102	E	Blinebry Oil & Gas	-
4. Well Location				
Unit Letter	: 2310 feet from the South	line and 99	00 feet from the	East line
Section 18	Township 22S Ra		NMPM Lea County	
111111	11. Elevation (Show whether DR,			2528 30 A
Pit or Below-grade Tank Application	or Closure			
Pit type Depth to Groundy	waterDistance from nearest fresh w	vater well Distan	ce from nearest surface water	
Pit Liner Thickness: mil			truction Material	<u>- 2001 - 500</u>
				Receiver Receiver
12. Check	Appropriate Box to Indicate N	ature of Notice, Re	eport or Other Data	Recent
	NTENTION TO:	SUBS		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS			ING OPNS. PAND	4919141812
PULL OR ALTER CASING		CASING/CEMENT J	ов 🗍	-319670
				1
OTHER:		OTHER:	· · · · · · · · · · · · ·	
	pleted operations. (Clearly state all pork). SEE RULE 1103. For Multip			
or recompletion.	ork). SEE ROLE 1105. For Multip	le completions. Attac	in wendore diagram of pro	posed completion
or recompletion.				
	& kill well. Finish POOH w/tbg and cc w/production string (rods). Hang wel			
running (auto).				
12/17/07 Bled well down. RU-KT, pump 50 bbl down casing. RU-PU, ND-WH, NU-BOP, RU-Spooler. POOH. LD equip. All checked good Elect. Sent in to SOS to be tested. RD spooler, RIH w/CIBP. Set @ 5390'. POOH W/WL. Test plug w/KT (Good). RIH w/perf				
gun and perf squeeze ho	bles @2405' 4-SPG, 90 phasing, 0.5	entry holes. SWI	WWL. Test plug wirth (Go	bu). Kin wipen
12/18/07 RU-KT, est pump in rate.	. Pump 16 bbl down casing. Casing I	oaded up. Pressured ι		
of 195 bbl to circ up surface valve. Well started to circ after 2:30 min @ 3-BPM on 1700 psi. (good returns) Call in report. RIH w/cmt retainer and set @ 2331'. (Total of 70 jts) Tested tbg. Tested casing and cmt retainer. All good. Sting into retainer and				
w/cmt retainer and set a	2331. (10tal of 70 jts) Tested tog. 10 bbl lime 2.5 bpm 450 psi, 5 bbl fw	ested casing and cmt	retainer. All good. Sting in	to retainer and
bpm 500 psi (20 bbl spac	cer instead of 5). Start lead cmt, 400	sks C Star Lite. 2% Ca	aCl, 2% C-45. 3# Sar Seal	, 20 001 W 2.5 , 7/10% C-41P
(13/1.89/10.74). 25 bbl g	one 2.5 bpm 400 psi, 50 bbl gone 2.5	5 bpm 250 psi, 75 bbl g	gone 3 bpm 350 psi, 100 b	bl gone 3 bpm
450 psi, 125 bbl gone 2.5	5 bpm 450 psi, 134.5 bbl gone 2.1 bp	om 450 psi, start tail ce	ment, 100 Sks Class C, 29	% ČaCl, 7/10% C-
41 (14.8/1.32/6.3), 15 bl	bl gone 2.1 bpm 450 psi, 23.5 bbl goi	ne 2.1 bpm 300 psi. St	art displacement. 10 bbls (Jone 2 bpm 500
psi, 12.5 bbi gone 1 bpm psi. RU packer, POOH w	600 psi, (returns start to turn gray an //tbg. SWI (See Page 2)	nd thickening) SD and	puil 3 stands. Reverse out	20 DDI 2 DPM 300
	/lbg. 0001 (======)= =,			
I hereby certify that the information grade tank has been/will be constructed or	above is true and complete to the be r closed according to NMOCD guidelines [est of my knowledge a], a general permit □ or :	nd belief. I further certify th an (attached) alternative OCD	at any pit or below- -approved plan .
signature Kinda	A) ~	Regulatory Analyst	DATE12/	
Type or print name Linda L. Bro For State Use Only	own E-mail address: lbrown	n@rangeresoureces.co	m Telephone No. (817)	865 ANS 0 3 24
	Williams TIFLE'ST	RICT SUPERVISOR/C	SENERAL MANAGER DATE	

APPROVED BY:	Chus	Williams
Conditions of Approva	l (if any):	

.

Page 2 – New Mexico M State #51 API No. 30-025-37355

- 12/19/07 Open well up. No pressure. RIH w/bit, 8 collars and tbg. Tag @ 2331' on cement retainer. Did not tag any cement on top of retainer. RU-reverse unit, broke circulation. Good returns. Drill out retainer and 1' of cement. Cement returns are very soft. Circulate clean. RD-reverse unit. POOH w/tbg and collars Surface pressure 600 PSI. SWI
- 12/20/07 Open well. No pressure on casing or surface. RU-power swivel. Drill out rest of cement down to 2470', below entry holes and tested casing to 500 psi, POOH w/tbg and collars. RD-power swivel. RU-WL, Run cement log from 230' 2470'. RD-WL. All good. Call Sylvia (OCD), verbally OK'd braidenhead test. SWI
- 12/21/07 Check well pressures. No pressure on casing or surface. PU new bit. RIH w/bit collars and tbg. Tag @ 5326', RU-Reverse rig. Circ well, all good. Drill on CIBP, drill 3', fell out. Lost circ. Pump total 160 bbl water. Never caught circ. Call in report. RD reverse rig. RIH w/tbg and tag @ 6134'. (ESP pump in the hole) Good. POOH w/tbg. SWI
- 12/22/07 SI Due to high winds
- 12/23/07 SI Due to high winds
- 12/24/07 RU-KT, Pmp 35 bbls down casing. Assemble SOS Equip. RU Spooler. RIH W/ Production String Tbg. (SOS). Landed Tbg. RD-Spooler, ND-BOP, NU-WH, and RD-KT. Ran equip: (3) Pmp; SD-1200/ 25 Stages, D-13/ 114 Stages and SD450/ 172 stages. (1) RGS, (2) Seals; 66L - 66L, (1) Mtr; 50HP/ 1390 Volts/ 23 Amps. Initial Psi- 1041, Start-up and Monitor. <u>NOTE</u>: Well isn't Surfacing Fluid. Call in report. Chris Garcia. Visit w/ pumper. Didn't Rig PU Dn. SWI
- 12/25/07 Turn well on & try to surface fluid. Well acts like there is a HIT. Left well down
- 12/26/07 Tried to surface Fluid again (SOS Tech and I) RU-KT. Drop a stand-in valve and test tbg. Tubing won't test w/55 bbl pump down tubing. ND-WH, NU-BOP, RU-Spooler. POOH w/tbg and SOS equip. Pull up to the HIT (found on 53rd jt). LD and mark Jt. RIH w/SOS-Equip and Tbg. Test to 2500 psi (good). RD Spooler, RIH w/fishing tool. Caught Stand in valve. POOH w/fish. RD-KT, ND-BOP, NU-WH. Start up and monitor. RD-PU. All good. Well back on production.