Submit 3 Copies To Appropriate District  Office  State of New Mexico	Form C-103
<u>District 1</u> Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO. 30-025-04731
1625 N French Dr., Hobbs, NM 88240 District II	WELL AFT NO. 30-023-04731
1301 W Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd, Aztec, NM 87410	STATE S FEE
District IV Santa Fe, NW 87303	6. State Oil & Gas Lease No. A1350
1220 S St Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Devonian State
PROPOSALS)	8. Well Number 4
1. Type of Well: Oil Well Gas Well Other	9. OGRID Number
2. Name of Operator Citation Oil & Gas Corp.	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 690688, Houston, Texas 77269-0688	Eumont Yates Seven Rivers Queen
4. Well Location	
Unit Letter H: 1980 feet from the North line and	660feet from theEastline
Section 20 Township 21S Range *36E	NMPM Lea County
11. Elevation (Show whether DR, RKB=RI-GR-etc. 3610' GR, 3616' GR	
3610' GR, 3616' GR  Pit or Below-grade Tank Application □ or Closure □	
/ N/	taue from nearest surface water
	onstruction Material
Pit Liner Thickness: mil Below-Grade Tank: Volume N S Nature of State of St	onstruction Material
\\\\\\\\\\	* - 1
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK  TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE OR	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WOR	ALTERING CASING
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DR	ILLING OPNS. T P AND A T
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	т јов 🔲
PULL OR ALTER CASING	т јов
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:	T JOB
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  Augustian of starting any proposed work). SEE RULE 1103. For Multiple Completions: Augustian A	T JOB
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:	T JOB
OTHER:  OTHER:	T JOB
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump  4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa	T JOB  d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	T JOB  d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ½" OS w/2 3/8" grapple, 4 ½" jars, s on 2 7/8" WS to 2405' RU foam air unit Attempt Est
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, so on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653'
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, so on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663' KS SION TOF @3653'
OTHER:  CASING/CEMEN  OTHER:	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, s on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' was proposed to 27/8" WS Tag TOF @3544', Retrieve
OTHER:  CASING/CEMEN  OTHER:	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, s on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' to 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion inder @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, s on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' to 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion inder @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, s on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' to 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, is on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve to clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869'
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WI. POOH w/108 jts & 1 cut 6-4 ¼" DE's & 4 ¼" intensified on 5 jts 2 7/8" WS SDON  5/1/2007 POOH w/10 jts 2 7/8" WS RIH w/ KutRite shoe, (5jts) 5 ½" wash pipe, 4 ½" po, jars & (6) 4 ¼" DC's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns CO1 & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 ¾"OS w/ 2/3" grapple, 4 ¼" bumper sub, 4 ¼" oil jars, (6) 4 /14" DC's & fish Set back down & tag up @3538' POOH w/ 2 7/8" WS, BHA & fish (recovered 100% Fish RU air foam unit & est circ @2423' RIH w/ 2 7/8" WS & tag up @3654' RU foam air unit Est circ & down to hole to 3870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964'  5/4/2007 RIH w/WS & tag @3907' No fill POOH w/WS  Tag @3907' No fill POOH w/WS  Till w/Ws to 3907' pump 110 gals Gryptron T-29 scale inhibitor over OH perfs & flush w/25 bbls 2% desander, 4' TS, 2/8" SN & 89 jts 2 3/8" tbg t0 2992 SION	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, so on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663' KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve telan out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869'
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WL. POOH w/108 jts & 1 cut 6-4 ¼" DE's & 4 ¼" intensified on 5 jts 2 7/8" WS SDON  5/1/2007 POOH w/10 jts 2 7/8" WS RIH w/ KutRite shoe, (5jts) 5 ½" wash pipe, 4 ½" po, jars & (6) 4 ½" DC's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns CO1 & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 ¾"OS w/2/3" grapple, 4 ¼" bumper sub, 4 ¼" oil jars, (6) 4 /14" DC's & fish Set back down & tag up @3538' POOH w/2 7/8" WS, BHA & fish (recovered 100% Fish 5/3/2007 RU air foam unit & est circ @2423' RIH w/2 7/8" WS & tag up @3654' RU foam air unit Est circ & down to hole to 3870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964'  5/4/2007 FIH w/WS & tag @3907' No fill POOH w/WS  5/7/2007 RIH w/Ws to 3907' pump 110 gals Gryptron T-29 scale inhibitor over OH perfs & flush w/25 bbls 2% desander, 4' TS, 2/8" SN & 89 jts 2 3/8" tbg t0 2992 SION  5/8/2007 FIH w/2 3/8" tbg ND BOP NU WH RIH w/swab made 3 swab runs RIH w/2"x1 ½"x16' pur Well pumping to battery	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, is on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663' KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' mp & ¾" rods Load to 500# w/10 bbls 2% KCL water
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WL. POOH w/108 Jts & 1 cut 6-4 ¼" DE's & 4 ¼" intensified on 5 Jts 2 7/8" WS SDON  5/1/2007 POOH w/10 Jts 2 7/8" WS RIH w/ KutRite shoe, (5Jts) 5 ½" wash pipe, 4 ½" po, jars & (6) 4 ¼" DC's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns COU & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 Jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 ¾"OS w/2/3" grapple, 4 ¼" bumper sub, 4 ¼" oil jars, (6) 4 /14" DC's & fish Set back down & tag up @35538' POOH w/2 7/8" WS, BHA & fish (recovered 100% Fish RU air foam unit & est circ @2423' RIH w/ 2 7/8" WS & tag up @3654' RU foam air unit Est circ & down to hole to 3870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964'  5/4/2007 FIH w/WS & tag @3907' No fill POOH w/WS  5/7/2007 RIH w/Ws to 3907' pump 110 gals Gryptron T-29 scale inhibitor over OH perfs & flush w/25 bbls 2% desander, 4' TS, 2/8" SN & 89 Jts 2 3/8" tbg t0 2992 SION  5/8/2007 RIH w/Sab BFL @2400', EFL @2600' Rec'd 105 bbls fluid in 35 swab runs RIH w/2"x1 ½"x16' pur Well pumping to battery  I hereby certify that the information above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, is on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' mp & ¾" rods Load to 500# w/10 bbls 2% KCL water tee and belief. I further certify that any pit or below-
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529' 3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WL. POOH w/108 jts & 1 cut 6-4 'w' DE's & 4 'w' intensified on 5 jts 2 7/8" WS SDON  5/1/2007 POOH w/10 jts 2 7/8" WS RIH w/ KutRite shoe, (5jts) 5 'y' wash pipe, 4 'w' po, jars & (6) 4 'w' DE's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns CO1 & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 '4"OS w/ 2/3" grapple, 4 'w' bumper sub, 4 'w' oil jars, (6) 4 /14" DC's & fish Set back down & tag up @3538' POOH w/ 2 7/8" WS, BHA & fish (recovered 100% Fish Colon to 1870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964'  5/4/2007 RIH w/WS & tag @3907' No fill POOH w/WS  5/7/2007 RIH w/WS to 3907' pump 110 gals Gryptron T-29 scale inhibitor over OH perfs & flush w/25 bbls 2% desander, 4' TS, 2/8" SN & 89 jts 2 3/8" tbg 10 2992 SION  5/8/2007 RIH w/23 3/8" SN & 89 jts 2 3/8" tbg 10 2992 SION  5/8/2007 RIH w/sab BFL @2400', EFL @2600' Rec'd 105 bbls fluid in 35 swab runs RIH w/2"x1 'y''x16' pur Well pumping to battery  I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, is on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' mp & ¾" rods Load to 500# w/10 bbls 2% KCL water tee and belief. I further certify that any pit or below-
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WL. POOH w/108 Jts & 1 cut 6-4 ¼" DE's & 4 ¼" intensified on 5 Jts 2 7/8" WS SDON  5/1/2007 POOH w/10 Jts 2 7/8" WS RIH w/ KutRite shoe, (5Jts) 5 ½" wash pipe, 4 ½" po, jars & (6) 4 ¼" DC's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns COU & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 Jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 ¾"OS w/2/3" grapple, 4 ¼" bumper sub, 4 ¼" oil jars, (6) 4 /14" DC's & fish Set back down & tag up @35538' POOH w/2 7/8" WS, BHA & fish (recovered 100% Fish RU air foam unit & est circ @2423' RIH w/ 2 7/8" WS & tag up @3654' RU foam air unit Est circ & down to hole to 3870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964'  5/4/2007 FIH w/WS & tag @3907' No fill POOH w/WS  5/7/2007 RIH w/Ws to 3907' pump 110 gals Gryptron T-29 scale inhibitor over OH perfs & flush w/25 bbls 2% desander, 4' TS, 2/8" SN & 89 Jts 2 3/8" tbg t0 2992 SION  5/8/2007 RIH w/Sab BFL @2400', EFL @2600' Rec'd 105 bbls fluid in 35 swab runs RIH w/2"x1 ½"x16' pur Well pumping to battery  I hereby certify that the information above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, is on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' mp & ¾" rods Load to 500# w/10 bbls 2% KCL water ge and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan □.
OTHER:  OTHER:	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ½" OS w/2 3/8" grapple, 4 ½" jars, son 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' w 4 ½" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' np & ½" rods Load to 500# w/10 bbls 2% KCL water ge and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE May 15, 2007
OTHER:    CASING/CEMEN	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ¾" OS w/2 3/8" grapple, 4 ¼" jars, is on 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' at 4 ¼" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' mp & ¾" rods Load to 500# w/10 bbls 2% KCL water ge and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan □.
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WI. POOH w/108 jts & 1 cut 6-4 ½" DE's & 4 ½" intensified on 5 jts 2 7/8" WS SDON  5/1/2007 POOH w/10 jts 2 7/8" WS RIH w/ kutRite shoe, (5jts) 5 ½" wash pipe, 4 ½" po, jars & (6) 4 ¼" DE's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns CO1 & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 ½"OS w/ 2/3" grapple, 4 ½" bumper sub, 4 ½" oil jars, (6) 4 /14" DE's fish Set back down & tag up @3538' POOH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/ 2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/ 2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ & down to hole to 3870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964' S/4/2007 FIH w/Ws to 3907' No fill POOH w/WS DE's & bit RU WI. RIH w/300 GR string shot String DC & WS Tag @3907' No fill POOH w/WS  5/7/2	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ½" OS w/2 3/8" grapple, 4 ½" jars, son 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' to 4 ½" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' np & ¾" rods Load to 500# w/10 bbls 2% KCL water ge and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE May 15, 2007  Telephone No. 281-517-7505
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  4/25/2007 MIRU, POOH w/ rods & pump 4/27/2007 RU WL RIH w/freepoint tools, showed 100% free @3012' 3269' 3529'3559 Set down on top of desa cutter Pump 5 bbls 2% KCL down tbg & cut tbg @3520' POOH & RD WI. POOH w/108 jts & 1 cut 6-4 ½" DE's & 4 ½" intensified on 5 jts 2 7/8" WS SDON  5/1/2007 POOH w/10 jts 2 7/8" WS RIH w/ kutRite shoe, (5jts) 5 ½" wash pipe, 4 ½" po, jars & (6) 4 ¼" DE's circulation Could not get circ FIH w/tbg to 3561' Hook up foam air unit Est circ w/50 returns CO1 & lost circ Worked pipe free, but could not go back down. POOH w/WS & BHA/ RIH w/4 jts 2 7/8"  5/2/2007 POOH w/4 jts KS RIH w/5 ½"OS w/ 2/3" grapple, 4 ½" bumper sub, 4 ½" oil jars, (6) 4 /14" DE's fish Set back down & tag up @3538' POOH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/ 2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/ 2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ @2423' RIH w/2 7/8" WS, BHA & fish (recovered 100% Fish Start foam unit & est circ & down to hole to 3870' Clean out fill to 3907' circulate hole clean POOH w/WS to 2964' S/4/2007 FIH w/Ws to 3907' No fill POOH w/WS DE's & bit RU WI. RIH w/300 GR string shot String DC & WS Tag @3907' No fill POOH w/WS  5/7/2	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ander @3566' POOH w/freepoint tools RIH w/chemical jts 2 3/8"tbg RIH w/5 ½" OS w/2 3/8" grapple, 4 ½" jars, son 2 7/8" WS to 2405' RU foam air unit Attempt Est to 3653' Wash pipe stuck after making connection @3663 KS SION TOF @3653' w 4 ½" acl sub on 2 7/8" WS Tag TOF @3544', Retrieve clean out sand to CIBP @3338' Drillout CIBP & push ag shot perfs f/2982-3907' POOH w/WL & RD RIH w/bit KCL wtr POOH & LD WS RIH w/2 3/8"BPMA, @3869' np & ½" rods Load to 500# w/10 bbls 2% KCL water ge and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE May 15, 2007