

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Brine Well

8. Well No.

1

9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER ☒ Brine Well

2. Name of Operator

McCasland Services, Inc.

3. Address of Operator

PO Box 99 Eunice, NM 88231

4. Well Location

Unit Letter J : Feet From The NW/4 Line and Feet From The SE/4 Line

Section 34 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) M.I.R.U. P.U., Nipple down well head, Install B.O.P. Tbg. stuck.
- 2) R.U. Rotary Wireline; R.I.H. w/ free point, Tbg. free to 1200', could not go below 1202'.
- 3) P.O.O.H.w/ 1232' Tbg. R.I.H. w/ bit, Could not get below 1200'.
- 4) R.I.H. w/ C.I.B.P. set @ 1190'. Dump 10' cement on to C.I.B.P., R.I.H. w/ retrievable pkr, test bridge plug, test casing : casing bad from 512' - 30'. Decided to plug well.
- 5) R.I.H. open ended, tag cement on top of C.I.B.P. @ 1180', pump 112 sks class C cement. P.O.Q.H. W.O.C. 5 Hr. R.I.H. Tag top of cement @ 515'. Mix 87 sks. class C cement. P.O.
- 6) R.I.H. Tag cement @ 45'. Mix 7 sks cement. Fill csg. to surface. Cut well head off. Install dry hole marker & cap.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Ray D. Ramsey

TITLE

Company Rep.

DATE

2/23/94

TYPE OR PRINT NAME

Ray D. Ramsey

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 28 1994

JC

CP