## OCD-HOBBS

Form 3160-5	UNITED STATES	2			FORM APPROVED		
(September 2001)		DEPARTMENT OF THE INTERIOR			OM B No. 1004-0135 Expires, Jamiary 31, 2004		
BUREAU OF LAND MANAGEMENT				5 Lease Scrial No.			
SUNDRY NOTICES AND REPORTS ON WELLS				NM NM 01135       6. If Indian, Allottee or Tribe Name			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.				N/A			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No			
I Type of Well ↓ Oil Well ← Gas Well ← Other				N/A			
				8 Well Name and No. Southeast Lusk 34 Federal #3			
2 Name of Operator Edge Petroleum Operating Company, Inc., 3a Address 3b Phone No (include area code)				9, API W	ell No.		
3a     Address     3b     Phon       1301     Travis, Ste 2000     Houston, TX 77002     713-33					10 Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Lusk, Delaware		
330' FNL & 330' FWL Unit U					11. County or Parish. State		
Sec. 34, T- 19S, R- 32E				Lea Co. NM			
12. CHEC	K APPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTIĆE, R	EPORT. OI	R OTHER DATA	2223	
TYPE OF SUBMISSION TYPE OF ACTION				H. County or Parish. State Lea Co. NM REPORT. OR OTHER DATA art/Resume) Witer Shut-Off UEC 2007 Well Integrity TOCOIVEO Other Hohrse handon			
Notice of Intent	Acidize	Deepen	Production (Sta	nt/Resume)	Wher shut-Off UEC 2007	52	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity Received	6 N	
Subsequent Report	Change Plans	Casing Repair New Construction Recomplete			Hobbe	N	
Final Abandonment Not	ice Convert to Injection	Plug Back	Water Disposal		<u> </u>	~~~~/	
testing has been complet datermined that the site is 6-26-2006 Test Chi 6-27-2006 Strip rods KCL, test to 3000# & 6-28-2006 POR w/ t 15,000# compression balled out. Surged hi 6-30-2006 Engage 3% KCL. 7-5-2007 Perforate w water, pumped 2 bbl Trting, PSI @ 2500# to flowback, flowed 7	the involved operations. If the operation ( ed. Final Abandonment Notices shall be f s ready for final inspection ) erry Canyon intervals and possible of & tubing out of hole. PU RBP & set : held for 15 min., release pressure & by, RH w/3 1/8" csg. gun & perf. fr . Pumped 500 gal 7 1/2 % NEFE w/ dls & finished job. Max. rate 2 bbls retreiving tool & move RBP to 4965 / 3 1/8" tbg gan from 4866'-4871' w/ s to break down ( <i>à</i> 3200#, Start on a ( <i>â</i> , 2 BPM, Max. trting. PSI ( <i>â</i> . 3200# bbls. RU to swab, made 5 runs-swa oil cut, Pumped 750 gals, NEFE 71	iled only after all requirer completion. ting tool. 7 HH w/ 158 j & dump 80# sand & di om 5000'-5004', 2 spf. 24 ball sealers. Max. p min. @ 2200#. 151P-1. '. pressure to 3000#. L ' 2 spf, no reaction troo cid & ball sealers. Ave # on ballout, 151P- 149 bbed dry. SD for 30 m	nents, meluding reclam (ts. 2 3/8" thg & set ( splace w/12 bbls 3% PU Arrowset pkr w ressure 2800#, brok 360 5 min1304 1 ay down 3 jts. Spot m formation. T1H w 25 5 min 1336# 1 dinDuid level @ 400	ation, have bee RBP @ 5160' KCL. /on-off tool, ' c to 2400# w/ 0 min1277   l sk sand on / 146 jts, tbg. 0 Min, - 1315 00' w/ 10% of	n completed, and the operator has ". Displace hole w/ 90 bbls 3 % THI w/ tbg to 4906' & set pkr. w/ / good ball action, broke to 1923#, 15 min. 1255. top of RBP, displace w/ 20 bbls . & set pkr. at 4776', Start on 5 # 15 min 1295#, RU if cut, SD for 30 minfluid		
14. Thereby certify that the Name (Printed/Type	e foregoing is true and correct J	<u> </u>	* 7				
Angela Lig	ntner angela@rkford.com	Title Co	insultant 432-682-	0440 office			
Signature	l'a Lighthen	Date	1	2/17/2007 A	CCEPTED FOR REC	ORD	
	THIS SPACE FOR F	EDERAL OR ST	ATE OFFICE	USE			
	a unit attached. Approval of this notice d	oes not warrant or	NICOR/GEN	PLO GAR	EB 0 7	2008	
certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.				ALEXIS C. SWOBODA			
Title 18 U.S.C. Section 1001 an	1 Title 43 U.S.C. Section 1212, make it a audulent statements or representations as	crime for any person kne s to any matter within its	wingly and willfully t jurisdiction	o make to any	department of agency of the United	R	
(Instructions on page 2)							

Edge Petroleum Operating Company, Inc. Southeast Lusk 34 Federal #3 API# 30-025-37358 Completion Cont.

<u>7-6-2006</u> POH w/146 jts.tbg. Perforate at 4824'-4836', 1 spf. 4850'-4864' 1 spf. 4873'-4876' 1 spf. 4880'-4887' 1 spf. no hole reaction-fluid at 1450'. TJH w/ 145 jts. tbg & set pkr. @ 4742' w/ 15,000#. Load back side & pressure up to 500#, pump 7200 gal 7 1/2% NEFE & 138 ball sealers. Max. pressure 3743 w/ 7.6 BPM. Avg. psi 3000#, avg. rate 6 BPM. Ball out @ 4800# -good ball action. ISIP 1296# 5 min.- 1193# 10 min.-1165 15 min.- 1145#. flush w/ 25 bbls 3% KCL load to recover 200 bbls.

<u>7-12-2006</u> TTH wl Arrowset pkr & 142 its. tbg. Packer set @ 4650'. Release from pkr. & load hole. Spotted acid to packer and latched back on parker. Pressure annulus to 560 psi. Acidize middle Cherry Canyon perfs. wl 3000 gal. 7 1/2% NEFE acid. Formation broke at 2400 psi @ 1.2 BPM. Increased rate slowly to 5.1 BPM @ 2595 psi. Balled out 5x to 3800 psi. wl 57 bbl acid in formation. Annulus psi to 1560 psi. Surged off & continued pumping 4.6 BPM & 2360 psi. ISIP- 1200 psi 5 min- 1070 psi 10 min. -1047psi 15 min- 1029 psi. TBLWTR=95. /flowed back 5 BLW. Released from pkr. & reverse curculated 47 bbl 3% KCL to clear annulus.

<u>7-11-2006</u> Release pkr & POOH. RIH w/ 10K lockset RBP & set @ 4810'. Circulated well clean w/ 3% KCL. Tested RBP to 3000 psi. Spotted 1 *cu.ft.* sand on RBP & displace w/ 15 bbl KCL. Perforate Middle Cherry Canyon from 4748'-4760' & 4762'-4765' w/3 1/8" esg. gun loaded 2 spf-phased 60 degrees, made 30 holes. No reaction from formation.

<u>Resume production 7-14-2006</u> Swab 2nd run, FL at 4500', no fluid recovered. 3rd run (1 hr. wait) FL at 4400', 50' recovered, 60% oil, gas blow after run. Released from pkr. & TOOH, LD pkr. & PU retrieving head. RIH, tagged sand @ 4795', RU kill truck & washed/ reverse circulated sand. Latched on & released RBP, TOOH, Ran tbg, & hung off in well.

<u>7-15-2006</u> ND BOP & set tbg. anchor w/ 15 pt.s tension. Flanged up wellhead. PU pump & rods & RIH. Spaced out and hung off to pump jack. Started pump jack & returned to production.