State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE FEB 1 5 2008 OIL CONSERVATION DIVISION		
DISTRICT I	WELL API NO.	
1625 N. French Dr., Hobbs BBS OCD Santa Fe, NM 87505	30-025-05440	
DISTRICTI	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE	
<u>DISTRICT III</u>	6 State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	Section 13	
1. Type of Well:	8. Well No. 121 /	
Oil Well Gas Well Other Temporarily Abandoned	9. OGRID No 157984	
2. Name of Operator	9. OGRID No 157984	
Occidental Permian Ltd. 3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX 79323	10008 (0/5/1)	
4. Well Location		
Unit Letter E . 1980 Feet From The North 660 Fee	et From The West Line	
Olit Letter E 1980 Teer Form File North	West Eme	
Section 13 Township 18-S Range 37-I	E NMPM Lea County	
11. Elevation (Show whether DF, RKB, RT GR, etc.)		
3692' DF		
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	IT JOB	
OTHER: Repair casin	g leak/TA status request X	
12 Describe Proposed or Completed Operations (Clearly state all partitions details, and give partitions dates		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any		
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed		
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.	completion or recompletion.	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed (1). RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'.	. RD HES. Circ clean. Continue drilling on cement. Fell out	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill collars.	. RD HES. Circ clean. Continue drilling on cement. Fell out	
<ol> <li>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &amp;RU. NU BOP/Unflange well.</li> <li>RIH w/packer set @915'. Test casing. Tested OK.</li> <li>RU HES &amp; pump 2 bbl of brine water &amp; 108 sxs of cement. Squeeze into leak @220-251'.</li> <li>RIH w/bit &amp; drill collars. Tag cement @75'. RU powerswivel &amp; drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit &amp; drill of ND BOP. NU Flange.</li> </ol>	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.	
<ol> <li>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &amp;RU. NU BOP/Unflange well.</li> <li>RIH w/packer set @915'. Test casing. Tested OK.</li> <li>RU HES &amp; pump 2 bbl of brine water &amp; 108 sxs of cement. Squeeze into leak @220-251'.</li> <li>RIH w/bit &amp; drill collars. Tag cement @75'. RU powerswivel &amp; drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit &amp; drill of the ND BOP. NU Flange.</li> <li>Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NM</li> </ol>	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.	
<ol> <li>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &amp;RU. NU BOP/Unflange well.</li> <li>RIH w/packer set @915'. Test casing. Tested OK.</li> <li>RU HES &amp; pump 2 bbl of brine water &amp; 108 sxs of cement. Squeeze into leak @220-251'.</li> <li>RIH w/bit &amp; drill collars. Tag cement @75'. RU powerswivel &amp; drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit &amp; drill collars. To BOP. NU Flange.</li> <li>Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU &amp; RU.</li> </ol>	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.	
<ol> <li>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &amp;RU. NU BOP/Unflange well.</li> <li>RIH w/packer set @915'. Test casing. Tested OK.</li> <li>RU HES &amp; pump 2 bbl of brine water &amp; 108 sxs of cement. Squeeze into leak @220-251'.</li> <li>RIH w/bit &amp; drill collars. Tag cement @75'. RU powerswivel &amp; drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit &amp; drill collars. To BOP. NU Flange.</li> <li>Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU &amp; RU.</li> </ol>	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.	
<ol> <li>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &amp;RU. NU BOP/Unflange well.</li> <li>RIH w/packer set @915'. Test casing. Tested OK.</li> <li>RU HES &amp; pump 2 bbl of brine water &amp; 108 sxs of cement. Squeeze into leak @220-251'.</li> <li>RIH w/bit &amp; drill collars. Tag cement @75'. RU powerswivel &amp; drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit &amp; drill of the ND BOP. NU Flange.</li> <li>Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NM</li> </ol>	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.	
<ol> <li>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &amp;RU. NU BOP/Unflange well.</li> <li>RIH w/packer set @915'. Test casing. Tested OK.</li> <li>RU HES &amp; pump 2 bbl of brine water &amp; 108 sxs of cement. Squeeze into leak @220-251'.</li> <li>RIH w/bit &amp; drill collars. Tag cement @75'. RU powerswivel &amp; drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit &amp; drill collars. To BOP. NU Flange.</li> <li>Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU &amp; RU.</li> </ol>	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill of the ND BOP. NU Flange.  5. ND BOP. NU Flange.  6. Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU & RU.  This Approval of Temporal Abandonment Expires.  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	Completion or recompletion.  RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary  3/6/20/3	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill on the ND BOP. NU Flange.  5. ND BOP. NU Flange.  6. Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU & RU.  This Approval of Temporal Abandonment Expires.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	Completion or recompletion.  RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary  1	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill on the ND BOP. NU Flange.  5. ND BOP. NU Flange.  6. Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU & RU.  This Approval of Temporal Abandonment Expires  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	Completion or recompletion.  RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary  1	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill of the State of the State of the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NM 7. RDPU & RU.  This Approval of Temporal Abandonment Expires.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines. , a general permit or an (attached) alternative plan.	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary 3/6/20/3  that any pit or below-grade tank has been/will be	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill on the ND BOP. NU Flange.  5. ND BOP. NU Flange.  6. Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU & RU.  This Approval of Temporal Abandonment Expires  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE  TITLE Administrative	RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary 3/6/20/3  that any pit or below-grade tank has been/will be	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill of the ND BOP. NU Flange.  5. ND BOP. NU Flange.  6. Test casing to 690# and chart for the NMOCD (lost 30 PSI in 30 min). Pat Richards w/NN RDPU & RU.  This Approval of Temporal Abandonment Expires.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	Completion or recompletion.  RD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU &RU. NU BOP/Unflange well.  2. RIH w/packer set @915'. Test casing. Tested OK.  3. RU HES & pump 2 bbl of brine water & 108 sxs of cement. Squeeze into leak @220-251'.  4. RIH w/bit & drill collars. Tag cement @75'. RU powerswivel & drill on cement to 244'. of cement @265'. Run bit to 307'. Circ. Clean. RD power swivel. POOH w/bit & drill of the State of the State of State of State Use Only.  This Approval of Temporal	Associate  CRD HES. Circ clean. Continue drilling on cement. Fell out ollars.  MOCD on location to witness test & approve test.  Drary  John John John John John John John John	

