Submit 3 Copies To Appropriate District Office	State of New Me	xico		Form C-103
District I 1625 N French Dr , Hobby 1988 40	State of New Me	ral Resources	WELL API NO.	May 27, 2004
District II	OIL CONSERVATION	1	30-025-06852	
1301 W Grand Ave., Artesia, NM 88210 District III	1220 Courth St. Enon	1	5. Indicate Type of Leas	
1000 Rio Brazos Rd, Aztec, NM MAR 2 () 2 District IV	UUÖ Santa Fe, NM 87	+	STATE 6. State Oil & Gas Lease	FEE X
1220 S St Francis Dr Sank Fe, M 87505	COCO		o. State on & Gas Least	
SUNDRY NOTICES	AND REPORTS ON WELLS		7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR USE "APPLICATION PROPOSALS")			EUNICE KING	
1. Type of Well: Oil Well Gas	Well Other		8. Well Number 15	
2. Name of Operator CHEVRON U.S.A. INC.			9. OGRID Number 432	3
3. Address of Operator			10. Pool name or Wildo	at
15 SMITH ROAD, MIDLAND, TEXAS 79705			SIMPSON;HARE	<u></u>
4. Well Location				
	the NORTH line and 2086 feet		/	
Section 28 Township 21	-S Range 37-E . Elevation (Show whether DR,	NMPM RKR RT GR etc.)	County LEA	
	·			
Pit or Below-grade Tank Application or Clo				
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appr	copriate Box to Indicate Na	ature of Notice, F	Report or Other Data	
NOTICE OF INTE	NTION TO:	SUBS	SEQUENT REPORT	ΓOF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN				
TEMPORARILY ABANDON			P,A 🗆	
PULL OR ALTER CASING M	DETIFLE COMPL	CASING/CEMENT	JOB 📙	
OTHER: SHUT-OFF WATER, ACIDIZ		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
CHEVRON U.S.A. INC. INTENDS TO SHUT-OFF THE WATER, ACIDIZE, & INSTALL ROD PUMP EQUIPMENT IN THE				
SUBJECT WELL.				
THE INTENDED PROCEDURE & CURRENT & PROPOSED WELLBORE DIAGRAMS ARE ATTACHED FOR YOUR APPROVAL.				
I haraby cartify that the information show	es is two and complete to the he	at a f l ala d		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines \square , a general permit \square or an (attached) alternative OCD-approved plan \square .				
Type or print name Denise Pinkerton E-mail Address: <u>leakdj@chevron.com</u> Telephone No. 432-687-7375				
For State Use Only	_	1	8 A A B	7 1 0000
APPROVED BY:	TITLE (5	eologist		å o i S008 –
Conditions of Approval (if any):				

Eunice King # 15 Hare; Simpson Field T21S, R37E, Section 28

Job: Shut-off Water, Acidize, And Install Rod Pump Equipment

Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 3/13/2008. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and **open valve** at header. Document this process in the morning report.
- 3. MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. Remove WH. Install BOP's and test as required. POH with 2 7/8" tbg string.
- 4. PU and GIH with 6 1/8" MT bit and 2 7/8" work string to PBTD at 7920'. POH with 2 7/8" work string and bit. LD bit.
- **5.** PU & GIH 7" RBP and pkr on 2 7/8" work string to approximately 7750'. Set pkr at 7750' with RBP swinging.
- 6. GIH and swab test perfs 7784-7906'. Report oil cut, recovered fluid volumes, pressures, and/or swabbing fluid levels. Note: Discuss swab results with Engineering before continuing with procedure.
- 7. Open well. Bleed off pressure, if any. Release pkr. Set RBP at 7750'. PUH and set pkr at 7670'.
- 8. GIH and swab test perfs 7682-7730'. Report oil cut, recovered fluid volumes, pressures, and/or swabbing fluid levels. Note: Discuss swab results with Engineering before continuing with procedure.
- 9. Open well. Bleed off pressure, if any. Release pkr. LD and engage RBP at 7750'. Release RBP. PUH and reset RBP at 7670'. PUH and set pkr at 7615'.


- 10. GIH and swab test perfs 7624-7658'. Report oil cut, recovered fluid volumes, pressures, and/or swabbing fluid levels. <u>Note</u>: Discuss swab results with Engineering before continuing with procedure.
- 11. Open well. Bleed off pressure, if any. Release pkr. LD and engage RBP at 7670'. Release RBP. PUH and set RBP at 7615'. PUH and set pkr at 7475'.
- 12. GIH and swab test perfs 7508-7612'. Report oil cut, recovered fluid volumes, pressures, and/or swabbing fluid levels. Note: Discuss swab results with Engineering before continuing with procedure.
- 13. Release pkr. LD and engage RBP at 7615'. Release RBP. POH with 2 7/8" work string, packer, and RBP. LD RBP.
- 14. MI & RU Baker Atlas electric line unit. Install lubricator and test to 2000 psi. GIH and set CIBP at 7676'. POH. GIH and dump bail 10' of cement on top of CIBP at 7676'. POH. RD & release electric line unit. Note: Use csg collars from PGAC GR-Neutron Log dated 5/13/60 for depth correction.
- 15. PU & GIH with 2 7/8" work string and packer to 7475'. Set packer at 7475'. Pressure test casing and pkr to 350 psi. Note: Do not exceed 350 psi casing pressure due to cmt sqzd perfs from 5093-7200'.
- 16. MI & RU DS Services. Pump down 2 7/8" work string and acidize perfs 7508-7658' with 4,000 gals regular antisludge 15% HCl acid ** at a maximum rate of **3 BPM** and a maximum surface pressure of **3500 psi**. Spot acid to bottom of 2 7/8" tbg. Displace acid with 8.6 PPG cut brine water -- do not overdisplace. Record ISIP, 5, 10, & 15 minute SIP's. RD & release DS Services.

** Acid system is to contain:	1 GPT A264	Corrosion Inhibitor
	8 GPT L63	Iron Control Agent
	2 PPT A179	Iron Control Aid
	20 GPT U66	Mutual Solvent
	2 GPT W53	Non-Emulsifier

- 17. GIH and swab back spent acid. Recover 100% of treatment and load volumes before shutting well in for night. Report recovered fluid volumes, pressures, and/or swabbing fluid levels.
- 18. Open well. Release pkr. POH LD 2 7/8" work string and packer.
- 19. PU and GIH w/ dump valve, 2 jts. 2 7/8" EUE 8R J-55 tbg, Cavins Desander, SN, 1 jt 2 7/8" EUE 8R J-55 IPC tbg, 10 jts 2 7/8" EUE 8R J-55 tbg, TAC, and 220 jts 2 7/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 7100', with EOT at 7550' and SN at 7475'.

- 20. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit. Note: Confer with ALS, Baker Petrolite Rep, and Pump Co. Rep. regarding prior chemical program and corrosion on previous rod pumps prior to running pump. Avoid using metallurgy in pump that demonstrated prior corrosion.
- 21. Start all continuous injection chemicals prior to starting well pumping. Turn well over to production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.

AMH 3/17/08



. . . `

eking15 wb diagram xls 3/18/2008 5 40 AM