

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE  MAD 2 0 2009 OIL CONSERVATION DIVISION	
DISTRICT I PLAN 20220 1220 South St. Francis Dr.	WELL API NO 30-025-34870
1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	5 Indicate Type of Lease
DISTRICT II  1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III	6 State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 29
1 Type of Well. Oil Well X Gas Well Other	8. Well No 624
Name of Operator     Occidental Permian Ltd.	9. OGRID No. 157984
3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	,
4. Well Location	
Onit collect 14 . 1150	t From The West Line
Section 29 Township 18-S Range 38-I	E NMPM Lea County
3641' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	
	24 - D 4
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Control NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
NOTICE OF INTENTION TO.	SEQUENT REPORT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	ALTERING CASING  NS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Open additional	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB   all perfs/acid stimulate  X  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Open additional	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB   all perfs/acid stimulate  X  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Open additiona  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB   all perfs/acid stimulate  X  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 clearly state all pertinent details, and give pertinent dates proposed on the proposed of the propose	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER:  OTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  all perfs/acid stimulate  X  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  I, including estimated date of starting any completion or recompletion.  The memical of the property of the prope
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Open additional  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  I, including estimated date of starting any completion or recompletion.  The memical of the property of the prope
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Open additional Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.  10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  I, including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  I/07/08 RDPU 02/13/08
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Open additiona  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.  10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  I, including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  1/07/08 RDPU 02/13/08  That any pit or below-grade tank has been/will be
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Open additional Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.  10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  I, including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  I/07/08 RDPU 02/13/08  That any pit or below-grade tank has been/will be
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Open additiona  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed in RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.  10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  I hereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative or an (attached) alternative or an extracted or closed according to NMOCD guidelines , a general permit or an (attached) alternative or an extracted or closed according to NMOCD guidelines , a general permit or an extracted or closed according to NMOCD guidelines or an extracted or closed according to NMOCD guidelines or an extracted or an extracted or an extracted or closed according to NMOCD guidelines or an extracted or closed according to NMOCD guidelines or an extracted or according to NMOCD guidelines or an extracted or an extracted or an extracted or an extracted or at a constant or an extracted	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  Including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  Including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  Including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Open additions  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline. 3. NU BOP/ND wellhead. POOH w/ESP equipment. 4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl. 5. Scanalog tubing. 6. RIH w/bit. Tag @4316'. POOH w/bit. 7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline. 8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer. 9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'. 10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  Including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  That any pit or below-grade tank has been/will be the OCD-approved  Associate  DATE 03/19/2008
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Open additiona  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed in RUPU & RU. Kill well.  2. RU wireline & perforate tubing @3876'. RD wireline.  3. NU BOP/ND wellhead. POOH w/ESP equipment.  4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl.  5. Scanalog tubing.  6. RIH w/bit. Tag @4316'. POOH w/bit.  7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline.  8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer.  9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'.  10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE  TITLE Administrative	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  Including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  No 1/07/08 RDPU 02/13/08  That any pit or below-grade tank has been/will be the OCD-approved  Associate  DATE 03/19/2008
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Open additiona  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed. 1. RUPU & RU. Kill well. 2. RU wireline & perforate tubing @3876'. RD wireline. 3. NU BOP/ND wellhead. POOH w/ESP equipment. 4. RIH w/packer set @2400'. Pump 500 gal of Xylene, 50 gal of 6496 chemical & 10 gal of 6495 cl. 5. Scanalog tubing. 6. RIH w/bit. Tag @4316'. POOH w/bit. 7. RU wireline & perforate hole @2 ISPF at 4055-64'. RD wireline. 8. RIH w/PPI packer set @3973'. RU HES. Pickle tubing w/5 bbl of 15% PAD acid. Acid treat ne HES. POOH w/PPI packer. 9. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @3990'. 10. ND BOP/NU C-prox wellhead. RDPU & RU. Clean location RUPU 02  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative mendy johnson@oxy.com	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  Il perfs/acid stimulate  X  Including estimated date of starting any completion or recompletion.  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08  The perfs w/35 bbl of 15% HCL PAD acid. RD  NOT/08 RDPU 02/13/08