State of New Mexic	20	
Frongy Minerals and Natural Reso	ources Department	Form C-103
State of New Mexico Form C-103 Revised 5-27-2004 FILE IN TRIPLICATE		
		·····
DISTRICT I 1220 South St. Franci	20.025.25759	
1625 N. French Dr., Hobbs, NM 8884AR 2 (1 2007; Santa Fe, NM 875	5. Indicate Type of Lease	
	STATE X	- FEE
1301 W Grand Ave, Artestan Mi 8300	6. State Oil & Gas Lease No.	
DISTRICT III III III III IIII IIII IIIIIIIIII	0. State Off & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreer	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG I		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such		
1. Type of Well:	8. Well No. 535	-
Oil Well X Gas Well Other		
2 Name of Operator	9. OGRID No 157984	
Occidental Permian Ltd.		-
3. Address of Operator	10. Pool name or Wildcat	Hobbs (G/SA)
HCR Box 90 Denver City, TX 79323		
4. Well Location		
Unit Letter K : 2188 Feet From The South	2510 Feet From The West	Line
Section 33 Township 18-S	Range 38-E NMPM	Lea County
11. Elevation (Show whether DF, RKB, RT GR, et	0 000	
3638' GR		
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh	n water well Distance from nearest s	urface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls	; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
		_
NOTICE OF INTENTION TO:	otice, Report, or Other Data SUBSEQUENT REPORT O	F:
NOTICE OF INTENTION TO:		F: G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL		
NOTICE OF INTENTION TO: REMEDIA PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMENT	SUBSEQUENT REPORT O	G CASING
NOTICE OF INTENTION TO: REMEDIA PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEI PULL OR ALTER CASING Multiple Completion CASING	SUBSEQUENT REPORT O	G CASING
NOTICE OF INTENTION TO: REMEDIA PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEI PULL OR ALTER CASING Multiple Completion CASING	SUBSEQUENT REPORT O	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER.	SUBSEQUENT REPORT O	G CASING
NOTICE OF INTENTION TO: REMEDIA PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEI PULL OR ALTER CASING Multiple Completion CASING	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. Katach wellbore dia	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. 2. POOH w/ESP equipment.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & 7 TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. RU wireline & shoot holes at 2887'. RD wireline.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of sigram of proposed completion or recompletion.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. RU wireline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH POH	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of sigram of proposed completion or recompletion.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. RU wireline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH S. RU wireline & shoot holes @3100'. RD wireline.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of sigram of proposed completion or recompletion.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. RU wireline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH POH	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s gram of proposed completion or recompletion. w/bit. w/bit.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of sigram of proposed completion or recompletion. w/bit. ine.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of sigram of proposed completion or recompletion. w/bit. ine.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'. 10. ND BOP/NU wellhead.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s gram of proposed completion or recompletion. w/bit. w/bit. IEFE. RD HES. POOH w/PPI packer.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & / TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of sigram of proposed completion or recompletion. w/bit. ine.	G CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEI PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 2. POOH w/ESP equipment. RU wireline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. 6. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean location.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. ine. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RDPU 02/05/08	G CASING ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'. 10. ND BOP/NU wellhead.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. ine. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RDPU 02/05/08	G CASING ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEI PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. POOH w/ESP equipment of 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel RIH w/PI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8'' tubing. Intake set @4236'. IO. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. Thereby certify that the information above is true and complete to the best of my knowledge and be constructed or	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. ine. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RDPU 02/05/08	G CASING ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA TEMPORARILY ABANDON CHANGE PLANS COMMEI PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. POOH w/ESP equipment on 133 Jts of 2-7/8" tubing. Intake set @4236'. 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. POH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'.	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. ine. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RDPU 02/05/08	G CASING ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENDIAL PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diat 1. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. OTHER. 3. RU wireline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. 6. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PPI packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8" tubing. Intake set @4236'. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. Thereby certify that the information above is true and complete to the best of my knowledge and be constructed or closed according to NMOCD guidelines , a general permit or an (at a closed according to NMOCD guidelines	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s gram of proposed completion or recompletion. w/bit. w/bit. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RUPU 01/17/08 RDPU 02/05/08 Iteff. I further certify that any pit or below-grade tank futtached) alternative OCD-approved	ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diates and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diates and proposed work) SEE 14. RUPU & RU. Kill well. NU BOP/ND wellhead. 2. POOH w/ESP equipment. 3. RU wireline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. 6. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. 8. RIH w/PIP packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. 9. RIH w/ESP equipment on 133 jts of 2-7/8'' tubing. Intake set @4236'. 10. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. Ihereby certify that the information above is true and complete to the best of my knowledge and be constructed or closed according to NMOCD guidelines	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. Including estimated date of a gram of proposed completion. Including estimated date of a gram of proposed completion. Including estimated dat	ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER. OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diates and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diates and proposed work) SEE 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diates and proposed work) SEE 14. RUPU & RU. Kill well. NU BOP/ND wellhead. POOH w/ESP equipment. 2. POOH w/ESP equipment. RL wireline & shoot holes at 2887'. RD wireline. 3. RU wireline & shoot holes @3100'. RD wireline. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wireline. 8. RIH w/PP1 packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8'' tubing. Intake set @4236'. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. Interest of my knowledge and be constructed or closed according to NMOCD	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of s gram of proposed completion or recompletion. w/bit. w/bit. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RUPU 01/17/08 RDPU 02/05/08 Iteff. I further certify that any pit or below-grade tank futtached) alternative OCD-approved	ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 14. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 2. POOH w/ESP equipment. RI wreline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. 6. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PP1 packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8'' tubing. Intake set @4236'. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. Intereby certify that the information above is true and complete to the best of my knowledge and be constructed or closed according to NMOCD guidelines 9. a general permit or an (a plan SIGNATURE <td< td=""><td>SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. ine. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RDPU 02/05/08 itef. I further certify that any pit or below-grade tank inttached) alternative OCD-approved Administrative Associate DAT johnson@oxy.com TELEPHONE NO</td><td>ABANDONMENT</td></td<>	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. ine. IEFE. RD HES. POOH w/PPI packer. RUPU 01/17/08 RDPU 02/05/08 itef. I further certify that any pit or below-grade tank inttached) alternative OCD-approved Administrative Associate DAT johnson@oxy.com TELEPHONE NO	ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENT PULL OR ALTER CASING Multiple Completion CASING OTHER: OTHER OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore dia 14. RUPU & RU. Kill well. NU BOP/ND wellhead. OTHER. 2. POOH w/ESP equipment. RI wreline & shoot holes at 2887'. RD wireline. 4. RIH w/bit. Tag @4420'. Clean out wellbore to 4425'. Circulate clean. POOH 5. RU wireline & shoot holes @3100'. RD wireline. 6. RIH w/bit from 1500' to 4470'. POOH w/bit. 7. RU wireline & perforate casing @2 JSPF @4334-4340', 4466-4471'. RD wirel 8. RIH w/PP1 packer set @4178'. RU HES and acidize perfs w/2400 gal of 15% N 9. RIH w/ESP equipment on 133 jts of 2-7/8'' tubing. Intake set @4236'. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean location. Intereby certify that the information above is true and complete to the best of my knowledge and be constructed or closed according to NMOCD guidelines 9. a general permit or an (a plan SIGNATURE <td< td=""><td>SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. Including estimated date of a gram of proposed completion. Including estimated date of a gram of proposed completion. Including estimated dat</td><td>ABANDONMENT</td></td<>	SUBSEQUENT REPORT O AL WORK ALTERING NCE DRILLING OPNS. PLUG & A TEST AND CEMENT JOB Repair ESP/ OAP / Acid treat give pertinent dates, including estimated date of a gram of proposed completion or recompletion. w/bit. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion or recompletion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. w/bit. Including estimated date of a gram of proposed completion. Including estimated date of a gram of proposed completion. Including estimated date of a gram of proposed completion. Including estimated dat	ABANDONMENT