## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

## OIL CONSERVATION DIVISION

DISTRICT I 1625 N. French DracHobbs NM 88240	1220 South St. Francis Dr.	WELL API NO. 30-025-07077
1625 N. French Drag Hobbs 7 NM 88240 DISTRICT II	Santa Fe, NM 87505	5 Indicate Type of Lease
1301 W. Grand Te Alexand (221)		STATE FEE X
DISTRICTION 1000 Rio Brazos Rd, Aztec, NM 87410		6. State Oil & Gas Lease No.
	ND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		NORTH HOBBS (G/SA) UNIT
	ON FOR PERMIT" (Form C-101) for such proposals.)	Section 30
1. Type of Well	P	8. Well No 111
Oil Well Gas V  2. Name of Operator	Well Other Injector	0.0000001
Occidental Permian Ltd.		9. OGRID No. 157984
3. Address of Operator		10 Pool name or Wildcat HOBBS (G/SA)
HCR 1 Box 90 Denver City, TX 79323  4. Well Location		/
	(II)	
Unit Letter D 330 Feet Fro	om The NORTH 330	Feet From The WEST Line
		38-E NMPM LEA County
11. Elev 3650'	vation (Show whether DF, RKB, RT GR, etc.) GR	
Put or Relay grade Tank Application	Classical Color	
Pit or Below-grade Tank Application or Closure  Pit Type  Denth of Ground Water  Distance from possest fresh water well.		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropri	iate Box to Indicate Nature of Notice, Report,	or Other Data
NOTICE OF INTENTION	TO: St	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AN	ND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE		
TEMPORARILY ABANDON CHANGE		OPNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE	E PLANS COMMENCE DRILLING Completion CASING TEST AND CEI	OPNS. PLUG & ABANDONMENT MENT JOB
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per	OPNS. PLUG & ABANDONMENT MENT JOB MENT JOB X
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per	OPNS. PLUG & ABANDONMENT  MENT JOB  rfs/re-perf/AT  ates, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP.	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per	OPNS. PLUG & ABANDONMENT  MENT JOB  rfs/re-perf/AT  ates, including estimated date of starting any sed completion or recompletion.
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer.	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per	OPNS. PLUG & ABANDONMENT  MENT JOB  rfs/re-perf/AT  ates, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details. Attach wellbore diagram of propositions. Attach wellbore diagram of propositions. Attach wellbore diagram of propositions. Pump 10 bbl 10# brine. RIH & tag gravel @	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attest, including estimated date of starting any red completion or recompletion.  The property of the property
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez.	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details and give pertinent details.  Completions: Attach wellbore diagram of propose the Pump 10 bbl 10# brine. RIH & tag gravel @ te perfs 4165-84' w/24 bbl (94 sxs) cement. RD	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attest, including estimated date of starting any red completion or recompletion.  The property of the property
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel &	COMMENCE DRILLING Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details.  Completions: Attach wellbore diagram of propose  Attach wellbore diagram of propose  Completions: Attach wellbore diagram of propose  Completion	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attest, including estimated date of starting any red completion or recompletion.  The property of the property
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear.	Completion CASING TEST AND CEI  Completion CASING TEST AND CEI  OTHER Squeeze per  Completions: Attach wellbore diagram of propose  Completion Castriper diagram diagram of propose  Completion Castriper diagram diagram diagram d	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attest, including estimated date of starting any red completion or recompletion.  The property of the property
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear. 7. RU wireline & perforate hole @4206-08', 421	Completion CASING TEST AND CEI  Completion CASING TEST AND CEI  OTHER Squeeze per  Completion Squeeze per  Completion Attach wellbore diagram of propose  Completions: Attach wellbore diagram of propose  Completion Squeeze per  Completion Garage and Squeeze per  Completion Garage an	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attes, including estimated date of starting any red completion or recompletion.  The property of the property o
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeeze 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. For Circulate clean RD power swivel & stripper head 7. RU wireline & perforate hole @4206-08', 421 8. RIH w/RTTS treating packer set @4150' RU	Completion CASING TEST AND CEI  Completion CASING TEST AND CEI  OTHER Squeeze per  Completion Squeeze per  Completion Attach wellbore diagram of propose  Completions: Attach wellbore diagram of propose  Completion Squeeze per  Completion Garage and Squeeze per  Completion Garage an	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Ates, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At 194'.  HES.  ICR @3988'. Drill to 3991'. Cement in returns.  ICR @3988'. Drill new formation to new TD @4275'.  @2 JSPF. RD wireline.  Pump 35 bbls of gel brine & 25 bbl of fresh water.
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear. 7. RU wireline & perforate hole @4206-08', 421	Completion CASING TEST AND CEI  Completion CASING TEST AND CEI  OTHER Squeeze per  Completion Squeeze per  Completion Attach wellbore diagram of propose  Completions: Attach wellbore diagram of propose  Completion Squeeze per  Completion Garage and Squeeze per  Completion Garage an	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attes, including estimated date of starting any red completion or recompletion.  The property of the property o
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COMPONDE PROPERTY OF THE PULL OF TH	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details. Attach wellbore diagram of propose le. Pump 10 bbl 10# brine. RIH & tag gravel @ te perfs 4165-84' w/24 bbl (94 sxs) cement. RD te stripper head. Tag cement @3986'. Drill on Cell out of cement. Drill on pea gravel from 4205 dd. 13-15', 4220-29', 4170-82', 4187-91', 4196-99' HES & acid treat well w/4000 gal of 15% acid.	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Ates, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion or recompletion.  Infs/re-perf/AT  At a tes, including estimated date of starting any sed completion.  Infs/re-perf/AT  Infs/re
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COMPONDE PROPOSED RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear. 7. RU wireline & perforate hole @4206-08', 421 8. RIH w/RTTS treating packer set @4150' RU RD HES. POOH w/RTTS packer	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details and give pertinent details are perfectly state all pertinent details. The completions: Attach wellbore diagram of propositions. Attach wellbore diagram of propositions are perfectly stated and propositions. Attach wellbore diagram of propositions. Attach wellbore dia	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Attes, including estimated date of starting any sed completion or recompletion.  Attention of the properties
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COMPONDE PROPOSED RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear. 7. RU wireline & perforate hole @4206-08', 421 8. RIH w/RTTS treating packer set @4150' RU RD HES. POOH w/RTTS packer	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details. Attach wellbore diagram of propose le. Pump 10 bbl 10# brine. RIH & tag gravel @ te perfs 4165-84' w/24 bbl (94 sxs) cement. RD te stripper head. Tag cement @3986'. Drill on Cell out of cement. Drill on pea gravel from 4205 dd. 13-15', 4220-29', 4170-82', 4187-91', 4196-99' HES & acid treat well w/4000 gal of 15% acid.	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Attes, including estimated date of starting any sed completion or recompletion.  Attention of the properties
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COMPONDE PROPOSED RULE 1103. For Multiple 1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear. 7. RU wireline & perforate hole @4206-08', 421 8. RIH w/RTTS treating packer set @4150' RU RD HES. POOH w/RTTS packer	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details. Attach wellbore diagram of propose le Pump 10 bbl 10# brine. RIH & tag gravel @ te perfs 4165-84' w/24 bbl (94 sxs) cement. RD te stripper head. Tag cement @3986'. Drill on Cell out of cement. Drill on pea gravel from 4205 dd. 13-15', 4220-29', 4170-82', 4187-91', 4196-99' HES & acid treat well w/4000 gal of 15% acid.  Plete to the best of my knowledge and belief. I further cer a general permit or an (attached) alternation plan	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Attest, including estimated date of starting any sed completion or recompletion.  Attest Attest Attention and
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COMPONDE PROPOSED PROPOS	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details and give pertinent details. The Completions: Attach wellbore diagram of propose the Pump 10 bbl 10# brine. RIH & tag gravel are perfs 4165-84' w/24 bbl (94 sxs) cement. RD at stripper head. Tag cement @3986'. Drill on Castripper head. Tag cement @3986'. Drill on Castripper head. Drill on pea gravel from 4205 dd.  13-15', 4220-29', 4170-82', 4187-91', 4196-99' HES & acid treat well w/4000 gal of 15% acid.  Plete to the best of my knowledge and belief. I further certain a general permit or an (attached) alternation or an (attached) alternation of the complete to the best of my knowledge and belief.	PLUG & ABANDONMENT  MENT JOB  Tris/re-perf/AT  Attes, including estimated date of starting any sed completion or recompletion.  The property of the property o
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COTHER:  1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper head. 7. RU wireline & perforate hole @4206-08', 421 8. RIH w/RTTS treating packer set @4150' RU RD HES. POOH w/RTTS packer  I hereby certify that the information above is true and componstructed or closed according to NMOCD guidelines ,	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details. Attach wellbore diagram of propose le Completions: Attach wellbore diagram of propose le Pump 10 bbl 10# brine. RIH & tag gravel @ te perfs 4165-84' w/24 bbl (94 sxs) cement. RD te stripper head. Tag cement @3986'. Drill on Cell out of cement. Drill on pea gravel from 4205 dd. l3-15', 4220-29', 4170-82', 4187-91', 4196-99' HES & acid treat well w/4000 gal of 15% acid.  plete to the best of my knowledge and belief. I further cer a general permit or an (attached) alternation plan  TITLE Administrat  mendy johnson@oxy	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Attest, including estimated date of starting any sed completion or recompletion.  Attest at the completion of the completion of the completion of the completion of the completion.  Attest at the completion of the comp
TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER:  13. Describe Proposed or Completed Operations (CI proposed work) SEE RULE 1103. For Multiple COTHER:  1. RUPU & RU. ND wellhead/NU BOP. 2. POOH w/injection equipment & packer. 3. RIH w/bit. Tag fill @4252'. POOH w/bit. 4. Dump 10 5 gal buckets of pea gravel down ho 5. RIH w/CICR set @3987'. RU HES & squeez. 6. RIH w/bit & drill collars. RU power swivel & Continue drilling cement from 3991 to 4205''. F. Circulate clean RD power swivel & stripper hear. 7. RU wireline & perforate hole @4206-08', 421 8. RIH w/RTTS treating packer set @4150' RU RD HES. POOH w/RTTS packer  I hereby certify that the information above is true and component constructed or closed according to NMOCD guidelines  TYPE OR PRINT NAME Mendy A. Johnson	Completion CASING TEST AND CEI OTHER Squeeze per learly state all pertinent details, and give pertinent details and give pertinent details, and give pertine	PLUG & ABANDONMENT  MENT JOB  Infs/re-perf/AT  Attest, including estimated date of starting any sed completion or recompletion.  Attest at the completion of the completion of the completion of the completion of the completion.  Attest at the completion of the comp

## NHU 30-111

- 9. RIH w/4-1/2" G-6 packer set on 122 jts of 2-7/8" Duoline 20 tubing. Packer set @4006'.
- 10. ND BOP/NU wellhead.
- 11. Test casing to 370# for 30 minutes and chart for the NMOCD. Mark Whitaker w/NMOCD was on location for test.
- 12. RDPU & RU. Clean location.

RUPU 01/15/2008 RDPU 01/30/2008

