FILE IN TRIPLICATE

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004


OIL CONSERVATION DIVISION

DISTRICT I 1625 N. French DMARbbs, 702 8240	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO 30-025-28942
	Santa 16, 14141 67505	5 Indicate Type of Lease
DISTRICT OF STAMPS TO CO		STATE FEE
DISTRICT III 1000 R ₁₀ Brazos Rd, Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		Section 30
1. Type of Well: Oil Well Gas We	Other Injector	8. Well No. 233
2 Name of Operator	I I I I I I I I I I I I I I I I I I I	9. OGRID No 157984
Occidental Permian Ltd. 3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		110000 (0/0.1)
4 Well Location		
Unit Letter K : 2455 Feet From The South 1480 Feet From The West Line		
		-E NMPM Lea County
11. Elevat 3666' KI	ion (Show whether DF, RKB, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
		
PERFORM REMEDIAL WORK PLUG AND	ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F		
	PLANS COMMENCE DRILLING O	PNS PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE F	PLANS COMMENCE DRILLING O CASING TEST AND CEME	PNS PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co	COMMENCE DRILLING O CASING TEST AND CEME OTHER: Squee:	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT X
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER 13. Describe Proposed or Completed Operations (Clear proposed work) SEE RULE 1103. For Multiple	COMMENCE DRILLING O CASING TEST AND CEME OTHER: Squeez arrly state all pertinent details, and give pertinent dat Completions: Attach wellbore diagram of proposed	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any discompletion or recompletion.
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clear proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI	COMMENCE DRILLING O CASING TEST AND CEME OTHER: Squeez arrly state all pertinent details, and give pertinent dat Completions: Attach wellbore diagram of proposed	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT x es, including estimated date of starting any discompletion or recompletion.
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH w	COMMENCE DRILLING OF CASING TEST AND CEMENT OTHER: Squeeze Carly state all pertinent details, and give pertinent data. Completions: Attach wellbore diagram of proposed P.	PNS PLUG & ABANDONMENT ENT JOB Ze/Run partial liner/perf/AT Es, including estimated date of starting any discompletion or recompletion. PMX 2D2
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pum	COMMENCE DRILLING O CASING TEST AND CEME OTHER: Squeez arly state all pertinent details, and give pertinent dat Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retained	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any d completion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES.
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH w	COMMENCE DRILLING O CASING TEST AND CEME OTHER: Squeez arly state all pertinent details, and give pertinent dat Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retained wer swivel & stripper head. Drill up CICR. Dril	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any d completion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pump 5. RIH w/bit & drill collars. Tag @4062'. RU pos stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow	COMMENCE DRILLING OF CASING TEST AND CEMENT	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any decompletion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars.
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pump 5. RIH w/bit & drill collars. Tag @4062'. RU pos stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & strip	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Squeeze parly state all pertinent details, and give pertinent data. Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retained wer swivel & stripper head. Drill up CICR. Driedlate clean. RD power swivel & stripper head. Wer swivel & stripper head. Mill thru tight spots in per head. POOH w/bit & string mill.	PNS PLUG & ABANDONMENT ENT JOB Ze/Run partial liner/perf/AT Es, including estimated date of starting any discompletion or recompletion. PMX - 2D2 Tr @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. In casing @4225' & 4235'. Clean out to PBTD
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pump 5. RIH w/bit & drill collars. Tag @4062'. RU pos stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & strip	COMMENCE DRILLING OF CASING TEST AND CEMENT	PNS PLUG & ABANDONMENT Ze/Run partial liner/perf/AT Es, including estimated date of starting any discompletion or recompletion. PMX - 2D2 Tr @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. In casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pump 5. RIH w/bit & drill collars. Tag @4062'. RU por stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & string 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line	COMMENCE DRILLING OF CASING TEST AND CEMENT	PNS PLUG & ABANDONMENT ENT JOB Ze/Run partial liner/perf/AT Es, including estimated date of starting any discompletion or recompletion. PMX - 2D2 Tr @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. In casing @4225' & 4235'. Clean out to PBTD
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pum 5. RIH w/bit & drill collars. Tag @4062'. RU por stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & string 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803'	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Squee: arrly state all pertinent details, and give pertinent date. Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retained wer swivel & stripper head. Drill up CICR. Dries and the clean. RD power swivel & stripper head. Wer swivel & stripper head. Mill thru tight spots apper head. POOH w/bit & string mill. on bottom @4342'. RU HES & cement liner in ***see additional date.	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any dicompletion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. in casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD a on attached sheet***
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH w 4. RU HES & run 5-1/2" CICR set @4062'. Pum 5. RIH w/bit & drill collars. Tag @4062'. RU por stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & string 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803'	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Squee: arrly state all pertinent details, and give pertinent dat Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retainer wer swivel & stripper head. Drill up CICR. Dri culate clean. RD power swivel & stripper head. wer swivel & stripper head. Mill thru tight spots in ver swivel & stripper head. Mill thru tight spots in pper head. POOH w/bit & string mill. on bottom @4342'. RU HES & cement liner in ***see additional date ete to the best of my knowledge and belief. I further certification.	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any discompletion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. in casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD a on attached sheet***
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH w 4. RU HES & run 5-1/2" CICR set @4062'. Pum 5. RIH w/bit & drill collars. Tag @4062'. RU por stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & string 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803'	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Squee: arrly state all pertinent details, and give pertinent date. Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retained wer swivel & stripper head. Drill up CICR. Dries and the clean. RD power swivel & stripper head. Wer swivel & stripper head. Mill thru tight spots apper head. POOH w/bit & string mill. on bottom @4342'. RU HES & cement liner in ***see additional date.	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any discompletion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. in casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD a on attached sheet***
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clea proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH w 4. RU HES & run 5-1/2" CICR set @4062'. Pum 5. RIH w/bit & drill collars. Tag @4062'. RU por stringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & string 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803'	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Squee: arrly state all pertinent details, and give pertinent dat Completions: Attach wellbore diagram of proposed P. w/bit & string mill. p 53 bbl of cement. Squeeze perfs below retainer wer swivel & stripper head. Drill up CICR. Dri culate clean. RD power swivel & stripper head. wer swivel & stripper head. Mill thru tight spots in pper head. POOH w/bit & string mill. on bottom @4342'. RU HES & cement liner in ***see additional date ete to the best of my knowledge and belief. I further certification or an (attached) alternation.	PNS PLUG & ABANDONMENT ENT JOB Ze/Run partial liner/perf/AT Es, including estimated date of starting any discompletion or recompletion. PMX - 2D2 Tr @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. In casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD as on attached sheet*** Ty that any pit or below-grade tank has been/will be live OCD-approved
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clear proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pump 5. RIH w/bit & drill collars. Tag @4062'. RU postringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & strip 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803' Thereby certify that the information above is true and complete constructed or closed according to NMOCD guidelines , a	COMMENCE DRILLING OF CASING TEST AND CEMBER OTHER: Squeeze arrly state all pertinent details, and give pertinent data Completions: Attach wellbore diagram of proposed P. Whit & string mill. p 53 bbl of cement. Squeeze perfs below retained wer swivel & stripper head. Drill up CICR. Driedlate clean. RD power swivel & stripper head. Wer swivel & stripper head. Mill thru tight spots and per head. POOH whit & string mill. The on bottom @4342'. RU HES & cement liner in the set of my knowledge and belief. I further certification of an (attached) alternation plan.	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any decompletion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. in casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD a on attached sheet*** fy that any pit or below-grade tank has been/will be live OCD-approved DATE 02/28/2008
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clear proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH w/or and the string mill. Tag @4062'. Rumpostringers & fill from 4298' to PBTD @4342'. Circ for RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & string r. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803' Thereby certify that the information above is true and complete constructed or closed according to NMOCD guidelines , a	COMMENCE DRILLING OF CASING TEST AND CEMBER	PNS PLUG & ABANDONMENT ENT JOB Dee/Run partial liner/perf/AT Es, including estimated date of starting any decompletion or recompletion. PMX - 2D2 The equation of the entire of the
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING Multiple Co OTHER: 13. Describe Proposed or Completed Operations (Clear proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. Kill well. ND wellhead/NU BOI 2. POOH w/injection equipment and packer. 3. RIH w/bit & string mill. Tag @4335'. POOH v 4. RU HES & run 5-1/2" CICR set @4062'. Pump 5. RIH w/bit & drill collars. Tag @4062'. RU postringers & fill from 4298' to PBTD @4342'. Circ 6. RIH w/bit & string mill. Tag @4182'. RU pow @4342'. Circ hole clean. RD power swivel & strip 7. RU Bull Rodger & run 4-1/2" FJ liner. Set line HES. Top of liner @3803' I hereby certify that the information above is true and complete constructed or closed according to NMOCD guidelines , a SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson	COMMENCE DRILLING OF CASING TEST AND CEMBER	PNS PLUG & ABANDONMENT ENT JOB ze/Run partial liner/perf/AT es, including estimated date of starting any decompletion or recompletion. PMX - 2D2 r @4062'. Reverse out 22 bbl of cement. RD HES. Il cement from 4063-4298'. Clean out cement POOH w/bit & drill collars. in casing @4225' & 4235'. Clean out to PBTD place w/13 bbl of cement. Reverse out 11 bbl. RD a on attached sheet*** fy that any pit or below-grade tank has been/will be live OCD-approved DATE 02/28/2008

NHU 30-233

- 8. RIH w/bit. Tag @4338'. POOH w/bit.
- 9. RU wireline & perforate hole @4196-99', 4226-34', 4238-42', 4248-56', 4260-64', 4272-74', 4278-90' @2 JSPF. RD wireline.
- 10. RIH w/PPI packer set @3850'. RU HES & pickle tubing. Acid treat new perfs w/1260 gals of 15% acid. RD HES. POOH w/PPI tools.
- 11. RIH w/4-1/2" Arrowset 1-X packer on 129 jts of 2-7/8" tubing. Packer set @4099'
- 12. Test casing to 620# & chart for the NMOCD.
- 13. RDPU & RU. Clean location.

RUPU 12/14/2007 RDPU 01/10/2008



Test smith services dest por a sol ship and por and por and por and por and por and the services and por a sol ship and por a s